 <p>Not Actual Photo YIC International Co., Limited.</p>	<h2 style="color: red;">B72520T350K62V50</h2>
	<p>Manufacturer Part Number: B72520T350K62V50</p> <p>Manufacturer/Brand: EOCOS</p> <p>Part of Description: EOCOS 1206SMD</p> <p>RoHs Status:</p> <p>Stock Condition: New original, 2500 pcs Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	









Specifications

Part Number	B72520T350K62V50
Manufacturer	EOCOS
Description	EOCOS 1206SMD
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	2500 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

B72520T350K62V50 is New Original in Stock, Search B72520T350K62V50 Datasheets, PDF, Inventory at Y-IC.com Online, Order B72520T350K62V50 with warrantied and confidence. RFQ B72520T350K62V50 : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>B72520T250K84 EPCOS VARISTOR 39V 200A 1206</p>	 <p>B72520T500K62 EPCOS VARISTOR 82V 100A 1206</p>	 <p>B72520T300K62 EPCOS B72520T300K62 EPCOS</p>	 <p>B72520T40M62 EPCOS VARISTOR 8V 150A 1206</p>
 <p>B72520T350K62 EPCOS B72520T350K62 EPCOS (TDK)</p>	 <p>B72520T500K62 V7 EPCOS EPCOS 1206</p>	 <p>B72520T400K62V9 EPCOS B72520T400K62V9 EPCOS</p>	 <p>B72520T500K72 EPCOS VARISTOR 82V 100A 1206</p>

Hot Parts More

- | | | | | |
|-----------------------|-------------------|----------------------|----------------------|----------------------|
| ⚙️ 08051C562J4T2A | ➡️ 1041300520 | ➡️ 1206SFS450F/32-2 | D 1210YC334KAT4A | ➡️ ADC1061CIWM |
| ⚡ ADSP-2186LKST-115 | ⚙️ ALPU-05-2052 | D AT24C02N-SU1.8 | ➡️ AZ574Z-E1 | ➡️ B39941-B7710-C610 |
| ⚙️ BA6790FP-TI | ⚡ BYV38-TAP | ⚙️ BZX84C20LT1G | ➡️ CC0603KRX7R6BB225 | ➡️ COP8CCE9IMT7 |
| D CSTCW24M0X51-R0 | ⚙️ DDTC144EE-7-F | ⚡ DEA212450BT-7031A1 | ⚙️ DHR400C5 | ➡️ EFCH1960TDB1 |
| ➡️ ERB1885C2E3R3BDX1D | ➡️ EUM6883MIR1 | ⚙️ FDB045AN08A0 | ⚡ IDT49FCT3805APYG8 | ➡️ IDT5V49EE902NLGI |
| ➡️ LM2594MX-3.3 | ➡️ LM26LVCSID-130 | D LM4040DIM3X-10.0 | ⚙️ LTC1729CMS8-8.2 | ⚡ LTC6803HG-2#PBF |
| ⚙️ M95640-VMN6T | D MMBT9013HLT1 | ➡️ P6KE91CA-E3/73 | ➡️ PM20CEE060-9 | ➡️ R9G02212XX |
| ⚡ RFP12N20 | ⚙️ RT9824GJ8 | ➡️ SCH150GB120DN2 | ➡️ SKNH92/16E | ➡️ SN74ALS86N |
| ⚙️ STD6N10T4 | ⚡ STI5518BVC | ⚙️ STM32F411RET6 | D T92S7D12-24 | ➡️ TCM810MENM713 |
| ➡️ TEN5-1210 | ⚙️ UGF1008GA | ⚡ UMK105CG271JVHF | ⚙️ UMK105CK1R5CW-F | ➡️ VI-JNB-EX |