

	<h2 style="color: #e67e22;">MAX16021LTEZ+</h2>	
	Manufacturer Part Number:	MAX16021LTEZ+
	Manufacturer/Brand:	Maxim Integrated
	Part of Description:	IC SUPERVISOR PP 2.323V 16TQFN
	Datasheets:	1.MAX16021LTEZ+.pdf 2.MAX16021LTEZ+.pdf
	RoHs Status:	 Lead free / RoHS
	Stock Condition:	Compliant New original, Stock Available.
	Ship From:	Hong Kong
	Shipment Way:	DHL/Fedex/TNT/UPS/EMS
<p>Image may be representation. See specs for product details.</p>		

Specifications

Part Number	MAX16021LTEZ+
Manufacturer	Maxim Integrated
Description	IC SUPERVISOR PP 2.323V 16TQFN
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Simple Reset/Power-On Reset
Package / Case	16-WQFN Exposed Pad
Supplier Device Package	16-TQFN (4x4)
Output	Push-Pull, Totem Pole
Reset	Active High/Active Low
Number of Voltages Monitored	1
Reset Timeout	145 ms Minimum
Voltage - Threshold	2.323V
Packaging	Tube

MAX16021LTEZ+ is New Original in Stock, Search MAX16021LTEZ+ Datasheets, PDF, Inventory at Y-IC.com Online, Order MAX16021LTEZ+ Maxim Integrated with warrantied and confidence. RFQ MAX16021LTEZ+ : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>MAX16021LTEW+ Maxim Integrated IC SUPERVISOR PP 1.661V 16TQFN</p>	 <p>MAX16021LTET+T Maxim Integrated IC SUPERVISOR PP 3.100V 16TQFN</p>	 <p>MAX16021PTEM+ Maxim Integrated IC SUPERVISOR PP 4.428V 16TQFN</p>	 <p>MAX16021PTES+ Maxim Integrated IC SUPERVISOR OD 2.946V 16TQFN</p>
 <p>MAX16021PTER+ Maxim Integrated IC SUPERVISOR OD 2.640V 16TQFN</p>	 <p>MAX16021PTES+T Maxim Integrated IC SUPERVISOR OD 2.946V 16TQFN</p>	 <p>MAX16021LTEV+ Maxim Integrated IC SUPERVISOR PP 1.571V 16TQFN</p>	 <p>MAX16021PTEL+ Maxim Integrated IC SUPERVISOR OD 4.6894V 16TQFN</p>

Hot Parts

[More](#)

- | | | | | |
|------------------------------------|---------------------------------|------------------------------------|------------------------------------|------------------------------------|
| 12061C104KAT4A | 1808CC102MAT3A | 1D500A030 | 7MBP150RUC060-02 | A4946GLPTR-T |
| AD5628BCPZ-2-RL7 | AD8072ARM-REEL7 | ADM1181AARW | APT8056BVFR | ATA5830N-PNQW1-19 |
| ATMEGA88-20MU | BD63000MUV-GE2 | CAT5114YI | CS0603-68NJ-S | EDJ2104BFBG-GN-F |
| FAN5330SX | FAN9612MX | GRM1556R1H3R2CZ01D | HCPL-7840 | ISL9003AIEMZ-T |
| LC4128ZC-42MNZ-75I | LM809M3X-4.38 | LT1308CS8 | LT1620IS8#TRPBF | MAX6033AAUT30#TG16 |
| ME6206A21PG | MM912H634CV1AE | PBL40171/1GML | PC81004C | PESD5V0S1UL |
| PZTA14E-6327 | QCA75A60 | RT9166-33GX | S-80831ANNP-EDV-T2 | S3CA460S01-YX80 |
| SAFSD942MCL0F04R13 | SC4538ULTRT | SD803C12S15C | SI32171-FM1 | SI3442BDV |
| SPC5604PF1VLL6 | SSD40P04-20D | STPR2420CT | STPS61150CW | SW14DXC27C |
| THS9000DRWR | TISP61089LDR-S | TT142NKO | TT25N06KOF | ZM4751A-7 |