

	<p><b>UJA1018TK,118</b></p>
	<p><b>Manufacturer Part Number:</b> UJA1018TK,118</p>
 <p>Not Actual Photo YIC International Co., Limited.</p>	<p><b>Manufacturer/Brand:</b> NXP Semiconductors / Freescale</p>
	<p><b>Part of Description:</b> IC TRANSCEIVER LIN 16HVSON</p>
<p>Image may be representation. See specs for product details.</p>	<p><b>RoHs Status:</b>  Lead free / RoHS</p>
	<p><b>Stock Condition:</b> Compliant New original, Stock Available.</p>
	<p><b>Ship From:</b> Hong Kong</p>
	<p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p>









### Specifications

Part Number	UJA1018TK,118
Manufacturer	NXP Semiconductors / Freescale
Description	IC TRANSCEIVER LIN 16HVSON
Category	Integrated Circuits (ICs) > Interface - Drivers, Receivers,
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 150°C
Mounting Type	Surface Mount
Type	Transceiver
Package / Case	16-VDFN Exposed Pad
Supplier Device Package	16-HVSON (3.5x5.5)
Voltage - Supply	4.9 V ~ 5.1 V
Protocol	LIN
Number of Drivers/Receivers	1/1
Duplex	-
Receiver Hysteresis	175mV
Data Rate	-
Packaging	Tape & Reel (TR)

UJA1018TK,118 is New Original in Stock, Search UJA1018TK,118 Datasheets, PDF, Inventory at Y-IC.com Online, Order UJA1018TK,118 NXP Semiconductors / Freescale with warrantied and confidence. RFQ UJA1018TK,118 : Info@Y-IC.com

### You May Be Also Be interested

In:

 <p><b>UJA1023T/2R04/C;51</b> NXP Semiconductors / Freescale IC CAN/LIN I/O SLAVE 16-SOIC</p>	 <p><b>UJA1061TW/3V3/C/T,</b> NXP Semiconductors / Freescale IC CAN/LIN FAIL-SAFE HS 32HTSSOP</p>	 <p><b>UJA1061TW/5V0</b> NXP NXP TSSOP</p>	 <p><b>UJA1023T/2R04,518</b> NXP Semiconductors / Freescale IC CAN/LIN I/O SLAVE 16SOIC</p>
 <p><b>UJA1023T/2R04,512</b> NXP Semiconductors / Freescale IC CAN/LIN I/O SLAVE 16SOIC</p>	 <p><b>UJA1023T/2R04/C,51</b> NXP Semiconductors / Freescale IC CAN/LIN I/O SLAVE 16-SOIC</p>	 <p><b>UJA1023T/2R04/C</b> NXP NXP SOP16</p>	 <p><b>UJA1061TW/3V3/C/T/</b> NXP Semiconductors / Freescale IC CAN/LIN FAIL-SAFE HS 32HTSSOP</p>

### Hot Parts

More

- |                        |                      |                   |                      |                       |
|------------------------|----------------------|-------------------|----------------------|-----------------------|
| ⚙️ 12103U470JAT2A      | 🔌 1808GC102JAT1A     | ➡️ 2RI100E-080X3  | D AE58256AJ-12       | ➡️ AT17LV002-10CU     |
| ⚡ AT25DF041A-SSH       | ⚙️ CC0603JRX7R7BB104 | D CL21A225KPCLNNC | ➡️ CY8C24794-24LTXI  | ➡️ DF353-800-30       |
| ⚙️ DMC9640N0R          | ⚡ DMP3130L-7         | ⚙️ ESDA6V1P6      | 🔌 FP15R12W1T4-B11    | ➡️ GRM1555C1H6R3WZ01D |
| D HIP1020CKZ-T         | ⚙️ IPS6041SPBF       | ⚡ IRU3037CSTRPBF  | ⚙️ LC33864M-80       | ➡️ LT1006S8           |
| ➡️ LT1963ES8-1.8#TRPBF | 🔌 LT6000IDCB#TRPBF   | ⚙️ LTC3406-ADJ    | ⚡ LTC3850IGN-2#PBF   | ➡️ MBRD1035CTLT4G     |
| 🔌 MCP1702-5002E/TO     | ➡️ MIG150Q6C3AOZ     | D MT2068F-02      | ⚙️ N40-5835P-16-00   | ⚡ NCP584LSN18T1G      |
| ⚙️ NCT6779D-R          | D NTD4302T4          | ➡️ OPA3682E/2K5   | 🔌 P4SMA400A          | ➡️ PGA205BU/1K        |
| ⚡ PIC10F204T-I/OT      | ⚙️ SI3241-GQ         | 🔌 SI6973DQ-T1-GE3 | ➡️ SI9183DT-33-T1-E3 | ➡️ SPX431AS-L/TR      |
| ⚙️ SW12CXC935          | ⚡ TAJA475K010RNJ     | ⚙️ TM30TPM-M      | D TPSB227M002R0150   | ➡️ UNR52AMG0LSO       |
| 🔌 UPC2791TB-E3         | ⚙️ V24A3V3M264BL     | ⚡ V8PA15HM3       | ⚙️ VD241212H-2W      | ➡️ VI-B10-IU          |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited