










| | |
|---|--|
|  | <p>FL1100-1Q0</p> <p>Manufacturer Part Number: FL1100-1Q0</p> <p>Manufacturer/Brand: FRESCO</p> <p>Part of Description: FRESCO 116DRQFN</p> <p>RoHs Status:</p> <p>Stock Condition: New original, 5600 pcs Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p> |
| | <p>Image may be representation. See specs for product details.</p> |

| Specifications | |
|----------------|---|
| Part Number | FL1100-1Q0 |
| Manufacturer | FRESCO |
| Description | FRESCO 116DRQFN |
| Category | Integrated Circuits (ICs) > Specialized Hot ICs |
| Part Status | 5600 pcs Stock |
| Series | - |
| RoHs Status | Lead free / RoHS Compliant |
| Condition | New Original Stock |
| Warranty | 100% Perfect Functions |
| Lead Time | 2-3days after payment. |
| Payment | PayPal / Telegraphic Transfer / Western Union |
| Shipping by | DHL / Fedex / UPS |
| Port | HongKong |
| RFQ Email | Info@Y-IC.com |

FL1100-1Q0 is New Original in Stock, Search FL1100-1Q0 Datasheets, PDF, Inventory at Y-IC.com Online, Order FL1100-1Q0 with warrantied and confidence. RFQ FL1100-1Q0 : Info@Y-IC.com

You May Be Also Be interested

In:

| | | | |
|---|--|---|--|
|  <p>FL11K10 Bussmann (Eaton) FUSE LK CPS K 010A NRB 23"</p> |  <p>FL1066 Pulse Electronics Corporation IC CHIP</p> |  <p>FL11K100 Bussmann (Eaton) FUSE LK CPS K 100A NRB 23"</p> |  <p>FL10801 Melexis FILE LOADER FOR MLX10801</p> |
|  <p>FL1100-1Q0-EX FRESCO FRESCO QFN</p> |  <p>FL1095S VALOR VALOR SOP14</p> |  <p>FL1100-1G0-SX FRESCO FRESCO BGA</p> |  <p>FL10KM-12A Ren Ren TO-220F</p> |

Hot Parts More

- | | | | | |
|--------------------|---------------------|----------------------|-----------------------|-------------------------|
| ⚙️ 04025A150GAT2A | ➡️ 06036D225KAT2A | ➡️ 1210AC222KAT1A | D AM29DL323DT-90WDI | ➡️ AM79C32AJC/J |
| ⊖ BA3574BFSBFS | ⚙️ BR24G256FJ-3GTE2 | D BZX585-C4V3 | ➡️ C0603CH1E040C030BA | ➡️ C1608C0G2E471J080AA |
| ⚙️ CL10CR47BB8NNNC | ⊖ CM600HA-24E | ⚙️ CS5525ASZ | ➡️ CSD18533KCS | ➡️ DFLT10A-7-F |
| D EGM100D12SV1 | ⚙️ FDMS3606S | ⊖ GRM152C80G104ME19D | ⚙️ HA3-2525-5 | ➡️ K5W4G2GACM-BP50000 |
| ➡️ LM2931CS | ➡️ LP3965ET-ADJ | ⚙️ LT1181ACSW#TRPBF | ⊖ LT1507CS8 | ➡️ LTC6420CUDC-20#PBF |
| ➡️ MBM100NS12AW | ➡️ MJ100BX120 | D ML101J21-47 | ⚙️ MPC184VMB | ⊖ MPXH6115A6U |
| ⚙️ OPA2131UJ/2K5 | D PM50CTL060-3 | ➡️ RCLAMP0544T.TCT | ➡️ RN1112FT | ➡️ SAF-XC164CS-16F40FBB |
| ⊖ SFH628-4 | ⚙️ SI3457BDV-T1-GE3 | ➡️ SI4174DY-T1-GE3 | ➡️ SKN650F16 | ➡️ SKYFR-000972 |
| ⚙️ SM40XC394 | ⊖ SMCJ78CA | ⚙️ SML4728A-E3/61 | D SN75C1168PWR | ➡️ SUB65P06-20-E3 |
| ➡️ TC514260BZLL-70 | ⚙️ TMK063CG010CPGF | ⊖ TS2019LF | ⚙️ TT7169R25CL | ➡️ VI-J51-CY/F2 |