

	<p>S-80846KNY-B-G</p>
	<p>Manufacturer Part Number: S-80846KNY-B-G</p>
	<p>Manufacturer/Brand: SII Semiconductor Corporation</p>
	<p>Part of Description: IC VOLT DETECTOR 4.6V TO-92</p>
	<p>Datasheets:  S-80846KNY-B-G.pdf</p>
	<p>RoHS Status:  Lead free / RoHS</p>
	<p>Stock Condition: Compliant New original, Stock Available.</p>
	<p>Ship From: Hong Kong</p>
<p>Image may be representation. See specs for product details.</p>	<p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>

Specifications

Part Number	S-80846KNY-B-G
Manufacturer	SII Semiconductor Corporation
Description	IC VOLT DETECTOR 4.6V TO-92
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	S-808xxC
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Through Hole
Type	Voltage Detector
Package / Case	TO-226-3, TO-92-3 (TO-226AA)
Supplier Device Package	TO-92-3
Output	Open Drain or Open Collector
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	-
Voltage - Threshold	4.6V
Packaging	Bulk

S-80846KNY-B-G is New Original in Stock, Search S-80846KNY-B-G Datasheets, PDF, Inventory at Y-IC.com Online, Order S-80846KNY-B-G SII Semiconductor Corporation with warrantied and confidence. RFQ S-80846KNY-B-G : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>S-80847ALUP-EEB-T2 SEIKO SEIKO SOT89</p>	 <p>S-80847CLMC-B68T2G SII Semiconductor Corporation IC VOLT DETECTOR 4.7V SOT23-5</p>	 <p>S-80846CNY-Z2-U SII Semiconductor Corporation IC VOLT DETECTOR 4.6V TO-92</p>	 <p>S-80846KNUA-D2CT2U SII Semiconductor Corporation IC VOLT DETECTOR 4.6V SOT89-3</p>
 <p>S-80846KNUA SEIKO SEIKO SOT-89</p>	 <p>S-80846KNUA-D2C-T2 SEIKO SEIKO SOT89</p>	 <p>S-80847ANNP-EJBT2G SEIKO S-80847ANNP-EJBT2G SEIKO</p>	 <p>S-80846KNUA-D2CT2G SII Semiconductor Corporation IC VOLT DETECTOR 4.6V SOT89-3</p>

Hot Parts

More

- | | | | | |
|---------------------|--------------------|---------------------|------------------|------------------|
| 06031C241JAT2A | 06033A100DAT2A | A3977SEDTR-T | D AD7147AACBZ-RL | AOB11S65 |
| AS200-313 | BA08CC0WFP-E2 | D BAS140WE6327 | BC847B-S4032R | BNX005-01 |
| BT152-600R | BYM11-400-E3/76 | BZT52C11 | DTA114EKAFRAT46 | E30NK90Z |
| ED411216 | F1842CCD600 | FNA40860B2 | FRD512S1 | GBLCSC03C-LF-T74 |
| G CJ31BR72E683KXJ1L | GJM0335C1E9R3DB01J | IES020ZG | IMP809LEUR/T | IRF1503STRLPBF |
| JA80486GXS F33 | K6X4008C1F-UF55 | LM2578AM | MAX7454UUP+T | MIC59300-1.2WU |
| MMPQ3725 | MT41J128M8JP-107:G | MT48LC4M32B2P-7IT:G | N490CH22GOO | NM27C64Q-200 |
| PSMN057-200P | RB205T-90LD | RMCF0603FT17K8 | S6D0110A31-B0CX | SI1067X-T1-GE3 |
| SKT56/02D | SMD2920P185TS | SN75155P | SQD30N05-20L | STE48NM60 |
| TLE2426CDRG4 | TLE4209G | TP2852HPHA | V24A28C400BG | VI-2TL-CU |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited