










	<h2 style="color: #E67E22;">LV5876MX-TLM-H</h2>
 Not Actual Photo YIC International Co., Limited.	<p>Manufacturer Part Number: LV5876MX-TLM-H</p> <hr/> <p>Manufacturer/Brand: AMI Semiconductor / ON Semiconductor</p> <hr/> <p>Part of Description: IC REG BUCK ADJ 2A SYNC MFP8</p> <hr/> <p>Datasheets:  LV5876MX-TLM-H.pdf</p> <hr/> <p>RoHs Status:  Lead free / RoHS</p> <hr/> <p>Stock Condition: Compliant New original, Stock Available.</p> <hr/> <p>Ship From: Hong Kong</p> <hr/> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	

Specifications

Part Number	LV5876MX-TLM-H
Manufacturer	AMI Semiconductor / ON Semiconductor
Description	IC REG BUCK ADJ 2A SYNC MFP8
Category	Integrated Circuits (ICs) > PMIC - Voltage Regulators -
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-20°C ~ 80°C (TA)
Mounting Type	Surface Mount
Voltage - Input (Max)	18V
Output Type	Adjustable
Package / Case	8-SOIC (0.173", 4.40mm Width) Exposed Pad
Supplier Device Package	8-MFP
Function	Step-Down
Current - Output	2A
Frequency - Switching	950kHz
Number of Outputs	1
Output Configuration	Positive
Topology	Buck
Voltage - Output (Min/Fixed)	0.8V
Voltage - Output (Max)	14.4V
Synchronous Rectifier	Yes
Voltage - Input (Min)	4.75V
Packaging	Tape & Reel (TR)

LV5876MX-TLM-H is New Original in Stock, Search LV5876MX-TLM-H Datasheets, PDF, Inventory at Y-IC.com Online, Order LV5876MX-TLM-H AMI Semiconductor / ON Semiconductor with warrantied and confidence. RFQ LV5876MX-TLM-H : Info@Y-IC.com

You May Be Also Be interested

 Not Actual Photo YIC International Co., Limited.	 Not Actual Photo YIC International Co., Limited.	 Not Actual Photo YIC International Co., Limited.	
<p>LV5857 SANYO LV5857 SANYO</p>	<p>LV5893M-TE-L-E SANYO SANYO SOP8</p>	<p>IV5856MXL-TLM-H SANYO SANYO SOP8</p>	<p>LV5857MX-TLM-H AMI Semiconductor / ON Semiconductor IC REG BUCK ADJ 3A SYNC MFP8</p>
 Not Actual Photo YIC International Co., Limited.	 Not Actual Photo YIC International Co., Limited.		 Not Actual Photo YIC International Co., Limited.
<p>LV5876MXL-TLM-H SANYO LV5876MXL-TLM-H SANYO</p>	<p>LV5876MXL SANYO LV5876MXL SANYO</p>	<p>LV5856MX-TLM-H AMI Semiconductor / ON Semiconductor IC REG BUCK ADJ 3A SYNC MFP8</p>	<p>LV5876MXL-TLM SANYO LV5876MXL-TLM SANYO</p>

Hot Parts

[More](#)

⊛ 08051A821KAT2A	↔ 0805YA102JAT2A	⇒ 1808AC122KATME	D AD6630ARZ	⇒ ADC12662CIV
⊣ AUJRLR2905ZTRL	⊛ BTA201-800E	D CC0805KRX7R9BB473	⇒ CL10C271JB8NNNC	⇒ CM150DY12E
⊛ DWM125X2-12U	⊣ EPM570T100C4	⊛ FB2015-10L2R5BT/LF	↔ FMS6410CS	⇒ GCM1885C1H8R2BA16D
D GSD2004WS-E3-18	⊛ HMSZ5257BT1	⊣ IRGB4061DPBF	⊛ IRKL132-18	⇒ ispGAL22LV10-4LKN
⇒ K4T1G084QF-BCF7	↔ LB11995H	⊛ LC75343M-TLM-E	⊣ LM2575SX-3.3	⇒ LMV324BG-13
↔ LPM9017B3F	⇒ LQH32MN680K23L	D M34507M2-329FP	⊛ MIC39150-2.5WU	⊣ NR3010T150M
⊛ P4SMA110A	D PCA24S08D	⇒ R5323Z029B-TR-FD	↔ RC0805JR-07100M	⇒ RKZ11B2KGP1Q
⊣ RT9607PS	⊛ SC380044VFR2	↔ SD603C18S20C	⇒ SI1024X-T1-E3	⇒ SIP12116DMP-T1-GE4
⊛ SKW30N60	⊣ SML-P12UTT86	⊛ SN74ALVCH16827DLR	D SS10P6-E3/86A	⇒ SSL3252UK/C2
↔ STD1766Y	⊛ TAS5612LADDV	⊣ TM10T38-H	⊛ V375A28C600AL001	⇒ WM8721EDS/R

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited