








	<p><b>TTC-2003</b></p>
	<p><b>Manufacturer Part Number:</b> <a href="#">TTC-2003</a></p> <p><b>Manufacturer/Brand:</b> <a href="#">Tamura</a></p> <p><b>Part of Description:</b> TRANSF ISOLATION 8UH HOME PNA</p> <p><b>RoHs Status:</b> Contains lead / RoHS non-compliant</p> <p><b>Stock Condition:</b> New original, 1000 pcs Stock Available.</p> <p><b>Ship From:</b> Hong Kong</p> <p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	

Specifications

Part Number	<a href="#">TTC-2003</a>
Manufacturer	<a href="#">Tamura</a>
Description	TRANSF ISOLATION 8UH HOME PNA
Category	<a href="#">Transformers &gt; Audio Transformers</a>
Part Status	1000 pcs Stock
Series	TTC
Operating Temperature	-
Approvals	-
Mounting Type	-
Size / Dimension	-
Height - Seated (Max)	-
Frequency Range	-
Termination Style	-
Insertion Loss	-
Return Loss	-
Voltage - Isolation	500VRMS @ 1 Minute
Turns Ratio - Primary:Secondary	1:1
Impedance - Primary (Ohms)	-
Impedance - Secondary (Ohms)	-
DC Resistance (DCR) - Primary	-
DC Resistance (DCR) - Secondary	-
Frequency Response	-
Power Level	-
Packaging	-

TTC-2003 is New Original in Stock, Search TTC-2003 Datasheets, PDF, Inventory at Y-IC.com Online, Order TTC-2003 Tamura with warrantied and confidence. RFQ TTC-2003 : [Info@Y-IC.com](mailto:Info@Y-IC.com)

You May Be Also Be interested In:

 <p><b>TTC-174</b> Tamura TRANSF TELE 600:600/600 50MADC</p>	 <p><b>TTC-170</b> Tamura TRANSF TELE COUP 600:600 0MADC</p>	 <p><b>TTC-2002</b> Tamura TRANSF ISOLATION 250UH HOME PNA</p>	 <p><b>TTC-218-2</b> Tamura MODEM TRANSFORMERS</p>
 <p><b>TTC-231</b> Tamura TRANSF TELE COUP 600:1200CT WET</p>	 <p><b>TTC-218</b> Tamura TRANSF TELE COUP 600 OHM 50MADC</p>	 <p><b>TTC-2000</b> Tamura TRANSF ISOLATION 10BASE-T PNA</p>	 <p><b>TTC-2012</b> Tamura TRANSF HOME RUN BANDPASS FILTER</p>

Hot Parts

[More](#)

- |                      |                      |                      |                      |                      |
|----------------------|----------------------|----------------------|----------------------|----------------------|
| ⊛ 04023A750FAT2A     | ↔ 04025A470JAT2A     | ⇒ 06033C153MAT4A     | D ADA4304-2ACPZ-R7   | ⇒ ADM2209EARU        |
| ⊣ ADSP-TS101SAB2-0   | ⊛ AOZ3015PI1         | D C2012CH2W821K060AA | ⇒ DD40F160           | ⇒ DW12-12S05B1       |
| ⊛ EMC5DXV5T1         | ⊣ GRJ32QR72J223KWJ1L | ⊛ GRM1555C1E6R5DZ01D | ↔ GRM32ER61E226ME15L | ⇒ ISL21070DIH306Z-TK |
| D LM317AT/NOPB       | ⊛ LMBTA14LT1G        | ⊣ LMX2541SQE3320E    | ⊛ LPC2420FBD208      | ⇒ LT1621CGN#TRPBF    |
| ⇒ LTC694CS8-3.3      | ↔ LTW-C193TS5-C      | ⊛ M95080-RMC6TG      | ⊣ MM3005ENRE         | ⇒ NDB6030PL          |
| ↔ NNCD6.8G-T1-A      | ⇒ PCMB061H-2R2MS     | D PI5C3126L          | ⊛ PS21255-AE         | ⊣ S-80129CNMC-JKO-T2 |
| ⊛ S29AL008D70BFIA23E | D SI1046X-T1-GE3     | ⇒ SKKH56/16E         | ↔ SKM600GAL126D      | ⇒ SM5003BCH-EL       |
| ⊣ SSM1001M           | ⊛ ST3222BTR          | ↔ STGW19NC60H/HD     | ⇒ STU6NF10           | ⇒ SY89218UHG         |
| ⊛ TEA5766UK1S21TM    | ⊣ TISP4290L3AJR-S    | ⊛ TTC-2002           | D TTC-6021           | ⇒ V300C3V3C75B       |
| ↔ VI-2NY-IU          | ⊛ XRP7603EDB-F       | ⊣ XRT75VL00DIV-F     | ⊛ ZXCT1009FTA        | ⇒ ZXM41N0F           |

Contact us:[Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited