









 <p>A Renesas Company</p>	<p><b>ISL31498EIBZ-T</b></p>
	<p><b>Manufacturer Part Number:</b> <a href="#">ISL31498EIBZ-T</a></p> <p><b>Manufacturer/Brand:</b> <a href="#">Intersil</a></p> <p><b>Part of Description:</b> IC TXRX RS485 FAULT PROT 8SOIC</p> <p><b>Datasheets:</b> <a href="#">ISL31498EIBZ-T.pdf</a></p> <p><b>RoHS Status:</b>  Lead free / RoHS</p> <p><b>Stock Condition:</b> Compliant New original, Stock Available.</p> <p><b>Ship From:</b> Hong Kong</p> <p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	

### Specifications

Part Number	ISL31498EIBZ-T
Manufacturer	Intersil
Description	IC TXRX RS485 FAULT PROT 8SOIC
Category	Integrated Circuits (ICs) > Interface - Drivers, Receivers,
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C
Mounting Type	Surface Mount
Type	Transceiver
Package / Case	8-SOIC (0.154", 3.90mm Width)
Supplier Device Package	8-SOIC
Voltage - Supply	4.5 V ~ 5.5 V
Protocol	RS422, RS485
Number of Drivers/Receivers	1/1
Duplex	Half
Receiver Hysteresis	25mV
Data Rate	15Mbps
Packaging	Tape & Reel (TR)

ISL31498EIBZ-T is New Original in Stock, Search ISL31498EIBZ-T Datasheets, PDF, Inventory at Y-IC.com Online, Order ISL31498EIBZ-T Intersil with warrantied and confidence. RFQ  
ISL31498EIBZ-T : [Info@Y-IC.com](mailto:Info@Y-IC.com)

### You May Be Also Be interested

<p><b>In:</b></p>  <p><b>ISL31498EIBZ-T7A</b> Intersil IC TXRX RS485 FAULT PROT 8SOIC</p>	 <p><b>ISL31498EIBZ</b> Intersil IC TXRX RS485 FAULT PROT 8SOIC</p>	 <p><b>ISL31498EIUZ-T</b> Intersil IC TXRX RS485 FAULT PROT 8MSOP</p>	 <p><b>ISL31498EIUZ-T7A</b> Intersil IC TXRX RS485 FAULT PROT 8MSOP</p>
 <p><b>ISL31496EIUZ-T7A</b> Intersil IC TXRX RS485 FAULT PROT 10MSOP</p>	 <p><b>ISL31496EIUZ</b> Intersil IC TXRX RS485 FAULT PROT 10MSOP</p>	 <p><b>ISL31496EIUZ-T</b> Intersil IC TXRX RS485 FAULT PROT 10MSOP</p>	 <p><b>ISL31498EIUZ</b> Intersil IC TXRX RS485 FAULT PROT 8MSOP</p>

### Hot Parts

[More](#)

<a href="#">24AA024HT-I/MNY</a>	<a href="#">2N6517TA</a>	<a href="#">AD8605ARTZ</a>	<a href="#">ADR510ART-REEL7</a>	<a href="#">BAV21WS_R1_00001</a>
<a href="#">C1608C0G1H2R2C</a>	<a href="#">CS0603KRX7R7BB474</a>	<a href="#">CSTCV25M4X54J-R0</a>	<a href="#">DDZ27CSF-7</a>	<a href="#">DPG30P300PJ</a>
<a href="#">DZ23C5V6-7-F</a>	<a href="#">GQM2195C2E620JB12D</a>	<a href="#">GRM0336T1E7R2DD01D</a>	<a href="#">GRM1555C1H360JZ01D</a>	<a href="#">HAT1127H-EL-E</a>
<a href="#">ICE2PCS01G</a>	<a href="#">ICS9112BM-17LF</a>	<a href="#">IP-AIM-C1</a>	<a href="#">IRFK6H450</a>	<a href="#">IRFP260N</a>
<a href="#">ISP1102BS</a>	<a href="#">L7812ABV</a>	<a href="#">LC4512V-75F256-10I</a>	<a href="#">LNK363GN</a>	<a href="#">LT3029EDE#PBF</a>
<a href="#">LT6100IMS8#TRPBF</a>	<a href="#">M24C64-WMN6TP</a>	<a href="#">M29F400BT70N1</a>	<a href="#">MAQ5280YME</a>	<a href="#">MAX188AEAP+</a>
<a href="#">MCP1827S-2502E/AB</a>	<a href="#">N1683CH12</a>	<a href="#">NS5S1153MUTAG</a>	<a href="#">P140CH02FLO</a>	<a href="#">PC925LENSZ0F</a>
<a href="#">PK110F80</a>	<a href="#">RPM7240-H5</a>	<a href="#">RT9176-25CL</a>	<a href="#">SI1470DH-T1-GE3</a>	<a href="#">SI4368DY-T1-E3</a>
<a href="#">SI4660DY-T1-GE3</a>	<a href="#">SKT160/16EUNF</a>	<a href="#">SMBJ30C-E3/52</a>	<a href="#">STB13NK60Z-1</a>	<a href="#">SY88933ALEYTR</a>
<a href="#">TC5563APL-12L</a>	<a href="#">TF252-4-TL-H</a>	<a href="#">TS5A3166DBVR</a>	<a href="#">TXS0102DQET</a>	<a href="#">VI-81405319</a>

Contact us:[Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited