 <p>A Renesas Company</p>	<p>X5163V14I-2.7T1</p>
	<p>Manufacturer Part Number: X5163V14I-2.7T1</p> <p>Manufacturer/Brand: Intersil</p> <p>Part of Description: IC SUPERVISOR CPU 16K EE 14TSSOP</p> <p>Datasheets: PDF X5163V14I-2.7T1.pdf</p> <p>RoHs Status: Contains lead / RoHS non-compliant</p> <p>Stock Condition: New original, Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	









Specifications

Part Number	X5163V14I-2.7T1
Manufacturer	Intersil
Description	IC SUPERVISOR CPU 16K EE 14TSSOP
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Simple Reset/Power-On Reset
Package / Case	14-TSSOP (0.173", 4.40mm Width)
Supplier Device Package	14-TSSOP
Output	Open Drain or Open Collector
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	100 ms Minimum
Voltage - Threshold	2.63V
Packaging	Tape & Reel (TR)

X5163V14I-2.7T1 is New Original in Stock, Search X5163V14I-2.7T1 Datasheets, PDF, Inventory at Y-IC.com Online, Order X5163V14I-2.7T1 Intersil with warrantied and confidence. RFQ X5163V14I-2.7T1 : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>X5163V14T1 Intersil IC SUPERVISOR CPU 16K EE 14TSSOP</p>	 <p>X5163ZAN Intersil X5163ZAN INTERSIL</p>	 <p>X5163V14I-2.7A Intersil IC SUPERVISOR CPU 16K EE 14TSSOP</p>	 <p>X5163V14IT1 Intersil IC SUPERVISOR CPU 16K EE 14TSSOP</p>
 <p>X5163ZAL INTERSI X5163ZAL INTERSI</p>	 <p>X5163V14-4.5A Intersil IC SUPERVISOR CPU 16K EE 14TSSOP</p>	 <p>X5163V14I-2.7 Intersil IC SUPERVISOR CPU 16K EE 14TSSOP</p>	 <p>X5163V14-2.7T1 Intersil IC SUPERVISOR CPU 16K EE 14TSSOP</p>

Hot Parts

[More](#)

- | | | | | |
|-----------------------|-------------------|------------------------|------------------------|-------------------|
| ⊛ 0805YC182KAT2A | ↔ 6R6D10A120BHX | ⇒ ADP120-AUJZ18R7 | D AM27C020-150JC | ⇒ AP18T10AGK |
| ⊣ APT11026JFLL | ⊛ AT25DF641-MWH-T | D B683F-2T | ⇒ BC807-16LT1G | ⇒ BTS736L2 |
| ⊛ C1005X5R1C155K050BC | ⊣ CDBB220-G | ⊛ CGA5H2X8R1E684M115AD | ↔ CGA5L3X8R1C475K160AB | ⇒ DZ1100N22K |
| D FJC1963RTF | ⊛ FMG2G75VS60 | ⊣ GRM1885C1H202JA01D | ⊛ HD64F3437TFI16 | ⇒ HT48F06E |
| ⇒ HUF76419S | ↔ ICL7611CCPA | ⊛ IRFD310PBF | ⊣ IRKH161-12 | ⇒ LM2831ZMFX |
| ↔ LQD30A48-3V3-2V5RE | ⇒ MAX14675CESE+T | D MFC400-16-1308331 | ⊛ ML03V12R1BAT2A | ⊣ NDT2955-NL |
| ⊛ NFC40-48T05-15-1X | D NKFD200-40 | ⇒ NTD4856NT4G | ↔ OPA564AIDWPR | ⇒ P1007LS08D |
| ⊣ PM25W020-100KCE | ⊛ RN2110FT | ↔ SD05C-01FTG | ⇒ SKT600/06D | ⇒ SM3323NHQAC-TRG |
| ⊛ SMP1307-001LF | ⊣ SN75176BDR | ⊛ SN761662DBTR | D STK79905 | ⇒ TA78L12F |
| ↔ TL1963A-25KTTT | ⊛ TPS652510RHAR | ⊣ TSC80C31-12CA | ⊛ UPA2450BTL-E1 | ⇒ VE-2T1-EW |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited