


	<b>HI4P0506-5Z</b>
	<b>Manufacturer Part Number:</b> <a href="#">HI4P0506-5Z</a>
	<b>Manufacturer/Brand:</b> Intersil
	<b>Part of Description:</b> IC MULTIPLEXER 16X1 28PLCC
<b>Datasheets:</b>  <a href="#">HI4P0506-5Z.pdf</a>	<b>RoHS Status:</b>  Lead free / RoHS
<b>Stock Condition:</b> Compliant New original, Stock Available.	<b>Ship From:</b> Hong Kong
<b>Image may be representation. See specs for product details.</b>	<b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS

### Specifications

Part Number	HI4P0506-5Z
Manufacturer	Intersil
Description	IC MULTIPLEXER 16X1 28PLCC
Category	Integrated Circuits (ICs) > Interface - Analog Switches,
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	0°C ~ 75°C (TA)
Package / Case	28-LCC (J-Lead)
Supplier Device Package	28-PLCC (11.51x11.51)
Number of Circuits	1
-3db Bandwidth	-
Multiplexer/Demultiplexer Circuit	16:1
Switch Circuit	-
On-State Resistance (Max)	400 Ohm
Voltage - Supply, Single (V+)	-
Voltage - Supply, Dual (V±)	±15V
Channel-to-Channel Matching (ΔRon)	20 Ohm
Switch Time (Ton, Toff) (Max)	250ns, 250ns (Typ)
Charge Injection	-
Channel Capacitance (CS(off), CD(off))	10pF, 52pF
Current - Leakage (IS(off)) (Max)	30pA (Typ)
Crosstalk	-
Packaging	Tube

HI4P0506-5Z is New Original in Stock, Search HI4P0506-5Z Datasheets, PDF, Inventory at Y-IC.com Online, Order HI4P0506-5Z Intersil with warrantied and confidence. RFQ HI4P0506-5Z : [Info@Y-IC.com](mailto:Info@Y-IC.com)

### You May Be Also Be interested

<p><b>In:</b></p>  <p><b>HI4P0508-5</b> INTERSI INTERSI PLCC</p>	 <p><b>HI4P0507-5</b> INTERSI INTERSI PLCC</p>	 <p><b>HI4P0509-5Z96</b> Intersil IC MULTIPLEXER DUAL 4X1 20PLCC</p>	 <p><b>HI4P0509-5Z</b> Intersil IC MULTIPLEXER DUAL 4X1 20PLCC</p>
 <p><b>HI4P0201-5Z</b> Intersil IC SWITCH QUAD SPST 20PLCC</p>	 <p><b>HI4-516</b> H H LCC</p>	 <p><b>HI4P0509-5</b> Intersil IC MULTIPLEXER DUAL 4X1 20PLCC</p>	 <p><b>HI4-509/883</b> INTERSI INTERSI CLCC</p>

### Hot Parts

More

- |                      |                     |                       |                        |                   |
|----------------------|---------------------|-----------------------|------------------------|-------------------|
| ⊛ 0603ZC102KAT4A     | ↔ 08055C473JAZ2A    | ⇒ 150R140A            | D AD7395AR             | ⇒ AD8052ARZ-REEL7 |
| ⊣ AK8814VQ           | ⊛ BZA856AVL         | D C4532X7R3D222K130KE | ⇒ CGA6M2X7R2A474K200AA | ⇒ CHL8103-02CRT.  |
| ⊛ CM2860KIM89TR      | ⊣ EXQ125-48S05      | ⊛ FN9263-3-06         | ↔ FT24C128A-USG-T      | ⇒ GM2574F-AS8RG   |
| D GRM0225C1E9R0DA03L | ⊛ ICS87339AGI-11LFT | ⊣ IRF7823TRPBF        | ⊛ IRFI730GPBF          | ⇒ IRFR3709ZC      |
| ⇒ IRLR8103VTR        | ↔ IRLU7821          | ⊛ ISO1176DWR          | ⊣ L08054R4CESTR        | ⇒ LAN91C96TQFP    |
| ↔ LL1005-FH1N0S      | ⇒ LQG18HN1N5S00D    | D LT1920IS8           | ⊛ LTC1196-2BCS8#PBF    | ⊣ MAX4052EEE      |
| ⊛ MAX8867EUK29-T     | D MAXQ610A-2535     | ⇒ OPA124U/2K5         | ↔ PD10IM440H           | ⇒ PQ018EZ01RPH    |
| ⊣ QM30DX-H           | ⊛ SD830YS_L2_00001  | ↔ SN74CBT3383DWR      | ⇒ SN74LVC1G38DCKR      | ⇒ SN75158DR       |
| ⊛ SP3483EN           | ⊣ SSC8035GS6        | ⊛ ST280C06C3          | D ST300C14CO           | ⇒ TCR3DF18        |
| ↔ TDA5103A           | ⊛ UMK063CH560JT-F   | ⊣ UP1B-R47            | ⊛ VI-B30-EV            | ⇒ VSSB410S-M3/52T |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited