


 life.augmented	<b>Manufacturer Part Number:</b> TS836-4IDT
	<b>Manufacturer/Brand:</b> STMicroelectronics
	<b>Part of Description:</b> IC SUPERVISOR VOLT RESET 8-SO
	<b>Datasheets:</b>  TS836-4IDT.pdf
	<b>RoHs Status:</b>  Lead free / RoHS
	<b>Stock Condition:</b> Compliant New original, Stock Available.
	<b>Ship From:</b> Hong Kong
Image may be representation. See specs for product details.	<b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS


### Specifications

Part Number	TS836-4IDT
Manufacturer	STMicroelectronics
Description	IC SUPERVISOR VOLT RESET 8-SO
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Simple Reset/Power-On Reset
Package / Case	8-SOIC (0.154", 3.90mm Width)
Supplier Device Package	8-SO
Output	Open Drain or Open Collector
Reset	Active High
Number of Voltages Monitored	1
Reset Timeout	20 µs Typical Response Time
Voltage - Threshold	4.5V
Packaging	Tape & Reel (TR)

TS836-4IDT is New Original in Stock, Search TS836-4IDT Datasheets, PDF, Inventory at Y-IC.com Online, Order TS836-4IDT STMicroelectronics with warrantied and confidence. RFQ  
TS836-4IDT : Info@Y-IC.com

### You May Be Also Be interested

In:

 <b>TS834-5ID</b> STMicroelectronics IC SUPERVISOR VOLT RESET 8-SOIC	 <b>TS834-5IPT</b> STMicroelectronics IC SUPERVISOR RESET 4.33V 8TSSOP	 <b>TS836-4IPT</b> STMicroelectronics IC SUPERVISOR VOLT RESET 8-TSSOP	 <b>TS834-5IDT</b> STMicroelectronics IC SUPERVISOR VOLT MCRPWR 8SOIC
 <b>TS83C51RB2-MA</b> TEMIC TEMIC TQFP44	 <b>TS836-4ID</b> STMicroelectronics IC SUPERVISOR VOLT RESET 8-SO	 <b>TS836-4IZ-AP</b> STMicroelectronics IC SUPERVISOR VOLT RESET TO-92	 <b>TS836-4IZT</b> STMicroelectronics IC SUPERVISOR VOLT RESET TO-92

### Hot Parts

More

- |                      |                      |                       |                      |                      |
|----------------------|----------------------|-----------------------|----------------------|----------------------|
| 2220AC332KAT1A       | 293D476X9016C2TE3    | 6MBP35VFN120-50       | D ADP3330ARTZ-5      | AMS1084CT-3.3        |
| AP4434GM-HF          | B340LB-13-F          | D C0603X5R1E331K030BA | CGA2B2C0G1H390J050BA | CGA3E1X7R1E684K080AD |
| CGA5H2X8R1E684K115AA | CMKD4448TR           | CY7C264-55WC          | DS32KHZSN#T&R        | DTD114EKT146         |
| ELM9427B-S           | HAT2015R-EL          | HCPL-V601             | IP-J21-EZ            | IRU1015CMTR          |
| L6585DTR             | LT1304CS8#TRPBF      | LT1461DHS8-3.3        | LT3680EMSE#PBF       | LTC1483IS8#TRPBF     |
| LTC2923CDE           | LTC4210-1CS6         | LX881533CDF-TANDR     | MAX4717EUB           | MAX5063CASA+T        |
| MB310T/R             | MBM29F002BC-70PD-SFK | MM3Z47VB              | NJM79L05UA-TE1-E3-B  | P6SMBJ200A_R1_00001  |
| PAH75D48-3325        | PK200FG40            | RK7002BMT116          | RL2010FK-07R62L      | RT9169-32CX          |
| S-1166B28MC-N7PTFG   | S-80860CLNB-B7LT2G   | SMBG6.5A-E3/52        | SML-D12FWT86         | SP6205EM5-L-1-8/TR   |
| SP6654EU/TR          | TPS79425DGNR         | VE-J22-IY             | VI-J62-CY            | VUO28-08N07          |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited