


	<p><b>S-80844CLNB-B65T2U</b></p>
	<p><b>Manufacturer Part Number:</b> S-80844CLNB-B65T2U</p>
	<p><b>Manufacturer/Brand:</b> SII Semiconductor Corporation</p>
	<p><b>Part of Description:</b> IC VOLT DETECTOR 4.4V SC-82AB</p>
	<p><b>Datasheets:</b>  <a href="#">S-80844CLNB-B65T2U.pdf</a></p>
	<p><b>RoHS Status:</b>  Lead free / RoHS</p>
	<p><b>Stock Condition:</b> Compliant New original, Stock Available.</p>
	<p><b>Ship From:</b> Hong Kong</p>
<p>Image may be representation. See specs for product details.</p>	<p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p>

### Specifications

Part Number	S-80844CLNB-B65T2U
Manufacturer	SII Semiconductor Corporation
Description	IC VOLT DETECTOR 4.4V SC-82AB
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	S-808xxC
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Voltage Detector
Package / Case	SC-82A, SOT-343
Supplier Device Package	SC-82AB
Output	Push-Pull, Totem Pole
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	-
Voltage - Threshold	4.4V
Packaging	Tape & Reel (TR)

S-80844CLNB-B65T2U is New Original in Stock, Search S-80844CLNB-B65T2U Datasheets, PDF, Inventory at Y-IC.com Online, Order S-80844CLNB-B65T2U SII Semiconductor Corporation with warrantied and confidence. RFQ S-80844CLNB-B65T2U : Info@Y-IC.com

### You May Be Also Be interested

In:

 <p><b>S-80844CLNB</b> SEIKO S-80844CLNB SEIKO</p>	 <p><b>S-80844CLNB-B65T2G</b> SII Semiconductor Corporation IC VOLT DETECTOR 4.4V SC-82AB</p>	 <p><b>S-80844CLUA-B65T2G</b> SII Semiconductor Corporation IC VOLT DETECTOR 4.4V SOT89-3</p>	 <p><b>S-80844CLUA-B65-T2</b> SEIKO S-80844CLUA-B65-T2 SEIKO</p>
 <p><b>S-80844CLPF-B65TFU</b> SII Semiconductor Corporation IC VOLT DETECTOR 4.4V SNT-4A</p>	 <p><b>S-80844CLMC-B65T2U</b> SII Semiconductor Corporation IC VOLT DETECTOR 4.4V SOT23-5</p>	 <p><b>S-80844CLPF-B65TFG</b> SII Semiconductor Corporation IC VOLT DETECTOR 4.4V SNT-4A</p>	 <p><b>S-80844CLUA-B65T2U</b> SII Semiconductor Corporation IC VOLT DETECTOR 4.4V SOT89-3</p>

### Hot Parts

More

- |                  |                    |                      |                        |                     |
|------------------|--------------------|----------------------|------------------------|---------------------|
| ⊛ 08053A1R3BAT2A | ↔ 1808GA390KAT9A   | ⇒ 1808WC681MAT3A     | D AIC1680N-35PU        | ⇒ AMIS30660CANH2RG  |
| ⊣ AP8801-50GX    | ⊛ BD46255G-TR      | D BZX84C7V5LT1G      | ⇒ C3216CH2E822J160AA   | ⇒ CC0402FRNP09BN200 |
| ⊛ CD430660       | ⊣ FT1000EY-20      | ⊛ GRM1555C1E4R7B201D | ↔ IXFX90N30            | ⇒ LMK105BJ473KV-F   |
| D LMV981IDCKR    | ⊛ LQH31CN100K03L   | ⊣ LT4351IMS#PBF      | ⊛ LTC1844ES5-1.8#TRPBF | ⇒ M30623F8PGP       |
| ⇒ MA2J111000L    | ↔ MB88141A         | ⊛ MIC5219-2.7YM5     | ⊣ MT46H16M32LFCX-5IT:B | ⇒ NTB75N03L09G      |
| ↔ PC80Q04N       | ⇒ PK4121ASI        | D S1JHE3/5AT         | ⊛ SCS4805S1            | ⊣ SF10A400HD        |
| ⊛ SFH6106-1T     | D SI3447CDV-T1-E3  | ⇒ SIA456DJ-T1-GE3    | ↔ SKM151FR             | ⇒ SSW-110-02-S-D    |
| ⊣ STT130GK14     | ⊛ TC1015-2.7VCT713 | ↔ TEN3-2411          | ⇒ TK33S10N1Z           | ⇒ TMK316AB7475MLHT  |
| ⊛ TPA6136A2YFFR  | ⊣ TPC8076-H        | ⊛ UCC3809DTR-1       | D UCN5800A             | ⇒ V110C12C150BN     |
| ↔ VI-J50-CX-01   | ⊛ VI-J5Y-CW        | ⊣ VUO68-16           | ⊛ XC4052XLA-09BG352I   | ⇒ ZXM64P035GTA      |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited