


 life.augmented	TS831-4IZT
	Manufacturer Part Number: TS831-4IZT
	Manufacturer/Brand: STMicroelectronics
	Part of Description: IC SUPERVISOR RESET 4.50V TO-92
	Datasheets:  TS831-4IZT.pdf
	RoHs Status:  Lead free / RoHS
	Stock Condition: Compliant New original, Stock Available.
	Ship From: Hong Kong
Image may be representation. See specs for product details.	Shipment Way: DHL/Fedex/TNT/UPS/EMS

Specifications

Part Number	TS831-4IZT
Manufacturer	STMicroelectronics
Description	IC SUPERVISOR RESET 4.50V TO-92
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 125°C (TA)
Mounting Type	Through Hole
Type	Simple Reset/Power-On Reset
Package / Case	TO-226-3, TO-92-3 (TO-226AA) (Formed Leads)
Supplier Device Package	TO-92-3
Output	Open Drain or Open Collector
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	20 µs Typical Response Time
Voltage - Threshold	4.5V
Packaging	Tape & Reel (TR)

TS831-4IZT is New Original in Stock, Search TS831-4IZT Datasheets, PDF, Inventory at Y-IC.com Online, Order TS831-4IZT STMicroelectronics with warrantied and confidence. RFQ TS831-4IZT : Info@Y-IC.com

You May Be Also Be interested

In:

 TS831-5IPT STMicroelectronics IC SUPERVISOR RESET 4.50V 8TSSOP	 TS831-4IPT STMicroelectronics IC SUPERVISOR RESET 4.50V 8TSSOP	 TS831-4IZ-AP\$YB ST TS831-4IZ-AP\$YB ST	 TS831-4IZ STMicroelectronics IC SUPERVISOR RESET 4.50V TO-92
 TS831-4IZ-AP STMicroelectronics IC SUPERVISOR RESET 4.50V TO-92	 TS831-5IZ STMicroelectronics IC SUPERVISOR RESET 4.33V TO-92	 TS831-5ID STMicroelectronics IC SUPERVISOR RESET 4.33V 8- SOIC	 TS831-5IDT STMicroelectronics IC SUPERVISOR VOLT MCRPWR 8SOIC

Hot Parts

More

- | | | | | |
|--|--|--|---|--|
|  0603YG333ZAT2A |  08053C473JAZ2A |  12103C334K4T2A |  195D226X9020ZT 22UF 10% 20V |  6MBI100UC-120-02 |
|  6MBI50UA060-50 |  7MBR20VKA060-50 |  AP1186K5LA |  AP6503ASP-13 |  APT50M85LVR |
|  ATTV4910ACH-TR |  BCM43234KMLG |  BU9409FV |  BZT52H-B27 |  CC0402BRNP09BN9R1 |
|  CGJ5H2C0G2A682J115AA |  CL31B223KHHNNNE |  CRCW2010402RFKEF |  DTC114YUA-TP |  GRJ216R72A222KE01D |
|  GRM0336S1E8R0CD01D |  GRM2196R2A5R3DD01D |  IRFP048PBF |  K50-3C0-SE20.0000MR |  MAX4234AUD |
|  MAX8877EUK50 |  MF-SM030-2-H5 |  MJH11017 |  MMBT5551-7 |  NM93C66LZM8X |
|  NP32N055SHE |  P3Z7AAT800W |  PDTA124XEF |  PMA4118LSF |  PMB2212RV1.1 |
|  PRF18BE471RB5RB |  R5F211B3D53SP#U0 |  RT0805BRE07270K |  S-25A320A0A-J8T2GD |  S25FL064P0XMF1001 |
|  SI4825DY-T1-E3 |  SMAJ130CA-E3/61 |  STM32F103 |  TDA8595TH/N2S |  TMP47P422VU |
|  TOP242YN |  TPA6203A1ZQVR |  TPS79942DDCR |  VI-210-CY |  VI-21P-CV |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited