

 <p>Not Actual Photo YIC International Co., Limited.</p>	<h2 style="color: red;">MK1442-02S</h2>
	<p>Manufacturer Part Number: MK1442-02S</p> <p>Manufacturer/Brand: MICROCLOC</p> <p>Part of Description: MICROCLOC SOIC-16</p> <p>RoHs Status:</p> <p>Stock Condition: New original, 1900 pcs Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	




Specifications

Part Number	MK1442-02S
Manufacturer	MICROCLOC
Description	MICROCLOC SOIC-16
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	1900 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

MK1442-02S is New Original in Stock, Search MK1442-02S Datasheets, PDF, Inventory at Y-IC.com Online, Order MK1442-02S with warrantied and confidence. RFQ MK1442-02S : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>MK1443-D2S ICS ICS SOP16</p>	 <p>MK1438-01RTR MICROCLOCK MICROCLOCK SSOP</p>	 <p>MK1444-04S MICROCLOC MICROCLOC SOP16</p>	 <p>MK1443-02 MICROCLOC MICROCLOC SOP16</p>
 <p>MK1437-02STR MIC MK1437-02STR MIC</p>	 <p>MK1443-02S MICROCLOC MICROCLOC SOP-16</p>	 <p>MK1443-02STR MICROCL MICROCL SOP16</p>	 <p>MK1442-01S ICS ICS SOP16</p>

Hot Parts

[More](#)

- | | | | | |
|--------------------|-----------------------|---------------------|---------------------|-------------------------|
| ⚙️ 6NBI125LB-120 | ➡️ AD8091ARTZ-RL7 | ➡️ BA5956FM-E2 | D BTA208S-600B | ➡️ C1608JB1C474K080AA |
| ⚡️ CL05F104Z05NNND | ⚙️ CLC5957MTDX | D CX20524-15 | ➡️ EP2C8F256I8N | ➡️ FM-1040FN-F-SNR |
| ⚙️ FQA14N30 | ⚡️ FS50R12U1T4 | ⚙️ FSA2271TUMX | ➡️ FUSB302UCX | ➡️ GRM1887U1H330JZ01D |
| D HAT1047RJ | ⚙️ IHLP1212BZER1R0M11 | ⚡️ IRFP22N60K | ⚙️ LC898217XH-MH | ➡️ LD2981ABM30TR |
| ➡️ LMX2531LQ1700E | ➡️ LP3874ESX-ADJ | ⚙️ LT1001CS8#TRPBF | ⚡️ LT1121CS8-3.3#TR | ➡️ LTC4300A-1IMS8#TRPBF |
| ➡️ M41T94MQ6 | ➡️ MAX4412EXK+T | D MAX845EUA+T | ⚙️ PIC16LF1826-I/MV | ⚡️ PM30-24S15 |
| ⚙️ PSMN045-80YS | D S1D13776B00B11B | ➡️ SBLF2040CT | ➡️ SE30AFD-M3/6A | ➡️ SK300GA100DC |
| ⚡️ SM3095PSD | ⚙️ SN74LVC1G34DCKRE4 | ➡️ SP809EK-2-3/TR | ➡️ ST203C06CFJ | ➡️ TC1185-1.8VCT |
| ⚙️ TC7116CPL | ⚡️ TCM320AC39CPT | ⚙️ TMK105ABJ474KV-F | D TPS51728RHAR | ➡️ TPS73133DBVR |
| ➡️ TPS76518DR | ⚙️ TZMC5252B-GS08 | ⚡️ UWR-5/3000-D48AT | ⚙️ VI-JW2-04 | ➡️ VI-RAM-EZ |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited