

	<h2>S-80817CLNB-B6CT2U</h2>
	<p>Manufacturer Part Number: S-80817CLNB-B6CT2U</p> <p>Manufacturer/Brand: SII Semiconductor Corporation</p> <p>Part of Description: IC VOLT DETECTOR 1.7V SC-82AB</p> <p>Datasheets: S-80817CLNB-B6CT2U.pdf</p> <p>RoHS Status:  Lead free / RoHS</p> <p>Stock Condition: Compliant New original, Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	

Specifications

Part Number	S-80817CLNB-B6CT2U
Manufacturer	SII Semiconductor Corporation
Description	IC VOLT DETECTOR 1.7V SC-82AB
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	S-808xxC
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Voltage Detector
Package / Case	SC-82A, SOT-343
Supplier Device Package	SC-82AB
Output	Push-Pull, Totem Pole
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	-
Voltage - Threshold	1.7V
Packaging	Tape & Reel (TR)

S-80817CLNB-B6CT2U is New Original in Stock, Search S-80817CLNB-B6CT2U Datasheets, PDF, Inventory at Y-IC.com Online, Order S-80817CLNB-B6CT2U SII Semiconductor Corporation with warrantied and confidence. RFQ S-80817CLNB-B6CT2U : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>S-80817CLPF-B6CTFU SII Semiconductor Corporation IC VOLT DETECTOR 1.7V SNT-4A</p>	 <p>S-80817CLY-B-G SII Semiconductor Corporation IC VOLT DETECTOR 1.7V TO-92</p>	 <p>S-80817CLMC-B6CT2U SII Semiconductor Corporation IC VOLT DETECTOR 1.7V SOT23-5</p>	 <p>S-80817ANNP-EDE-T2 SEIKO S-80817ANNP-EDE-T2 SEIKO</p>
 <p>S-80817CLNB-B6CT2G SII Semiconductor Corporation IC VOLT DETECTOR 1.7V SC-82AB</p>	 <p>S-80817CLPF-B6CTFG SII Semiconductor Corporation IC VOLT DETECTOR 1.7V SNT-4A</p>	 <p>S-80817CLMC-B6CT2G SII Semiconductor Corporation IC VOLT DETECTOR 1.7V SOT23-5</p>	 <p>S-80817CLUA-B6CT2G SII Semiconductor Corporation IC VOLT DETECTOR 1.7V SOT89-3</p>

Hot Parts

More

- | | | | | |
|-------------------|-------------------|-----------------------|----------------------|----------------------|
| ⊛ 08053A821JAT4A | ↔ 154501D0449 | ⇒ 1N4148W-7 | D AD587KRZ-REEL | ⇒ AP1501-33K5LA |
| ⊣ ATA5721C-PLQW | ⊛ ATF860X12D | D BD8651FV-E2 | ⇒ BK1608LL181-T | ⇒ BZT52-B30ST/R |
| ⊛ EL3012M-V | ⊣ FZT600BTA | ⊛ GCM1885C1H3R8CA16D | ↔ GRM0335C1E2R3BA01D | ⇒ GRM31CC80J476KE18L |
| D IPP65R110CFDA | ⊛ IRL3705ZSPBF | ⊣ JMK107BJ335KA-T | ⊛ K6T0808C1D-GB70 | ⇒ KPTB-1612LNSGC |
| ⇒ LD2981ABM33TR | ↔ LMX2532LQ1065 | ⊛ LQH2HPN2R2MJ0L | ⊣ LT1170HVIQ | ⇒ LT3023IDD#PBF |
| ↔ M63993FP | ⇒ MIC2005-1.2BM6 | D MT2060-F-02 | ⊛ PK55F160 | ⊣ R3955SH20 |
| ⊛ RM25HG24S | D S2A-E3/52T | ⇒ SCA200A160 | ↔ SE30AFD-M3/6A | ⇒ SI2300DS |
| ⊣ SN74ALS86N | ⊛ SN74LVC574ARGYR | ↔ SST39VF160-70-4C-EK | ⇒ TCET1109G | ⇒ TDA7492PETR |
| ⊛ TMK325B7475KNHT | ⊣ TRS207CDBR | ⊛ TT66N8FN | D VI-911628 | ⇒ VI-J43-IW |
| ↔ WM8962BECSN/R | ⊛ WR48S12/60K | ⊣ XC6221S10XGR | ⊛ YS190113P40G | ⇒ ZK800A1400V |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited