










 <p>A Renesas Company</p>	<h2 style="color: red;">ISL31490EUIZ-T7A</h2>		
	<p><b>Manufacturer Part Number:</b> <a href="#">ISL31490EUIZ-T7A</a></p>		
	<p><b>Manufacturer/Brand:</b> <a href="#">Intersil</a></p>		
	<p><b>Part of Description:</b> IC TXRX RS485 FAULT PROT 10MSOP</p>		
	<p><b>Datasheets:</b>  <a href="#">ISL31490EUIZ-T7A.pdf</a></p>		
	<p><b>RoHs Status:</b>  Lead free / RoHS</p>		
	<p><b>Stock Condition:</b> Compliant New original, Stock Available.</p>		
	<p><b>Ship From:</b> Hong Kong</p>		
<p>Image may be representation. See specs for product details.</p>	<p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p>		

### Specifications

Part Number	<a href="#">ISL31490EUIZ-T7A</a>
Manufacturer	<a href="#">Intersil</a>
Description	IC TXRX RS485 FAULT PROT 10MSOP
Category	<a href="#">Integrated Circuits (ICs) &gt; Interface - Drivers, Receivers,</a>
Part Status	<a href="#">Require For Quote &amp; Check Stock</a>
Series	-
Operating Temperature	-40°C ~ 85°C
Mounting Type	Surface Mount
Type	Transceiver
Package / Case	10-TFSOP, 10-MSOP (0.118", 3.00mm Width)
Supplier Device Package	10-MSOP
Voltage - Supply	4.5 V ~ 5.5 V
Protocol	RS422, RS485
Number of Drivers/Receivers	1/1
Duplex	Full
Receiver Hysteresis	25mV
Data Rate	250kbps
Packaging	Tape & Reel (TR)

ISL31490EUIZ-T7A is New Original in Stock, Search ISL31490EUIZ-T7A Datasheets, PDF, Inventory at Y-IC.com Online, Order ISL31490EUIZ-T7A Intersil with warrantied and confidence.  
RFQ ISL31490EUIZ-T7A : [Info@Y-IC.com](mailto:Info@Y-IC.com)

### You May Be Also Be interested

<p><b>In:</b></p>  <p><b>ISL31492EIBZ-T</b> Intersil IC TXRX RS485 FAULT PROT 8SOIC</p>	 <p><b>ISL31490EIRTZ</b> Intersil IC TXRX RS485 FAULT PROT 10TDFN</p>	 <p><b>ISL31491EIBZ-T</b> Intersil IC TXRX RS485 FAULT PROT 8SOIC</p>	 <p><b>ISL31491EIBZ-T7A</b> Intersil IC TXRX RS485 FAULT PROT 8SOIC</p>
 <p><b>ISL31491EIBZ</b> Intersil IC TXRX RS485 FAULT PROT 8SOIC</p>	 <p><b>ISL31492EIBZ</b> Intersil IC TXRX RS485 FAULT PROT 8SOIC</p>	 <p><b>ISL31490EIRTZ-T7A</b> Intersil IC TXRX RS485 FAULT PROT 10TDFN</p>	 <p><b>ISL31490EUIZ</b> Intersil IC TXRX RS485 FAULT PROT 10MSOP</p>

### Hot Parts

[More](#)

0603ZC273KAT4A	2MBI450U4N-170-50	6MBI100U4B-120	AD45061-REEL	AIC1633PS
CL10C150JB8NNNC	CQ0805CRNPO0BN5R1	DIM400WLS12-A	DXT2012P5-13	ELM33417CA
EMX18T2R	EP1C4F324I7	EP3C5F256I7N	GQM2195C2A8R2CB01D	GRM1555C1E391JA01D
GRM1555C1HR50CZ01D	IP-263-EU	ISL97682IRTZ	IXFX90N30	J2S-Q02A-C
LP5951MG-1.5	LQG15HN39NJ02D	LT1375IS8	MAX4772ETT+TG40	MBRS120LT1
MC10EL07DR2G	MDD172-13N1	MJE243G.	MTP3055VL	NCV612SQ28T1G
NMC1206X5R226M16TRPLPF	PBD90/08	PCS3P73F01	R2J20602NP	R5F212K4SNFP
S29AL004D70TFI01	SD101AW-7-F	SD2500API	SG2001-3.3XN5	SI4459ADY-T1-GE3
SI7716ADN-TI-GE3	SN0307009BZHK	SN74LVC823ADBR	TPS7A1601DRBR	TPSMAC30A
TW2984-NA2-CR	UQCL2A240JAT2A\500	VE-J03-MY	VUO85-14N07	Z161B-10

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited