


	<h2>S-80913CLNB-G6HT2G</h2>
	<p><b>Manufacturer Part Number:</b> S-80913CLNB-G6HT2G</p> <p><b>Manufacturer/Brand:</b> SII Semiconductor Corporation</p> <p><b>Part of Description:</b> IC VOLT DETECTOR 1.3V SC-82AB</p> <p><b>Datasheets:</b>  <a href="#">S-80913CLNB-G6HT2G.pdf</a></p> <p><b>RoHS Status:</b>  Lead free / RoHS</p> <p><b>Stock Condition:</b> Compliant New original, Stock Available.</p> <p><b>Ship From:</b> Hong Kong</p> <p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	









### Specifications

Part Number	S-80913CLNB-G6HT2G
Manufacturer	SII Semiconductor Corporation
Description	IC VOLT DETECTOR 1.3V SC-82AB
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	S-809xxC
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Voltage Detector
Package / Case	SC-82A, SOT-343
Supplier Device Package	SC-82AB
Output	Push-Pull, Totem Pole
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	2.7 ms Minimum
Voltage - Threshold	1.3V
Packaging	Tape & Reel (TR)

S-80913CLNB-G6HT2G is New Original in Stock, Search S-80913CLNB-G6HT2G Datasheets, PDF, Inventory at Y-IC.com Online, Order S-80913CLNB-G6HT2G SII Semiconductor Corporation with warrantied and confidence. RFQ S-80913CLNB-G6HT2G : Info@Y-IC.com

### You May Be Also Be interested

In:

 <p><b>S-80913CNMC</b> SEIKO S-80913CNMC SEIKO</p>	 <p><b>S-80913CLMC-G6HT2G</b> SII Semiconductor Corporation IC VOLT DETECTOR 1.3V SOT23-5</p>	 <p><b>S-80913CNMC-G8HT2G</b> SII Semiconductor Corporation IC VOLT DETECTOR 1.3V SOT23-5</p>	 <p><b>S-80913CLMC-G6HT2U</b> SII Semiconductor Corporation IC VOLT DETECTOR 1.3V SOT23-5</p>
 <p><b>S-80913CLPF-G6HTFG</b> SII Semiconductor Corporation IC VOLT DETECTOR 1.3V SNT-4A</p>	 <p><b>S-80913CLPF-G6HTFU</b> SII Semiconductor Corporation IC VOLT DETECTOR 1.3V SNT-4A</p>	 <p><b>S-80913ANMP</b> SEIKO S-80913ANMP SEIKO</p>	 <p><b>S-80912ANMP-D72-T2</b> SEIKO S-80912ANMP-D72-T2 SEIKO</p>

### Hot Parts

More

- |                        |                      |                  |                       |                        |
|------------------------|----------------------|------------------|-----------------------|------------------------|
| ⊛ 06031A221JAT2A       | ↔ 12061A751JAT2A     | ⇒ 6DI20S-060     | D 6MBI100F-060        | ⇒ ADM1811-10ARTZ       |
| ⊣ AN77L08M-E1          | ⊛ AP1509-5.0         | D BSP296NH6327   | ⇒ CB346MIB            | ⇒ CGA3E2C0G2A6R8D080AD |
| ⊛ CGA5F1X7T2J153M085AC | ⊣ DT93N16K0F         | ⊛ ELM14620AA-N   | ↔ FDMC2512SDC         | ⇒ GMK212BJ474KGHT      |
| D GRM0335C1H6R6BA01D   | ⊛ GRM1885C1H1R2CZ01D | ⊣ HCM1305-1R5-R  | ⊛ HCPL-2730           | ⇒ HMA2701R2            |
| ⇒ HVC306ATRU           | ↔ IR2D26U6           | ⊛ IR333C/H2/L268 | ⊣ IS43R16160D-5TL-TR  | ⇒ IXGH17N100AU1        |
| ↔ KD324515             | ⇒ LDG500-48S28       | D LM2902PT       | ⊛ LSF0108RKSR         | ⊣ M1MA152KT1           |
| ⊛ M24C64-WMN6TP        | D MLK0603L2N4ST000   | ⇒ MP23AB02BTR    | ↔ MPB252010T-2R2M0NA2 | ⇒ MT46V16M16P-5B       |
| ⊣ MVB20040CT           | ⊛ PS8501L3-V-E3-     | ↔ RP1205-18PBR   | ⇒ RURD4120            | ⇒ S-93C46ADP           |
| ⊛ SAFEA2G01FLOF00      | ⊣ SI3441DV           | ⊛ SP488ECT       | D SSM3J120TU          | ⇒ ST72651AR6T1/NYM     |
| ↔ TCM1005-900-2P-T002  | ⊛ TLE62510S          | ⊣ TM55EZ-24      | ⊛ TPS78625KTTTRG3     | ⇒ VC15MA0340KBA        |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited