

 <p>A Renesas Company</p>	<p>ISL23428UFVZ-TK</p>
	<p>Manufacturer Part Number: ISL23428UFVZ-TK</p> <p>Manufacturer/Brand: Intersil</p> <p>Part of Description: IC DGTL POT 2CH 50K 14TSSOP</p> <p>Datasheets:  ISL23428UFVZ-TK.pdf</p> <p>RoHs Status:  Lead free / RoHS</p> <p>Stock Condition: Compliant New original, Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	









Specifications

Part Number	ISL23428UFVZ-TK
Manufacturer	Intersil
Description	IC DGTL POT 2CH 50K 14TSSOP
Category	Integrated Circuits (ICs) > Data Acquisition - Digital
Part Status	Require For Quote & Check Stock
Series	XDCP™
Operating Temperature	-40°C ~ 125°C
Features	-
Interface	SPI
Configuration	Potentiometer
Tolerance	±20%
Package / Case	14-TSSOP (0.173", 4.40mm Width)
Supplier Device Package	14-TSSOP
Number of Circuits	2
Voltage - Supply	1.2 V ~ 5.5 V, 1.7 V ~ 5.5 V
Memory Type	Volatile
Resistance (Ohms)	50k
Taper	Linear
Number of Taps	128
Temperature Coefficient (Typ)	65 ppm/°C
Resistance - Wiper (Ohms) (Typ)	70
Packaging	Tape & Reel (TR)

ISL23428UFVZ-TK is New Original in Stock, Search ISL23428UFVZ-TK Datasheets, PDF, Inventory at Y-IC.com Online, Order ISL23428UFVZ-TK Intersil with warrantied and confidence. RFQ ISL23428UFVZ-TK : Info@Y-IC.com



















































You May Be Also Be interested

In:

 <p>ISL23428WVFZ Intersil IC DGTL POT 2CH 10K 14TSSOP</p>	 <p>ISL23428WFRUZ-TK Intersil IC DGTL POT 2CH 10K 16UTQFN</p>	 <p>ISL23428UFRUZ-TK Intersil IC DGTL POT 2CH 50K 16UTQFN</p>	 <p>ISL23428WVFZ-TK Intersil IC DGTL POT 2CH 10K 14TSSOP</p>
 <p>ISL23428UFVZ Intersil IC DGTL POT 2CH 50K 14TSSOP</p>	 <p>ISL23428UFVZ-T7A Intersil IC DGTL POT 2CH 50K 14TSSOP</p>	 <p>ISL23428WFRUZ-T7A Intersil IC DGTL POT 2CH 10K 16UTQFN</p>	 <p>ISL23428WVFZ-T7A Intersil IC DGTL POT 2CH 10K 14TSSOP</p>

Hot Parts

[More](#)

- | | | | | |
|--|--|---|--|--|
|  06035A1R2C4T2A |  08051A9R1DAT2A |  111MT100KB |  D 1827589-2 |  2225AC333KAT1A\SB |
|  ADM1032ARMZ-REEL7 |  ADM1811-10ARTZ-RL7 |  D ADS1000A1IDBVR |  AH175-WG-7-B |  AT17LV256-10PI |
|  BCP5216TA |  BF1005-A2 |  C2012X8R1H104KT000H |  C3216C0G2J121J060AA |  CC1206ZKY5V9BB225 |
|  D CGA3EAC0G2A332J080AC |  CP0402A1842BNTR |  DZ540N04K |  ESM3045DF |  FAN5365UC00X |
|  HAT20AAJ |  HCNW3120 |  HCPL-2611-020E |  ICL7611DCBA-T |  IHLP5050CERZ1R0M01 |
|  ISL6556BCR-T |  IXFP110N15T2 |  D LA7780M-TE-L |  LMX2316TMX |  LTC1199LCMS8#TRPBF |
|  LTC3728LXCUH#TRPBF |  D M74HC126RM13TR |  MPQ2451DT-LF-Z |  MSO15000-C |  OPA333AIDBVR |
|  PC81715NIP0F |  PE-65723NLT |  PI5L102LEX |  PSMN4R2-30MLD |  R3101012 |
|  RSS090N03TB. |  S-80815ALUP-EAC-T2 |  S-812C43BMC-C4XT2G |  D SiR404DP-T1-E3 |  SMV1417-001LF |
|  TC4SU11F |  TL061ACP |  UDN2588A-T |  VND5E012AY-E |  VS-MBRS360TRPBF |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited