	<p><b>GRM39CH180J50PT</b></p>
	<p><b>Manufacturer Part Number:</b> GRM39CH180J50PT</p> <p><b>Manufacturer/Brand:</b> MURATA</p> <p><b>Part of Description:</b> MURATA SMD</p> <p><b>RoHs Status:</b></p> <p><b>Stock Condition:</b> New original, 4500 pcs Stock Available.</p> <p><b>Ship From:</b> Hong Kong</p> <p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	


**Specifications**

Part Number	GRM39CH180J50PT
Manufacturer	MURATA
Description	MURATA SMD
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	4500 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

GRM39CH180J50PT is New Original in Stock, Search GRM39CH180J50PT Datasheets, PDF, Inventory at Y-IC.com Online, Order GRM39CH180J50PT with warrantied and confidence. RFQ GRM39CH180J50PT : Info@Y-IC.com

You May Be Also Be interested

In:

 <p><b>GRM39C0G3R3C50Z500/T115</b> Murata Electronics GRM39C0G3R3C50Z500/T115 MURATA</p>	 <p><b>GRM39COG070D50P</b> MURATA GRM39COG070D50P MURATA</p>	 <p><b>GRM39COG181J50D500</b> MURATA GRM39COG181J50D500 MURATA</p>	 <p><b>GRM39C0G510J50D500/T115</b> Murata Electronics GRM39C0G510J50D500/T115 MURATA</p>
 <p><b>GRM39CK020C50Z500</b> Original PT266</p>	 <p><b>GRM39CH430J50PT</b> MURATA</p>	 <p><b>GRM39C0G471J50PT</b> MURATA MURATA SMD</p>	 <p><b>GRM39C0G471J50D500/T115</b> Murata Electronics GRM39C0G471J50D500/T115 MURATA</p>

**Hot Parts** More

- |                      |                       |                       |                      |                     |
|----------------------|-----------------------|-----------------------|----------------------|---------------------|
| ⚙️ 12062A1R0BAT2A    | ➡️ ACPM-7381          | ➡️ AP1117K18LA        | D AT49LV002-12TC     | ➡️ AT88SC0808C      |
| ⚡️ BA33B00FP-E2      | ⚙️ BZM55B51-TR        | D C3225Y5V1A476Z      | ➡️ CC0603DRNPO9BN7R0 | ➡️ CM100DY-24E      |
| ⚙️ CMHZ5227B         | ⚡️ CSNF161-002        | ⚙️ DDTC123EUA-7-F     | ➡️ DS1624S+          | ➡️ ESD9X12ST5G      |
| D GRM1556T1H6R1CD01D | ⚙️ GRM1886S1H131JZ01D | ⚡️ GRM188R71H152JA01D | ⚙️ HT-121BP5         | ➡️ IRGBC30M         |
| ➡️ IXTA5N50P         | ➡️ KA2000A800V        | ⚙️ LM385BLP-2.5V      | ⚡️ LT3080EST#TRPBF   | ➡️ LTC1290BCSW      |
| ➡️ MAX814LESAT       | ➡️ MBRS1100TRPBF      | D MG400J1US21         | ⚙️ MIG50J5PS60S      | ⚡️ MLF2012DR56KT000 |
| ⚙️ MVR22HXBRN101     | D PE42850MLBA-X       | ➡️ PKL4119APILA       | ➡️ PSMN070-200P      | ➡️ R0809LS10B       |
| ⚡️ RB151L-40         | ⚙️ S-L2985B2J-H4T1    | ➡️ S29GL512P11TFI01   | ➡️ SKD146/12-L105    | ➡️ SL0902A090SM     |
| ⚙️ SMV1233-994LF     | ⚡️ SP3222CY           | ⚙️ ST380CH06C0L       | D T1270N38TOF        | ➡️ TA7774GP         |
| ➡️ TK11248AMTL       | ⚙️ TLE2037CDR         | ⚡️ TMK107BBJ225KAHT   | ⚙️ TS944AIN          | ➡️ UPD72870AF1-FA2  |