


	<p>S-80915CLNB-G6KT2U</p>
	<p>Manufacturer Part Number: S-80915CLNB-G6KT2U</p>
	<p>Manufacturer/Brand: SII Semiconductor Corporation</p>
	<p>Part of Description: IC VOLT DETECTOR 1.5V SC-82AB</p>
	<p>Datasheets:  S-80915CLNB-G6KT2U.pdf</p>
	<p>RoHS Status:  Lead free / RoHS</p>
	<p>Stock Condition: Compliant New original, Stock Available.</p>
	<p>Ship From: Hong Kong</p>
<p>Image may be representation. See specs for product details.</p>	<p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>

Specifications

Part Number	S-80915CLNB-G6KT2U
Manufacturer	SII Semiconductor Corporation
Description	IC VOLT DETECTOR 1.5V SC-82AB
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	S-809xxC
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Voltage Detector
Package / Case	SC-82A, SOT-343
Supplier Device Package	SC-82AB
Output	Push-Pull, Totem Pole
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	18 ms Minimum
Voltage - Threshold	1.5V
Packaging	Tape & Reel (TR)

S-80915CLNB-G6KT2U is New Original in Stock, Search S-80915CLNB-G6KT2U Datasheets, PDF, Inventory at Y-IC.com Online, Order S-80915CLNB-G6KT2U SII Semiconductor Corporation with warrantied and confidence. RFQ S-80915CLNB-G6KT2U : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>S-80915CNMC-G8K-G SEIKO SEIKO SOT25</p>	 <p>S-80915CLNB-G6KT2G SII Semiconductor Corporation IC VOLT DETECTOR 1.5V SC-82AB</p>	 <p>S-80915ANMP-DDC-T2 RICOH RICOH SOT</p>	 <p>S-80915CLPF-G6KTFG SII Semiconductor Corporation IC VOLT DETECTOR 1.5V SNT-4A</p>
 <p>S-80915CLPF-G6KTFU SII Semiconductor Corporation IC VOLT DETECTOR 1.5V SNT-4A</p>	 <p>S-80915CLMC-G6KT2U SII Semiconductor Corporation IC VOLT DETECTOR 1.5V SOT23-5</p>	 <p>S-80915CNMC-G8K-T2 SEIKO S-80915CNMC-G8K-T2 SEIKO</p>	 <p>S-80915CNMC-G8K SEIKO SEIKO SOT153</p>

Hot Parts

More

- | | | | | |
|----------------------|----------------------|----------------------|-----------------------|-----------------|
| ⊕ 0402ZC330KAT2A | ↔ 08051A330FAT2A | ⇒ 7MBR50JC060-01 | D ACE50225BM+ | ⇒ AD8018ARUZ |
| ⊖ AT-210TR | ⊕ BA15BCOFP | D BA7815CP | ⇒ BC817-25LT1 | ⇒ BJHCS-LTS-25A |
| ⊕ BLF100-S7NA | ⊖ BU4584BF-E2 | ⊕ BZM55C3V3-TR | ↔ DD65N1600K | ⇒ DF75LA80 |
| D DUS-1212 | ⊕ EWS300-5 | ⊖ FAN3226TMX | ⊕ FDMS7692E | ⇒ FQP11P06 |
| ⇒ GRM0336T1E7R0CD01D | ↔ GRM1557U1H3R7CZ01D | ⊕ L5022502EB | ⊖ LM26LVCISD-145/NOPB | ⇒ LMC6462AIMX |
| ↔ LQA06TC300 | ⇒ LT3082IST#TRPBF | D LT6004IDD#TRPBF | ⊕ LTC1148CS#PBF | ⊖ MRF1C0916T1G |
| ⊕ N680CH12 | D NCV1117ST50T3G | ⇒ PD160F40 | ↔ PK40F-80/60/40 | ⇒ PK70FG-40 |
| ⊖ PS9513L3-E3-AX | ⊕ RT9167A-15PB | ↔ S-80820ALUP-EAH-T2 | ⇒ SAB80C535-16-N | ⇒ SG3525ADW-TR |
| ⊕ SN0307009BZHK | ⊖ SN74AUP1G32YZPR | ⊕ SN74F574DWR | D SP8M21TB | ⇒ SSD2009ATF. |
| ↔ TG2403CT | ⊕ TMS320WP010PZ | ⊖ WRF0503S-1W | ⊕ XC4VFX12-10FF668I | ⇒ YS150104P26D |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited