

	<p><b>MPC973</b></p>
	<p><b>Manufacturer Part Number:</b> MPC973</p> <p><b>Manufacturer/Brand:</b> MOT</p> <p><b>Part of Description:</b> MOT TQFP52</p> <p><b>RoHs Status:</b></p> <p><b>Stock Condition:</b> New original, 800 pcs Stock Available.</p> <p><b>Ship From:</b> Hong Kong</p> <p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	

### Specifications

Part Number	MPC973
Manufacturer	MOT
Description	MOT TQFP52
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	800 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

MPC973 is New Original in Stock, Search MPC973 Datasheets, PDF, Inventory at Y-IC.com Online, Order MPC973 with warrantied and confidence. RFQ MPC973 : Info@Y-IC.com

### You May Be Also Be interested

In:

 <p><b>MPC972</b> MOT MPC972 MOT</p>	 <p><b>MPC973FA</b> MOT MPC973FA MOT</p>	 <p><b>MPC96877VK</b> IDT (Integrated Device Technology) IC CLK DRIVER 1:10 SDRAM 52-BGA</p>	 <p><b>MPC970</b> MOT MPC970 MOT</p>
 <p><b>MPC9772</b> MOT MOT TQFP52</p>	 <p><b>MPC974FA</b> MOT MPC974FA MOT</p>	 <p><b>MPC972FAR2</b> MOTOROL MPC972FAR2 MOTOROL</p>	 <p><b>MPC974</b> MOT MPC974 MOT</p>

### Hot Parts

More

- |                      |                     |                       |                        |                          |
|----------------------|---------------------|-----------------------|------------------------|--------------------------|
| ⊕ 04023C103KAJ2A     | ↔ 1206GC331KAT1A    | ⇒ 24LC04BT-I/OT       | D A2C53132552          | ⇒ AAT3526ICX-4.63-200-T1 |
| ⊖ AD7391ARU-REEL     | ⊕ ADA4743-TR1G      | D ADUM3100ARZ         | ⇒ AP130-33RL-7         | ⇒ AP3406KT-ADJTRG1       |
| ⊕ ATD200BA60         | ⊖ BYG21M-E3/TR      | ⊕ C0603C0G1E4R4C030BG | ↔ CGA8N3X7R2E334M230KA | ⇒ CM200-24-S004          |
| D CX25837-35Z        | ⊕ D5NE740M0P1C4-ZAS | ⊖ DSA403-44GG         | ⊕ FOD2712R2V           | ⇒ GRM1886S1H9R9DZ01D     |
| ⇒ GRM219D71A475KE15D | ↔ IRF7342TRPBF      | ⊕ ISL12057IUZ         | ⊖ IXTH152N085T         | ⇒ LP2992AIM5X-5.0        |
| ↔ LT3958IUHE#PBF     | ⇒ MAX4376FAUK       | D MAX713ESE           | ⊕ MAX743EWE+T          | ⊖ MCP9509CT-E/OT         |
| ⊕ MP2112DJ-LF-Z      | D MP612XCG          | ⇒ NDS8434-NL          | ↔ NUP3115UPMUTAG       | ⇒ PBSS5350/DG            |
| ⊖ PIC16F1936-I/MV    | ⊕ S1K75574B00C000   | ↔ SA5532D8            | ⇒ SEMIX453GB12T4S      | ⇒ SF962SFU05             |
| ⊕ SFH5410-36-Z       | ⊖ SGA-4286Z-TR2     | ⊕ SI-8005Q            | D SMA6F7.5A-M3/6A      | ⇒ SN75467P               |
| ↔ TC7W66FK           | ⊕ TLC541IFNR        | ⊖ TS12001ITD1022T     | ⊕ UM1512-01WH          | ⇒ VI-26B-17              |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited