










| | |
|---|---|
|  <p>Not Actual Photo YIC International Co., Limited.</p> | <p>BU426A</p> <p>Manufacturer Part Number: BU426A</p> <p>Manufacturer/Brand: ON</p> <p>Part of Description: BU426A ON</p> <p>RoHs Status:</p> <p>Stock Condition: New original, 9 pcs Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p> |
| | <p>Image may be representation. See specs for product details.</p> |

| Specifications | |
|----------------|---|
| Part Number | BU426A |
| Manufacturer | ON |
| Description | BU426A ON |
| Category | Integrated Circuits (ICs) > Specialized Hot ICs |
| Part Status | 9 pcs Stock |
| Series | - |
| RoHs Status | Lead free / RoHS Compliant |
| Condition | New Original Stock |
| Warranty | 100% Perfect Functions |
| Lead Time | 2-3days after payment. |
| Payment | PayPal / Telegraphic Transfer / Western Union |
| Shipping by | DHL / Fedex / UPS |
| Port | HongKong |
| RFQ Email | Info@Y-IC.com |

BU426A is New Original in Stock, Search BU426A Datasheets, PDF, Inventory at Y-IC.com Online, Order BU426A with warranted and confidence. RFQ BU426A : Info@Y-IC.com

You May Be Also Be interested

| | | | |
|--|---|---|---|
| <p>In:</p>  <p>BU4310F-TR LAPIS Semiconductor IC DETECTOR VOLT 1.0V CMOS 4SOP</p> |  <p>BU4248G-TR LAPIS Semiconductor IC DETECTOR VOLT 4.8V ODRN 5SSOP</p> |  <p>BU4309F-TR LAPIS Semiconductor IC DETECTOR VOLT 0.9V CMOS 4SOP</p> |  <p>BU4309G-TR LAPIS Semiconductor IC DETECTOR VOLT 0.9V CMOS 5SSOP</p> |
|  <p>BU426A-S Bourns, Inc. TRANS NPN 400V 6A</p> |  <p>BU4309FVE-TR LAPIS Semiconductor IC DETECTOR VOLT 0.9V CMOS 5VSOP</p> |  <p>BU4248FVE LAPIS Semiconductor BU4248FVE ROHM</p> |  <p>BU426 Central Semiconductor POWER TRANSISTOR NPN TO218</p> |

Hot Parts

More

- | | | | | |
|----------------------|----------------------|----------------------|---------------------|------------------|
| # 06032U1R6BAT2A | ↔ 12065A150LAT2A | ⇒ 12102U221JAT4A | D AOD5N50M | ⇒ AOZ2237QI-01 |
| ↳ BD3504FVM-TR | # BQ2085DBT | D BYT30P-400 | ⇒ C0603COG1H110J | ⇒ C2012X5R106MCP |
| # CDBB360-G | ↳ CL10B224KP8NNNC | # ESDALC12-1T2 | ↔ F1206FA0750V063T | ⇒ FDS4435A |
| D GRM2197U2A4R7CD01D | # GRM3167U1H102JZ01D | ↳ GRM3196S2A681JZ01D | # ICE1PCS02G | ⇒ IP-222-EX |
| ⇒ IP-J61-EX | ↔ IRF640NSTRRPBF | # IS62C256-70UI | ↳ K6R1008C1C-JC12 | ⇒ LE79272PQCT |
| ↔ LMV7239M7X | ⇒ MA27V020R2TD | D MAX632BCSA | # MC145407 | ↳ MC68HC908GR8CP |
| # MGF539E3336-01 | D MMBTA14-7-F | ⇒ NCP300LSN47T1G | ↔ P6SMB33AHE3/52 | ⇒ PS2701-1-F3 |
| ↳ RCJ330N25TL | # RJK1535DPJ | ↔ S-817A54ANB-CVRT2G | ⇒ SGF80N60UFTU | ⇒ SKKT57-16D |
| # SMAJ6.0CA-13-F | ↳ SN74AUP1G97DCKR | # SN74LVC1G99YZPR | D TC1054-2.85VCT713 | ⇒ TLV2462IDGKR |
| ↔ TZX30A-TAP | # UA78L05CDRG4 | ↳ V300B12E250BL | # VI-24L-IX | ⇒ VIPER100SP |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited