


	<p>S-80915CLNB-G6KT2G</p>
	<p>Manufacturer Part Number: S-80915CLNB-G6KT2G</p>
	<p>Manufacturer/Brand: SII Semiconductor Corporation</p>
	<p>Part of Description: IC VOLT DETECTOR 1.5V SC-82AB</p>
	<p>Datasheets:  S-80915CLNB-G6KT2G.pdf</p>
	<p>RoHS Status:  Lead free / RoHS</p>
	<p>Stock Condition: Compliant New original, Stock Available.</p>
	<p>Ship From: Hong Kong</p>
<p>Image may be representation. See specs for product details.</p>	<p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>









Specifications

Part Number	S-80915CLNB-G6KT2G
Manufacturer	SII Semiconductor Corporation
Description	IC VOLT DETECTOR 1.5V SC-82AB
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	S-809xxC
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Voltage Detector
Package / Case	SC-82A, SOT-343
Supplier Device Package	SC-82AB
Output	Push-Pull, Totem Pole
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	18 ms Minimum
Voltage - Threshold	1.5V
Packaging	Tape & Reel (TR)

S-80915CLNB-G6KT2G is New Original in Stock, Search S-80915CLNB-G6KT2G Datasheets, PDF, Inventory at Y-IC.com Online, Order S-80915CLNB-G6KT2G SII Semiconductor Corporation with warrantied and confidence. RFQ S-80915CLNB-G6KT2G : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>S-80915CLPF-G6KTFG SII Semiconductor Corporation IC VOLT DETECTOR 1.5V SNT-4A</p>	 <p>S-80915CLPF-G6KTFU SII Semiconductor Corporation IC VOLT DETECTOR 1.5V SNT-4A</p>	 <p>S-80915CNMC-G8K SEIKO SEIKO SOT153</p>	 <p>S-80915CNMC-G8K-G SEIKO SEIKO SOT25</p>
 <p>S-80915ANMP-DDC-T2 RICOH RICOH SOT</p>	 <p>S-80915ANMP SEIKO SEIKO SOT-153SOT23-5</p>	 <p>S-80915CLMC-G6K-T2 SEIKO S-80915CLMC-G6K-T2 SEIKO</p>	 <p>S-80915CLMC-G6KT2U SII Semiconductor Corporation IC VOLT DETECTOR 1.5V SOT23-5</p>

Hot Parts

More

- | | | | | |
|--------------------------|------------------------|----------------------|----------------------|--------------------|
| ⊛ 06035C153KAT2A | ↔ 08053C561KAJ2A | ⇒ 12061A472JAT2A | D 1206YC274JAT2A | ⇒ 1808AC103MAT2A |
| ⊣ 18125A104FAT2A | ⊛ 1SMA5942BT3G | D A3123ELTTR | ⇒ ACR50U08JF-01 | ⇒ AD1984AXCPZ |
| ⊛ ADM8617SAYAKSZ | ⊣ APT10090BFLL | ⊛ AT29C512-15TC | ↔ AZ23C6V2-R1 | ⇒ BSZ0904NSI |
| D C3216JB1E335M160AA | ⊛ CGA4J2X7R1H104M125AE | ⊣ DMN2400UFD-7 | ⊛ DZ23C5V6-E3-08 | ⇒ FF400R06ME3 |
| ⇒ FI212C245036 | ↔ GCM1885C2A7R7DA16D | ⊛ GRM1555C1H270JZ01D | ⊣ GRM1887U1H242JA01D | ⇒ ISL21009CFB841Z |
| ↔ ISL9502CRZ | ⇒ L6219DST-TR | D LTC6087CDD#1ADPBF | ⊛ M0334RC160 | ⊣ MAX9719AETE+ |
| ⊛ MCC310-22io1B | D MCL2012S100MT | ⇒ NCP186BMX175TAG | ↔ P4SMA30A-E3/61 | ⇒ PF38F5060MOYOCHB |
| ⊣ RYM002N05 | ⊛ SFC05-5.WC | ↔ STGW40NC60W | ⇒ T92S7D12-12 | ⇒ TI120010 |
| ⊛ TL061BMDT | ⊣ TMK107B7105MA-T | ⊛ TPCA8060-H | D TPSS4610QPWPRQ1 | ⇒ UPC1679G-E2 |
| ↔ UPD789405AGK-A91-9EU-A | ⊛ V300C3V3C150A3 | ⊣ W0438RD220 | ⊛ W180-53G | ⇒ XC56311GC150 |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited