












| | | |
|---|--|---------------------------|
|  | <h2 style="color: #E67E22;">MAX9313ECJ+T</h2> | |
| | Manufacturer Part Number: | MAX9313ECJ+T |
|  | Manufacturer/Brand: | Maxim Integrated |
| | Part of Description: | IC CLK BUFFER 2:10 32TQFP |
| Datasheets: | 1.MAX9313ECJ+T.pdf 2.MAX9313ECJ+T.pdf | |
| RoHs Status: |  Lead free / RoHS | |
| Stock Condition: | Compliant New original, Stock Available. | |
| Ship From: | Hong Kong | |
| Shipment Way: | DHL/Fedex/TNT/UPS/EMS | |

Specifications

| | |
|-----------------------------|---|
| Part Number | MAX9313ECJ+T |
| Manufacturer | Maxim Integrated |
| Description | IC CLK BUFFER 2:10 32TQFP |
| Category | Integrated Circuits (ICs) > Clock/Timing - Clock Buffers, |
| Part Status | Require For Quote & Check Stock |
| Series | - |
| Operating Temperature | -40°C ~ 85°C |
| Mounting Type | Surface Mount |
| Type | Fanout Buffer (Distribution), Multiplexer, Data |
| Frequency - Max | 3GHz |
| Package / Case | 32-LQFP |
| Supplier Device Package | 32-TQFP (7x7) |
| Number of Circuits | 1 |
| Voltage - Supply | 2.25 V ~ 3.8 V |
| Output | LVECL, LVPECL |
| Input | HSTL, LVECL, LVPECL |
| Ratio - Input:Output | 2:10 |
| Differential - Input:Output | Yes/Yes |
| Packaging | Tape & Reel (TR) |

MAX9313ECJ+T is New Original in Stock, Search MAX9313ECJ+T Datasheets, PDF, Inventory at Y-IC.com Online, Order MAX9313ECJ+T Maxim Integrated with warrantied and confidence.
RFQ MAX9313ECJ+T : Info@Y-IC.com

You May Be Also Be interested

| | | | |
|---|---|--|---|
| <p>In:</p>  <p>MAX9314ECJ+T Maxim Integrated IC CLK BUFFER 1:5</p> |  <p>MAX9315EUP+ Maxim Integrated IC CLK BUFFER 2:5 1.5GHZ 20TSSOP</p> |  <p>MAX9314ECJ+ Maxim Integrated IC CLK BUFFER 1:5</p> |  <p>MAX9312ETJ+T Maxim Integrated IC CLK BUFFER 1:5 3GHZ 32TQFN</p> |
|  <p>MAX9312ETJ+ Maxim Integrated IC CLK BUFFER 1:5 3GHZ 32TQFN</p> |  <p>MAX9312ECJ-T MAX MAX9312ECJ-T MAX</p> |  <p>MAX9312ECJ+T Maxim Integrated IC CLK BUFFER 1:5 3GHZ 32LQFP</p> |  <p>MAX9315EUP MAXIM MAX9315EUP MAXIM</p> |

Hot Parts

[More](#)

- | | | | | |
|---------------------|----------------------|-------------------------|--------------------------|-------------------------|
| ⚙️ 12103C394JA2A | ➡️ 70S2-04-D-03-V | ➡️ 7MBP100RA120-04 | D AD7276YUJZ-500RL7 | ➡️ AK4534VN-L |
| ➡️ APR3011-30BI-TRG | ⚙️ AT25160N-10SU-2.7 | D BB659E6805 | ➡️ CDBU0240 | ➡️ CGA9N2X7R2A155K230KA |
| ⚙️ DMP4050SSD-13 | ➡️ EMK107F105ZA-T | ⚙️ GJM1555C1HR30BB01D | ➡️ GRM0337U1H8R5DD01D | ➡️ H1260NLT |
| D IRS2500STRPBF | ⚙️ ISL1557IUEZ-T7 | ➡️ ISL6146DFRZ-TK | ⚙️ KSA1156OS | ➡️ LFB321G74SN1-770 |
| ➡️ LT3430EFE-1#PBF | ➡️ M51348FP | ⚙️ MAX4208AUA+T | ➡️ MB85RC16VPNF-G-JNERE1 | ➡️ MBD54DWT1G |
| ➡️ MC7808CDTG | ➡️ MCD95-12IO8 B | D ML4800ISX | ⚙️ MP62551DJ | ➡️ MT48H32M16LFBF-6:B |
| ⚙️ MUBW30-06T7 | D N280SH16 | ➡️ NJW1166L | ➡️ OPA2677H/2K5 | ➡️ OPA2683IDCNR |
| ➡️ PCA9543AD | ⚙️ PCF50600HN-N1 | ➡️ PS9601L-E3 | ➡️ R5007ANX | ➡️ SFH618A-4T |
| ⚙️ SIA811DJ-T1-GE3 | ➡️ SKY65601-477LF | ⚙️ SSM-107-L-SV-BE-P-TR | D TL074BCDR | ➡️ TPS78223DDCT |
| ➡️ TPS79501DCQR | ⚙️ TS5A63157DCKT | ➡️ UT4957G-S08-R | ⚙️ VE-241-MV | ➡️ VI-250-EV |