



	<h2 style="color: #E67E22;">CS2100CP-EZZR</h2>	
	Manufacturer Part Number: CS2100CP-EZZR	CS2100CP-EZZR
	Manufacturer/Brand: Cirrus Logic	Cirrus Logic
	Part of Description: IC CLOCK MULTIPLIER	IC CLOCK MULTIPLIER
Datasheets:	 1.CS2100CP-EZZR.pdf  2.CS2100CP-EZZR.pdf	
RoHs Status:	 Lead free / RoHS	
Stock Condition:	Compliant New original, Stock Available.	
Ship From:	Hong Kong	
Shipment Way:	DHL/Fedex/TNT/UPS/EMS	









Specifications

Part Number	CS2100CP-EZZR
Manufacturer	Cirrus Logic
Description	IC CLOCK MULTIPLIER
Category	Integrated Circuits (ICs) > Clock/Timing - Clock
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 105°C
Mounting Type	Surface Mount
Type	Fractional N Synthesizer
Frequency - Max	75MHz
Package / Case	10-TFSOP, 10-MSOP (0.118", 3.00mm Width)
Supplier Device Package	10-MSOP
Number of Circuits	1
Voltage - Supply	3.1 V ~ 3.5 V
Output	Clock
Input	Clock
PLL	Yes
Ratio - Input:Output	2:2
Differential - Input:Output	No/No
Divider/Multiplier	Yes/Yes
Packaging	Tape & Reel (TR)

CS2100CP-EZZR is New Original in Stock, Search CS2100CP-EZZR Datasheets, PDF, Inventory at Y-IC.com Online, Order CS2100CP-EZZR Cirrus Logic with warrantied and confidence. RFQ CS2100CP-EZZR : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>CS2100CP-DZZR Cirrus Logic IC CLK MULT CTRL PORT 10-MSOP</p>	 <p>CS2100P-DZZ Cirrus Logic IC CLK MULT OTP 10-MSOP</p>	 <p>CS2100P-DZZR Cirrus Logic IC CLK MULT OTP 10-MSOP</p>	 <p>CS2100CP-CZZR Cirrus Logic IC CLK MULT CTRL PORT 10-MSOP</p>
 <p>CS2100CP-CZZ Cirrus Logic IC CLK MULT FRACTIONAL N 10MSOP</p>	 <p>CS2100CP-DZZ Cirrus Logic IC CLK MULT CTRL PORT 10-MSOP</p>	 <p>CS2100P-CZZR Cirrus Logic IC CLK MULT OTP 10-MSOP</p>	 <p>CS2102-50I03 BBC IGBT Modules</p>

Hot Parts

More

- | | | | | |
|----------------------|-----------------------|-----------------------|----------------------|----------------------|
| ⊕ 08051C332JAT2A | ↔ 12061C393KAT4A | ⇒ 12105A822KAT2A | D 1N5236BTR | ↔ 1SMA5941BT3 |
| ⊖ 2220SA102KAZ2A | ⊕ 7MBR25NH120 | D AD9788BSVZ | ⇒ AOZ8075DI | ↔ ASP-153304-04 |
| ⊕ AT1003S14 | ⊖ BSM100OB120DN2 | ⊕ C2012X8R1H154M125AB | ↔ C3334TX682 | ↔ DMA201010R |
| D FFPF04U40DNTU | ⊕ FGPF50N33BT | ⊖ FQU5N60C | ⊕ GRM0337U1H110JD01D | ↔ GRM1555C2A1R1CA01D |
| ⇒ GRM155R61A105KE01D | ↔ GRM216R71H103MA01D | ⊕ HCPL-4100-000E | ⊖ KNF21400-W3 | ↔ KTD2536EHD-TR |
| ↔ LM20136MH | ⇒ LMS1587CSX-3.3/NOBP | D LT1019CN-2.5 | ⊕ LT3663EDCB#TRPBF | ⊖ MAX8671CETL+ |
| ⊕ MP2249DN-LF-Z | D N540CH12GOO | ⇒ NJM2137V-TE1 | ↔ PPD10-48-1515 | ↔ S-80724SN |
| ⊖ S1F75000F0A0000 | ⊕ SC1410CQSTRT | ↔ SI6465DQ-T1-E3 | ⇒ SK35GD126ET | ↔ SKM145GAL176D |
| ⊕ SQD50N05-11L-GE3 | ⊖ SW08PHN470 | ⊕ TD150-N0196 | D TMK432BJ106KM-T | ↔ TMP89FM42AUG |
| ↔ TPS62046DGQR | ⊕ UAA2075G | ⊖ VI-J64-02 | ⊕ VSSC8L45-M3/57T | ↔ YPPD-J017A |