
	<p>X40031V14I-AT1</p>
	<p>Manufacturer Part Number: X40031V14I-AT1</p> <hr/> <p>Manufacturer/Brand: Intersil</p> <hr/> <p>Part of Description: IC VOLTAGE MONITOR TRPL 14-TSSOP</p> <hr/> <p>Datasheets:  X40031V14I-AT1.pdf</p> <hr/> <p>RoHs Status: Contains lead / RoHS non-compliant</p> <hr/> <p>Stock Condition: New original, Stock Available.</p> <hr/> <p>Ship From: Hong Kong</p> <hr/> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	









Specifications

Part Number	X40031V14I-AT1
Manufacturer	Intersil
Description	IC VOLTAGE MONITOR TRPL 14-TSSOP
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Multi-Voltage Supervisor
Package / Case	14-TSSOP (0.173", 4.40mm Width)
Supplier Device Package	14-TSSOP
Output	Open Drain or Open Collector
Reset	Active Low
Number of Voltages Monitored	3
Reset Timeout	Adjustable/Selectable
Voltage - Threshold	1.8V, 2.9V, 4.6V
Packaging	Tape & Reel (TR)

X40031V14I-AT1 is New Original in Stock, Search X40031V14I-AT1 Datasheets, PDF, Inventory at Y-IC.com Online, Order X40031V14I-AT1 Intersil with warrantied and confidence. RFQ X40031V14I-AT1 : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>X40031V14I-A Intersil IC VOLTAGE MONITOR TRPL 14-TSSOP</p>	 <p>X40031V14-B Intersil IC VOLTAGE MONITOR TRPL 14-TSSOP</p>	 <p>X40031V14I-C Intersil IC VOLTAGE MONITOR TRPL 14-TSSOP</p>	 <p>X40031V14I-B Intersil IC VOLTAGE MONITOR TRPL 14-TSSOP</p>
 <p>X40031V14-BT1 Intersil IC VOLTAGE MONITOR TRPL 14-TSSOP</p>	 <p>X40031V14I-BT1 Intersil IC VOLTAGE MONITOR TRPL 14-TSSOP</p>	 <p>X40031V14-CT1 Intersil IC VOLTAGE MONITOR TRPL 14-TSSOP</p>	 <p>X40034S INTERASIL INTERASIL SOP14</p>

Hot Parts

More

- | | | | | |
|-----------------------|-------------------|-------------------|--------------------|----------------------|
| ⊛ 04025A2R7KAT2A | ↔ 08055C332JA12A | ⇒ 1206YA103GAT2A | D APR3001-26AI-TRL | ⇒ BD1020HFV-T |
| ⊣ BD6889GU-E2 | ⊛ BSM100GB120DN2B | D BU26TD2WNVX-TL | ⇒ BZT52C39 | ⇒ C1608JB1V224M080AB |
| ⊛ C4532C0G2A683K250KA | ⊣ CM3200A3OP-HS | ⊛ CMDSH05-45 | ↔ CPH5802-TB | ⇒ DF2B7M3CL |
| D DTA123EU | ⊛ DVRN6056-7-G | ⊣ FOD2742CR1V | ⊛ FSB50250UD | ⇒ GQM2195C1H680GB01D |
| ⇒ GRM1885C1H820FA01D | ↔ HCF40103BEY | ⊛ KS221K03 | ⊣ MAX649CSA+T | ⇒ MBRB1545CT-E3/81 |
| ↔ MIC5206-3.2YM5 | ⇒ MMD70E160X | D N0416SD020 | ⊛ P6KE56CA | ⊣ P6SMB18CAT3 |
| ⊛ PDH2008A | D PH4030DLA | ⇒ PVZ3A502A01R00 | ↔ SG2003-3.0XN5 | ⇒ SMAJ16CA-E3/61 |
| ⊣ SP213EHEA | ⊛ SPF5189Z | ↔ SPX432AM-L | ⇒ ST1S03PMR | ⇒ STK4042V |
| ⊛ T730N18TOF | ⊣ TD106N11KOF | ⊛ TDA7540NCD | D TPCA8081 | ⇒ TW9900DBTA1-GR |
| ↔ UPD78F0513AGA | ⊛ V300A3V3H264AL2 | ⊣ VS-8ETH03STRPBF | ⊛ WKO222MCPDJ0KR | ⇒ ZUW1R54815 |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited