









	<p><b>X4005M8Z</b></p>
	<p><b>Manufacturer Part Number:</b> X4005M8Z</p> <hr/> <p><b>Manufacturer/Brand:</b> Intersil</p> <hr/> <p><b>Part of Description:</b> IC SUPERVISOR CPU I2C 8-MSOP</p> <hr/> <p><b>Datasheets:</b>  <a href="#">X4005M8Z.pdf</a></p> <hr/> <p><b>RoHS Status:</b>  Lead free / RoHS</p> <hr/> <p><b>Stock Condition:</b> Compliant New original, Stock Available.</p> <hr/> <p><b>Ship From:</b> Hong Kong</p> <hr/> <p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	

### Specifications

Part Number	X4005M8Z
Manufacturer	Intersil
Description	IC SUPERVISOR CPU I2C 8-MSOP
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	0°C ~ 70°C (TA)
Mounting Type	Surface Mount
Type	Simple Reset/Power-On Reset
Package / Case	8-TSSOP, 8-MSOP (0.118", 3.00mm Width)
Supplier Device Package	8-MSOP
Output	Open Drain or Open Collector
Reset	Active High
Number of Voltages Monitored	1
Reset Timeout	100 ms Minimum
Voltage - Threshold	4.38V
Packaging	Tube

X4005M8Z is New Original in Stock, Search X4005M8Z Datasheets, PDF, Inventory at Y-IC.com Online, Order X4005M8Z Intersil with warrantied and confidence. RFQ X4005M8Z : Info@Y-IC.com

### You May Be Also Be interested

<p><b>In:</b></p>  <p><b>X4005S8</b> Intersil IC SUPERVISOR CPU I2C 8-SOIC</p>	 <p><b>X4005M8IZ</b> Intersil IC SUPERVISOR CPU I2C 8-MSOP</p>	 <p><b>X4005M8IZ-4.5A</b> Intersil IC SUPERVISOR CPU I2C 8-MSOP</p>	 <p><b>X4005M8IZ-2.7A</b> Intersil IC SUPERVISOR CPU I2C 8-MSOP</p>
 <p><b>X4005M8IZ-2.7</b> Intersil IC SUPERVISOR CPU I2C 8-MSOP</p>	 <p><b>X4005S8-2.7</b> Intersil IC SUPERVISOR CPU I2C 8-SOIC</p>	 <p><b>X4005M8Z-4.5A</b> Intersil IC SUPERVISOR CPU I2C 8-MSOP</p>	 <p><b>X4005M8Z-2.7</b> Intersil IC SUPERVISOR CPU I2C 8-MSOP</p>

### Hot Parts

More

 08055A680GAT2P	 7MBP150VDA060-50	 AAT2823IBK-1-T1	 AP1702EWL	 AP6203B-33PA1
 AT45DB041D-SSU-SL954	 BCM5482SA2IFBG	 BTA16-800BRG	 CL10B105KA8VPNC	 CM600YE2N-12F
 DS1023S-25	 DTD513ZM	 ELM7504BEL	 EPM3128ATC100-10	 FDG6332C_F085
 D FQPF5P10	 HCF4071M013TR	 HTB400-P/SP5	 IPB90R340C3	 IRLU3802PBF
 => ISP1181BBSUM	 LM2936BMX-3.3	 LM3670MFX-1.8	 LM95231BIMM	 LME49710MA
 => LTC1329CS8-50#TRPBF	 => LTC6907CS6/IS6/HS6	 D M30260F6T-104GPU1Q	 MAX14641ETA+	 MC14402L2
 MCA501-12io1	 D MM74HCT273WMX	 => NJM78L09A	 => NL453232T-4R7M	 PI5A124TX
 HT- PIC24FJ32GB002T-I/SO	 S-80843CLUA-B64T2G	 => SEMIX603GB066HDS	 => SKKH27-08	 => SLF6025T-6R8M1R3-PF
 MCA501-12io1	 HT- SMD0805-010	 MCA501-12io1	 D STI7141BNWB	 => SVC203SPA-AL
 => TC74LCX07FK	 MCA501-12io1	 HT- UPC8119T	 MCA501-12io1	 => XC61CC2802MR

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited