









 <p>A Renesas Company</p>	<p><b>ISL88706IP829Z</b></p>
	<p><b>Manufacturer Part Number:</b> <a href="#">ISL88706IP829Z</a></p> <p><b>Manufacturer/Brand:</b> <a href="#">Intersil</a></p> <p><b>Part of Description:</b> IC SUPERVISOR MPU 2.92V 8DIP</p> <p><b>Datasheets:</b> <a href="#">ISL88706IP829Z.pdf</a></p> <p><b>RoHS Status:</b>  Lead free / RoHS</p> <p><b>Stock Condition:</b> Compliant New original, 40 pcs Stock Available.</p> <p><b>Ship From:</b> Hong Kong</p> <p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	

### Specifications

Part Number	ISL88706IP829Z
Manufacturer	Intersil
Description	IC SUPERVISOR MPU 2.92V 8DIP
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	40 pcs Stock
Series	-
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Through Hole
Type	Simple Reset/Power-On Reset
Package / Case	8-DIP (0.300", 7.62mm)
Supplier Device Package	8-PDIP
Output	Open Drain or Open Collector
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	140 ms Minimum
Voltage - Threshold	2.92V
Packaging	Tube

ISL88706IP829Z is New Original in Stock, Search ISL88706IP829Z Datasheets, PDF, Inventory at Y-IC.com Online, Order ISL88706IP829Z Intersil with warrantied and confidence. RFQ ISL88706IP829Z : Info@Y-IC.com

### You May Be Also Be interested

<p><b>In:</b></p>  <p><b>ISL88706IB844Z</b> Intersil IC SUPERVISOR 4.38V 8-SOIC</p>	 <p><b>ISL88706IB831Z-TK</b> Intersil IC SUPERVISOR MPU 3.09V 8-SOIC</p>	 <p><b>ISL88707IB846Z</b> Intersil IC SUPERVISOR 4.64V 8-SOIC</p>	 <p><b>ISL88707IB846Z-TK</b> Intersil IC SUPERVISOR MPU 4.64V 8-SOIC</p>
 <p><b>ISL88706IP826Z</b> Intersil IC SUPERVISOR MPU 2.63V 8DIP</p>	 <p><b>ISL88707IP846Z</b> Intersil IC SUPERVISOR MPU 4.64V 8DIP</p>	 <p><b>ISL88706IP844Z</b> Intersil IC SUPERVISOR MPU 4.38V 8DIP</p>	 <p><b>ISL88706IB844Z-TK</b> Intersil IC SUPERVISOR MPU 4.38V 8-SOIC</p>

### Hot Parts

More

08055U131FAT9A	18087C102KAT1A	AAT3522IGY	D C0603X5R1C222M	C1608X7R1H153M080AA
CGA3E2X7R1H102M080AD	CL32A106KOCLNWE	D CY283420C	DMN3404LQ-7	DS1233AZ-5
ELM9330AA-S	FS35R12W1T4-B11	GRM1886S1H5R5D201D	HIP6008CB-T	ICS83026AMILFT
D IP-230-CV-TRI	ISL6744AAUZ	LBMF1608T4R7M	LCMX0640C-3TN144C	LD031C182KAB2A
LM258ADT	LM27964SQX-A	LPT675-N1-4-0-30	LQH2MCN220K02L	LT1117CST-1.2TR
LT3460ES5#TRPBF	MCP4011-502E/SN	D MCZ1210AH360TA0G	MIC5370-PKYMT	MMBZ5245BTS-7
N1467NS200	D N330CH24H00	NB638DL-LF-Z	NCP1203D60R2G	NCP4586DSN30T1G
NST3904DXV6T5	P562F1001	PKF2610ASI	PKM4218PI	S-81246SGY
SI4336DY-T1-E3	SI8441AB-D-ISR	STM32F103T8U7	D TM130EZ-24	TS823CX5ARF
UCC27524DGNR	V24B3V3C150BS	V24C15T100AL3	VE-253-IW	WX166MC360

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited