







	<h2 style="color: red;">3314G-2-503E</h2>
	<p>Manufacturer Part Number: 3314G-2-503E</p> <p>Manufacturer/Brand: BOURNS</p> <p>Part of Description: BOURNS NA</p> <p>RoHs Status:</p> <p>Stock Condition: New original, 3500 pcs Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	

Specifications

Part Number	3314G-2-503E
Manufacturer	BOURNS
Description	BOURNS NA
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	3500 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

3314G-2-503E is New Original in Stock, Search 3314G-2-503E Datasheets, PDF, Inventory at Y-IC.com Online, Order 3314G-2-503E with warrantied and confidence. RFQ 3314G-2-503E : Info@Y-IC.com

You May Be Also Be interested

<p>In:</p>  <p>3314G001503E BOURNS 3314G001503E BOURNS</p>	 <p>3314G-2-504E Bourns, Inc. TRIMMER 500K OHM 0.25W GW TOP</p>	 <p>3314G-2-503E Bourns, Inc. TRIMMER 50K OHM 0.25W GW TOP ADJ</p>	 <p>3314G001502E BOURNS 3314G001502E BOURNS</p>
 <p>3314G001200E BOURNS 3314G001200E BOURNS</p>	 <p>3314G-2-501E Bourns, Inc. TRIMMER 500 OHM 0.25W GW TOP ADJ</p>	 <p>3314G-FV3-100 BOURNS 3314G-FV3-100 BOURNS</p>	 <p>3314G-2-502E BOURNS BOURNS SOP3</p>

Hot Parts

[More](#)

- | | | | | |
|-----------------------|--------------------|-----------------------|-----------------------|-----------------------|
| ⚙️ 0201YA390JAT2A | ➡️ 08055C561K4T2A | ➡️ 1206PC103KAT1A | D 1775060-1 | ➡️ 6MBP50RU2A120-01 |
| ⚡️ 7MBP150NA-060 | ⚙️ A3955SLBTR-T | D AD8403A10 | ➡️ ASP1255DGQW | ➡️ C1005JB0J224K050BB |
| ⚙️ C1608JB1E225M080AB | ⚡️ CBTS3257PW | ⚙️ CPDQR5V0UP-HF | ➡️ CY74FCT16827ETPAC | ➡️ DWF100A40 |
| D FSA641UMX | ⚙️ FZ1800R16KF4-S1 | ⚡️ GRJ31MR71E105KE01L | ⚙️ GRM155R71H332KA01J | ➡️ GRM3196T2A120JD01D |
| ➡️ LB1845L-S-E | ➡️ LM7806CT | ⚙️ LPC2292FET144/01 | ⚡️ LT1999MPS8-50#PBF | ➡️ M24C32-MW6T/KM |
| ➡️ MAX3768CUA+T | ➡️ MCR03EZHZ152 | D MDS500A1600V | ⚙️ MMDF2P02HDR2 | ⚡️ MP2122DQ-LF-Z |
| ⚙️ MP3389EY-C355-LF-Z | D NDS9952A-NL | ➡️ NT68565FG | ➡️ NT68F63LG | ➡️ PKJ4113AT |
| ⚡️ QM2A1UA004/EL | ⚙️ RS8M-00R0-XIN | ➡️ S3GHE3/9AT | ➡️ SA5.0A-E3/73 | ➡️ SB25W05T |
| ⚙️ SFAF1008G | ⚡️ SG1500GXH23 | ⚙️ STLVD532BD | D T408F13TSM | ➡️ TOP266KG-TL |
| ➡️ UMK105CG181JV-F | ⚙️ V300C28C150AL2 | ⚡️ VI-26L-E | ⚙️ VKA50MS24 | ➡️ ZM4751A-GS18 |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.
Copyright © 2019 YIC International Co., Limited