


	<b>AN8495SB</b>
	<b>Manufacturer Part Number:</b> AN8495SB
 <p>Not Actual Photo YIC International Co., Limited.</p>	<b>Manufacturer/Brand:</b> Panasonic
	<b>Part of Description:</b> IC MOTOR DRIVER PAR 42HSOP
<b>Datasheets:</b>	 <a href="#">AN8495SB.pdf</a>
<b>RoHS Status:</b>	 Lead free / RoHS
<b>Stock Condition:</b>	Compliant New original, 107 pcs Stock Available.
<b>Ship From:</b>	Hong Kong
<b>Shipment Way:</b>	DHL/Fedex/TNT/UPS/EMS
<p>Image may be representation. See specs for product details.</p>	

### Specifications

Part Number	AN8495SB
Manufacturer	Panasonic
Description	IC MOTOR DRIVER PAR 42HSOP
Category	Integrated Circuits (ICs) > PMIC - Motor Drivers,
Part Status	107 pcs Stock
Series	-
Technology	Power MOSFET
Operating Temperature	-
Mounting Type	Surface Mount
Interface	Parallel
Applications	General Purpose
Package / Case	28-BSOP (0.327", 8.30mm) + 2 Heat Tabs
Supplier Device Package	42-HSOP
Voltage - Supply	4.75 V ~ 5.25 V
Function	Driver - Fully Integrated, Control and Power Stage
Current - Output	1.5A
Output Configuration	Half Bridge (4)
Voltage - Load	18 V ~ 28 V
Motor Type - Stepper	Bipolar
Motor Type - AC, DC	-
Step Resolution	-
Packaging	Bulk

AN8495SB is New Original in Stock, Search AN8495SB Datasheets, PDF, Inventory at Y-IC.com Online, Order AN8495SB Panasonic with warrantied and confidence. RFQ AN8495SB : Info@Y-IC.com

### You May Be Also Be interested

In:

 <p><b>AN8498SH-E1V</b> PANASON AN8498SH-E1V PANISON</p>	 <p><b>AN8481SB-E1</b> PANA PANA SOP-30</p>	 <p><b>AN8485SB</b> PANASON PANASON HSOP</p>	 <p><b>AN8496SA-E1V</b> PANASON AN8496SA-E1V PANASON</p>
 <p><b>AN8498SH-E1V</b> PANASON PANASON TSSOP</p>	 <p><b>AN8495SB-E1V</b> Panasonic IC MOTOR DRIVER PAR 42HSOP</p>	 <p><b>AN8481SB</b> PANA PANA SOP</p>	 <p><b>AN8480NSB-E1</b> PANASONIC PANASONIC SOP</p>

### Hot Parts

More

- |                     |                   |                    |                         |                           |
|---------------------|-------------------|--------------------|-------------------------|---------------------------|
| ⚙️ 12063A472JAT2A   | ⚙️ 1808SC331KATME | ➡️ 6FL100S05       | D A6841SLWTR-20-T       | ➡️ AAT3522IGY-2.32-200-T1 |
| ⚙️ AT1041K6         | ⚙️ BC338-40       | D BQ29400PW        | ➡️ CAT4139TD-GT3        | ➡️ CL05B822KB5NNNC        |
| ⚙️ CY28409ZC        | ⚙️ DAC8802IPW     | ⚙️ DMN2500UFB4-7   | ⚙️ EL6203CW-T7          | ➡️ FAN2501S25X            |
| D FM7G15US60        | ⚙️ FPD92220       | ⚙️ FQPF9N08        | ⚙️ GRM188R61C474KA93D   | ➡️ IR3720MTRPBF.          |
| ➡️ KPTB-1615SURKSGC | ⚙️ LM431CCMX      | ⚙️ LT6237CMS8      | ⚙️ LTC2856IDD-2#TRPBF   | ➡️ MAX1857EUA47+          |
| ⚙️ MAX698CWE        | ➡️ MC145010DW     | D MC146823P        | ⚙️ MC74LCX138DT         | ⚙️ MCP809T-475I/TT        |
| ⚙️ MMO62-12I06      | D P6SMB36A        | ➡️ PBSS5130T       | ⚙️ PRTR5VOU2F           | ➡️ PRX43-0000010-9        |
| ⚙️ REG101NA-2.5     | ⚙️ RURP15100      | ⚙️ S30814-Q288-B-5 | ➡️ SC1457ISK-1.8TRT     | ➡️ SIT8003AJ-11-30E       |
| ⚙️ SKKD260/02       | ⚙️ SKM75GAL128D   | ⚙️ SN74221N        | D SPX431LAM1-L          | ➡️ STM8AF6288TDY          |
| ⚙️ TC74LCX125F      | ⚙️ TOP260YN       | ⚙️ TPS3125L30DBVR  | ⚙️ UPD78F1166AGF-GAS-AX | ➡️ X9312ZS                |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited