









| | |
|--|---|
|  <p>A Renesas Company</p> | <p>X93156WM8I-2.7</p> |
| | <p>Manufacturer Part Number: X93156WM8I-2.7</p> <p>Manufacturer/Brand: Intersil</p> <p>Part of Description: IC XDCP 32-TAP 12.5K 3WIRE 8MSOP</p> <p>Datasheets: X93156WM8I-2.7.pdf</p> <p>RoHs Status: Contains lead / RoHS non-compliant</p> <p>Stock Condition: New original, Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p> |
| <p>Image may be representation. See specs for product details.</p> | |

Specifications

| | |
|---------------------------------|---|
| Part Number | X93156WM8I-2.7 |
| Manufacturer | Intersil |
| Description | IC XDCP 32-TAP 12.5K 3WIRE 8MSOP |
| Category | Integrated Circuits (ICs) > Data Acquisition - Digital |
| Part Status | Require For Quote & Check Stock |
| Series | XDCP™ |
| Operating Temperature | -40°C ~ 85°C |
| Features | - |
| Interface | Up/Down (U/D, INC, CS) |
| Configuration | Potentiometer |
| Tolerance | ±25% |
| Package / Case | 8-TSSOP, 8-MSOP (0.118", 3.00mm Width) |
| Supplier Device Package | 8-MSOP |
| Number of Circuits | 1 |
| Voltage - Supply | 2.7 V ~ 5.5 V |
| Memory Type | Non-Volatile |
| Resistance (Ohms) | 12.5k |
| Taper | Linear |
| Number of Taps | 32 |
| Temperature Coefficient (Typ) | ±35 ppm/°C |
| Resistance - Wiper (Ohms) (Typ) | 1100 (Max) |
| Packaging | Tube |

X93156WM8I-2.7 is New Original in Stock, Search X93156WM8I-2.7 Datasheets, PDF, Inventory at Y-IC.com Online, Order X93156WM8I-2.7 Intersil with warrantied and confidence. RFQ X93156WM8I-2.7 : Info@Y-IC.com

You May Be Also Be interested

| | | | |
|---|---|---|--|
| <p>In:</p>  <p>X93156UM8I-2.7T1 Intersil IC XDCP 32-TAP 50K 3-WIRE 8-MSOP</p> |  <p>X93156WM8IZ-2.7 Intersil IC XDCP 32-TAP 12.5K 3WIRE 8MSOP</p> |  <p>X93156WM8I-2.7T1 Intersil IC XDCP 32-TAP 12.5K 3WIRE 8MSOP</p> |  <p>X93156UM8I-2.7 Intersil IC XDCP 32-TAP 50K 3-WIRE 8-MSOP</p> |
|  <p>X93156UM8IZ-2.7T1 Intersil IC POT DGTL 50K OHM 8-MSOP</p> |  <p>X93156UM8IZ-2.7 Intersil IC XDCP 32-TAP 50K 3-WIRE 8-MSOP</p> |  <p>X93156WM8IZ-2.7T1 Intersil IC POT DGTL 12.5K OHM 8-MSOP</p> |  <p>X93156WM8IZ Intersil IC XDCP 32-TAP 12.5K 3WIRE 8MSOP</p> |

Hot Parts

[More](#)

| | | | | |
|-----------------|--------------------|-----------------|--------------------|-------------------|
| 06036A151GAT2A | A50L-0001-0420 | ADP3820ART-4.2 | AT25F512A | AZ1086H-5.0 |
| B39901B7681L310 | BUK7214-75B | BYM300B170DN2 | C1005CH1H101J050BA | CC1206JRX7R9BB682 |
| CSG2001-18A04 | CSHD5-40TR13 | DVIULC6-2M6 | ERB1885C2ER50CDX1D | EWS600-48 |
| FBA75CA45 | GCM1885C2A3R3C213D | HFA1C-300C | ICS9248AG-195t | IMP811TEUS |
| IR3871MTR1PBF | ISL8036IRZ-T | LM2598S-ADJ | LT1022CN8 | LT1963AEFE#PBF |
| M34513M4-199FP | M MDF2C02HDR2G | MMSZ4684 | MOC3063SM | P0603BVG |
| PDTC143EU | PMB6850EV2.1DC12 | PT7M6134NLTA3EX | QM75E2Y-HD | RFBPB1608060A9T |
| S15VTA60 | S1G-008/11 | SMBJ6.5A-13-F | SMS15C.TC | STL55NH3LL |
| STTH15L06FP | SW06DXC30C | TDC1025C | TMK063CG030DPGF | TT8J21TR |
| UCD9125RHBT | W25Q256FVFIG | WJCE6353 | XC61FN2412MR | ZNBG6001 |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited