

 <p>A Renesas Company</p>	<h2 style="color: #E67E22;">X5323V14T1</h2>	
	<p><b>Manufacturer Part Number:</b> <a href="#">X5323V14T1</a></p> <hr/> <p><b>Manufacturer/Brand:</b> <a href="#">Intersil</a></p> <hr/> <p><b>Part of Description:</b> IC SUPERVISOR CPU 32K EE 14TSSOP</p> <hr/> <p><b>Datasheets:</b> <a href="#">PDF X5323V14T1.pdf</a></p> <hr/> <p><b>RoHs Status:</b> Contains lead / RoHS non-compliant</p> <hr/> <p><b>Stock Condition:</b> New original, Stock Available.</p> <hr/> <p><b>Ship From:</b> Hong Kong</p> <hr/> <p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p>	
<p>Image may be representation. See specs for product details.</p>		

### Specifications

Part Number	X5323V14T1
Manufacturer	Intersil
Description	IC SUPERVISOR CPU 32K EE 14TSSOP
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	0°C ~ 70°C (TA)
Mounting Type	Surface Mount
Type	Simple Reset/Power-On Reset
Package / Case	14-TSSOP (0.173", 4.40mm Width)
Supplier Device Package	14-TSSOP
Output	Open Drain or Open Collector
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	100 ms Minimum
Voltage - Threshold	4.38V
Packaging	Tape & Reel (TR)

X5323V14T1 is New Original in Stock, Search X5323V14T1 Datasheets, PDF, Inventory at Y-IC.com Online, Order X5323V14T1 Intersil with warrantied and confidence. RFQ X5323V14T1 : Info@Y-IC.com

### You May Be Also Be interested

In:

 <p><b>X5325P-2.7</b> Intersil IC SUPERVISOR CPU 32K EE 8-DIP</p>	 <p><b>X5323V14I-2.7</b> Intersil IC SUPERVISOR CPU 32K EE 14TSSOP</p>	 <p><b>X5325</b> INTRESIL INTRESIL SOP8</p>	 <p><b>X5323V14I-2.7T1</b> Intersil IC SUPERVISOR CPU 32K EE 14TSSOP</p>
 <p><b>X5325P-2.7A</b> Intersil IC SUPERVISOR CPU 32K EE 8-DIP</p>	 <p><b>X5323V14I-4.5A</b> Intersil IC SUPERVISOR CPU 32K EE 14TSSOP</p>	 <p><b>X5323V14IT1</b> Intersil IC SUPERVISOR CPU 32K EE 14TSSOP</p>	 <p><b>X5325P</b> Intersil IC CPU SUPRV 32K EE RST HI 8DIP</p>

### Hot Parts

More

- |   |  |  |   |   |
|---|--|--|---|---|
| <ul style="list-style-type: none"> <li>⚙️ 1MBI400JN-140-01</li> <li>⚡️ CY23FS08OXI-03T</li> <li>⚙️ GAL16V8H-10JC/4</li> <li>D HSG1002VE-TL-E</li> <li>➡️ LM2937ES-5.0</li> <li>➡️ MA2711100L</li> <li>⚙️ MCC161-20I01B</li> <li>⚡️ PC74HCT86T</li> <li>⚙️ TLV320AIC23BPWR</li> <li>➡️ TT50F06KOC</li> </ul> | <ul style="list-style-type: none"> <li>➡️ ADP1711AUJZ-3.3-R7</li> <li>⚙️ CY2509ZXC-1T</li> <li>⚡️ GRM1886R1H3R9C201D</li> <li>⚙️ IP-220-CW</li> <li>➡️ LPC2365FBD100/04</li> <li>➡️ MBRF20100CL</li> <li>D MCP111T-270E/LB</li> <li>⚙️ PESD3V3L2BT</li> <li>⚡️ TMS320TCI6484CMH</li> <li>⚙️ UMK316B7224KLHT</li> </ul> | <ul style="list-style-type: none"> <li>➡️ ADS54T04IZAYR</li> <li>D CY283780CT</li> <li>⚙️ GRM1887U1H102JA01J</li> <li>⚡️ IXFX44N50F</li> <li>⚙️ LTC4252-2IMS#TRPBF</li> <li>D MBT3906DW1T1G</li> <li>➡️ MIC4428BN</li> <li>➡️ R7000405UA</li> <li>⚙️ TMX320C5545AZQWR</li> <li>⚡️ UPS130LE3/TR7</li> </ul> | <ul style="list-style-type: none"> <li>D AP7115-29SEG-7</li> <li>➡️ DG211CSE</li> <li>➡️ GRM2165C2A121JA01D</li> <li>⚙️ K9F5608UOD-PCBO</li> <li>⚡️ LX1665CDW</li> <li>⚙️ MC33269DR2G</li> <li>➡️ MIG30J806H</li> <li>➡️ SW50CX560</li> <li>D TPS2829QDBVRQ1</li> <li>⚙️ V20120C-M3/4W</li> </ul> | <ul style="list-style-type: none"> <li>➡️ BTS124-A</li> <li>➡️ DMN2170U</li> <li>➡️ HSC278TRF-E</li> <li>➡️ LM2937ES-12/NOPB</li> <li>➡️ M28W640FSB7OZA6E</li> <li>⚡️ MC33275ST-3.3T3</li> <li>➡️ MMG100HB060B6EN</li> <li>➡️ THC63LVDF64B</li> <li>➡️ TS391AG-AF5-R</li> <li>➡️ ZXT13P40DE6TA</li> </ul> |
|---|--|--|---|---|

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited