

 <p>A Renesas Company</p>	<h2>ICL3207CB</h2>	
	<p><b>Manufacturer Part Number:</b> ICL3207CB</p>	
	<p><b>Manufacturer/Brand:</b> Intersil</p>	
	<p><b>Part of Description:</b> IC 5DRVR/3RCVR RS232 3V 24-SOIC</p>	
	<p><b>Datasheets:</b>  <a href="#">ICL3207CB.pdf</a></p>	
	<p><b>RoHs Status:</b> Contains lead / RoHS non-compliant</p>	
	<p><b>Stock Condition:</b> New original, 700 pcs Stock Available.</p>	
	<p><b>Ship From:</b> Hong Kong</p>	
<p>Image may be representation. See specs for product details.</p>	<p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p>	


### Specifications

Part Number	ICL3207CB
Manufacturer	Intersil
Description	IC 5DRVR/3RCVR RS232 3V 24-SOIC
Category	Integrated Circuits (ICs) > Interface - Drivers, Receivers,
Part Status	700 pcs Stock
Series	-
Operating Temperature	0°C ~ 70°C
Mounting Type	Surface Mount
Type	Transceiver
Package / Case	24-SOIC (0.295", 7.50mm Width)
Supplier Device Package	24-SOIC
Voltage - Supply	3 V ~ 5.5 V
Protocol	RS232
Number of Drivers/Receivers	5/3
Duplex	Full
Receiver Hysteresis	300mV
Data Rate	250kbps
Packaging	Tube


ICL3207CB is New Original in Stock, Search ICL3207CB Datasheets, PDF, Inventory at Y-IC.com Online, Order ICL3207CB Intersil with warrantied and confidence. RFQ ICL3207CB : Info@Y-IC.com

### You May Be Also Be interested


In:




**ICL3078EIBZ**  
INTERSIL  
INTERSIL SOP-8




**ICL3207CAZ-T**  
Intersil  
IC 5DRVR/3RCVR RS232 3V 24-SSOP




**ICL3207ECA**  
Intersil  
IC 5DRVR/3RCVR RS232 3V 24-SSOP




**ICL3207CA**  
Intersil  
IC 5DRVR/3RCVR RS232 3V 24-SSOP




**ICL3207ECA-T**  
Intersil  
IC 5DRVR/3RCVR RS232 3V 24-SSOP



**ICL3207CAZ**  
Intersil  
IC 5DRVR/3RCVR RS232 3V 24-SSOP



**ICL3207CA-T**  
Intersil  
IC 5DRVR/3RCVR RS232 3V 24-SSOP



**ICL3207CBZ-T**  
Intersil  
IC 5DRVR/3RCVR RS232 3V 24-SOIC

### Hot Parts

More

- |                      |                       |                  |                 |                      |
|----------------------|-----------------------|------------------|-----------------|----------------------|
| 0402YC471KAJ2A       | 12061C562KAZ2A        | 12065C334KAT4A   | D 16CTQ100      | 1812CC823KAT3A\SB    |
| 22255A123JAT2A       | AA10B-048L-050DE      | D APT6017JLL     | ⇒ AQY212G2S     | ⇒ BZD27C9V1P-E3-08   |
| BZT52-B68S           | ┆ C1005X7S1A684K050BC | 0 EC49809LB-F    | ⇒ ESM2010DV     | ⇒ GJM0335C1E3R3CB01D |
| D GQM1875C2E360JB12D | 0 GRM1886T1H8R1DD01D  | ┆ ICS85211AMILFT | 0 IRLU7807Z     | ⇒ ISL31495EIBZ       |
| ⇒ LM4140BCM1.0       | ⇒ LM7815CT            | 0 LT1070HVCQ     | ┆ LT1129IST-3.3 | ⇒ LT1990CS8#PBF      |
| ⇒ MAX700CSA+T        | ⇒ MAX824MEUK+T        | D MAX9705CETB+T  | 0 MBRX1100      | ┆ OPA684ID           |
| 0 PP3-12-15          | D QRW025A0F41-H       | ⇒ R220CH06CK0    | ⇒ RB168L-30DD   | ⇒ RP130N121D-TR-FE   |
| ┆ RTQ035N03TR        | 0 SC2614IMLTR         | ⇒ SCH2821-TL-E   | ⇒ SKKT162/18E   | ⇒ SM16DZ41           |
| 0 SM8S26A-E3/2D      | ┆ SN74LVC1G97DBVR     | 0 SP3239ECA      | D STK76001      | ⇒ STM6510WCACDG6F    |
| ⇒ STTH810G-TR        | 0 TC51N2702ECBTR      | ┆ TL061IDR       | 0 TLA-6T207A-T  | ⇒ X9250UV24Z-2.7     |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited