

	ZL30150GGG2
	Manufacturer Part Number: ZL30150GGG2
 <p>Not Actual Photo YIC International Co., Limited.</p>	Manufacturer/Brand: Microsemi
	Part of Description: IC CLK TRANSLATOR 2CH 100FBGA
<p>Image may be representation. See specs for product details.</p>	Datasheets:  ZL30150GGG2.pdf
	RoHs Status: Lead free / RoHS non-compliant
	Stock Condition: New original, 112 pcs Stock Available.
	Ship From: Hong Kong
	Shipment Way: DHL/Fedex/TNT/UPS/EMS









Specifications

Part Number	ZL30150GGG2
Manufacturer	Microsemi
Description	IC CLK TRANSLATOR 2CH 100FBGA
Category	Integrated Circuits (ICs) > Clock/Timing - Application
Part Status	112 pcs Stock
Series	-
Operating Temperature	-40°C ~ 85°C
Mounting Type	Surface Mount
Frequency - Max	-
Package / Case	100-LBGA
Supplier Device Package	100-LBGA (11x11)
Number of Circuits	1
Voltage - Supply	-
Output	HCSSL, LVCMOS, LVDS, LVPECL
Main Purpose	Ethernet, SONET/SDH
Input	Clock
PLL	Yes
Ratio - Input:Output	4:20
Differential - Input:Output	Yes/Yes
Packaging	Tray

ZL30150GGG2 is New Original in Stock, Search ZL30150GGG2 Datasheets, PDF, Inventory at Y-IC.com Online, Order ZL30150GGG2 Microsemi with warrantied and confidence. RFQ
ZL30150GGG2 : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>ZL30146GGG2 Microsemi IC SYNCHRONIZER ETH 64CABGA</p>	 <p>ZL30151LDG1 Microsemi IC LINE CARD ETH PLL 3I/O 32QFN</p>	 <p>ZL30152 MICROSE ZL30152 MICROSE</p>	 <p>ZL30152GGG Microsemi IC CLK TRANSLATOR 2CH 100FBGA</p>
 <p>ZL30145GGG2 Microsemi IC DPLL SONET/SDH/ETH 64CABGA</p>	 <p>ZL30150GGG20038 Microsemi IC CLK TRANSLATOR 2CH 100LBGA</p>	 <p>ZL30151LDF1 Microsemi IC LINE CARD ETH PLL 3I/O 32QFN</p>	 <p>ZL30146GGG Microsemi IC SYNCHRONIZER ETH 64CABGA</p>

Hot Parts

[More](#)

- | | | | | |
|----------------------|----------------------|----------------------|-------------------|----------------------|
| ⊕ 04023U4R7CAT2A | ↔ 06031C822KAT4A | ⇒ 06035A150DAT2A | D 06035A220K4T2A | ↗ 08055C273KAJ2A |
| ⊖ 12CTQ035 | ⊕ AAT2512IWP-AA-T1 | D AK8130D-E2 | ⇒ AT49BV322A-CI | ↗ BH9598FP |
| ⊕ BL9110-150BPBA | ⊖ C1005JB1E473K050BA | ⊕ C1608JB2A153K080AA | ↔ CL-191YG-CD-T | ↗ CQ0603BRNPOYBN2R7 |
| D DS1706EUA+TR | ⊕ DTC125TK | ⊖ EZ1584IT-3.3 | ⊕ FODM121CV | ↗ GQM1875C2ER40CB12D |
| ⇒ GRM188R71A684KA61J | ↔ IRFR9024NCTRPBF | ⊕ LB1638ML-TE-L | ⊖ LC1608T12NJ | ↗ LM340K-5.0 |
| ↔ LNJ310M6UOER | ⇒ MMBF4119 | D NJT4030PT3G | ⊕ P6SMB350A | ⊖ PC9S08QG8CFFE |
| ⊕ PCM1754BDQR | D PD100N8C | ⇒ PM2024D15-2178 | ↔ SC14430A5M80VDN | ↗ SD1700C45K |
| ⊖ SDR1006-332KL | ⊕ SF14-2132M5UBA2 | ↔ SI4761-A10-AMR | ⇒ SMCJ36CA-E3/57T | ↗ SS12P4SHM3/86A |
| ⊕ SXB-2089Z | ⊖ TCA9535RTWR | ⊕ TZ310N12 | D V24A24H400AL | ↗ VI-JT3-IY |
| ↔ VI-JW0-IX | ⊕ VSP2224R/1K | ⊖ WR48S05/3000XC | ⊕ XR3170EID-F | ↗ ZC833ATA |