


	MAX6865UK20D2S+T	
	Manufacturer Part Number:	MAX6865UK20D2S+T
	Manufacturer/Brand:	Maxim Integrated
	Part of Description:	IC MPU SUPERVISOR SOT23-5
	Datasheets:	1.MAX6865UK20D2S+T.pdf 2.MAX6865UK20D2S+T.pdf
	RoHs Status:	 Lead free / RoHS
Stock Condition:	Compliant New original, Stock Available.	
Ship From:	Hong Kong	
Shipment Way:	DHL/Fedex/TNT/UPS/EMS	

Specifications

Part Number	MAX6865UK20D2S+T
Manufacturer	Maxim Integrated
Description	IC MPU SUPERVISOR SOT23-5
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Simple Reset/Power-On Reset
Package / Case	SC-74A, SOT-753
Supplier Device Package	SOT-23-5
Output	Push-Pull, Totem Pole
Reset	Active High
Number of Voltages Monitored	1
Reset Timeout	40 ms Minimum
Voltage - Threshold	2V
Packaging	Tape & Reel (TR)

MAX6865UK20D2S+T is New Original in Stock, Search MAX6865UK20D2S+T Datasheets, PDF, Inventory at Y-IC.com Online, Order MAX6865UK20D2S+T Maxim Integrated with warranted and confidence. RFQ MAX6865UK20D2S+T : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>MAX6865UK20D3S+T Maxim Integrated IC MPU SUPERVISOR SOT23-5</p>	 <p>MAX6865UK20D5L+T Maxim Integrated IC MPU SUPERVISOR SOT23-5</p>	 <p>MAX6865UK20D1L+T Maxim Integrated IC MPU SUPERVISOR SOT23-5</p>	 <p>MAX6865UK19D6L+T Maxim Integrated IC MPU SUPERVISOR SOT23-5</p>
 <p>MAX6865UK20D1S+T Maxim Integrated IC MPU SUPERVISOR SOT23-5</p>	 <p>MAX6865UK20D4S+T Maxim Integrated IC MPU SUPERVISOR SOT23-5</p>	 <p>MAX6865UK20D3L+T Maxim Integrated IC MPU SUPERVISOR SOT23-5</p>	 <p>MAX6865UK20D2L+T Maxim Integrated IC MPU SUPERVISOR SOT23-5</p>

Hot Parts

More

- | | | | | |
|--------------------|------------------|--------------------|--------------------|----------------------|
| AP2127K-4.2TRG1 | APL5308-28AI-TRL | AT25010N-10SA-5.0B | ATTINY28V-1MU | AXK738247G |
| BS6-12-12 | BSM100GAR120DN2 | C2328A-Y | C4532JB2A105M230KA | CGA2B3X8R1C473K050BD |
| CL05C270JB51PNC | CL21B474KOFNNNF | CS0805-5N6J-S | FG1000CX-50 | FQD12N20 |
| GRM188R72A104KA35D | HN58X2402TI | IRFB20SPBF | IXTQ182N055T | LDC21897M19D-079 |
| LM2640MTC-ADJ/NOPB | LM27CIM5X-ZHJ | M34508G4H-068FP-W3 | M74HC4066RM13TR | MBB100A6 |
| MC33879EK | MP3386EY-LF-Z | MVR22HXBRN682 | NJM3414M | OPA337UA/2K5 |
| QM08N60F | QM200E2Y-HB | RF2172TR13 | RM30CZ-M | RX-8025T |
| S-8211CAT-I6T1U | SFF1040CT | SMF8.5AT1G | STD60NF55LA | STPS2H100U |
| SUM110N04-03P | TDA7479DTR | TL072IDT | U92-H215-2002-31 | UP01213G0L |
| VI-20Y-EX | X9C303S8ZT1 | YFF21SC1H101MT000N | ZXM66P03N8TA | ZXMN6A08E6TA |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited