










| | |
|---|---|
|  | <p>P0080SA-L</p> <p>Manufacturer Part Number: P0080SA-L</p> <p>Manufacturer/Brand: Littelfuse</p> <p>Part of Description: P0080SA-L Littelfuse</p> <p>RoHs Status:</p> <p>Stock Condition: New original, 6000 pcs Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p> |
| | <p>Image may be representation. See specs for product details.</p> |

Specifications

| | |
|--------------|---|
| Part Number | P0080SA-L |
| Manufacturer | Littelfuse |
| Description | P0080SA-L Littelfuse |
| Category | Integrated Circuits (ICs) > Specialized Hot ICs |
| Part Status | 6000 pcs Stock |
| Series | - |
| RoHs Status | Lead free / RoHS Compliant |
| Condition | New Original Stock |
| Warranty | 100% Perfect Functions |
| Lead Time | 2-3days after payment. |
| Payment | PayPal / Telegraphic Transfer / Western Union |
| Shipping by | DHL / Fedex / UPS |
| Port | HongKong |
| RFQ Email | Info@Y-IC.com |

P0080SA-L is New Original in Stock, Search P0080SA-L Datasheets, PDF, Inventory at Y-IC.com Online, Order P0080SA-L with warrantied and confidence. RFQ P0080SA-L : Info@Y-IC.com

You May Be Also Be interested In:

| | | | |
|--|---|--|---|
|  <p>P0080S1BLRP Hamlin / Littelfuse THYRISTOR 250A 55A DO214AC</p> |  <p>P0080S1ALRP Hamlin / Littelfuse SIDACTOR BI 6V 150A DO214AC</p> |  <p>P0080SAMC Hamlin / Littelfuse SIDACTOR MC BI 6V 150A DO-214AA</p> |  <p>P0080SA Hamlin / Littelfuse SIDACTOR 6V 150A DO-214</p> |
|  <p>P0080SALRP Hamlin / Littelfuse SIDACTOR BIDIR 6V 150A DO-214AA</p> |  <p>P0080SAMCL Hamlin / Littelfuse P0080SAMCL Littelfuse</p> |  <p>P0080S3NLRP Hamlin / Littelfuse SIDACTOR 6V 2500A DO-214AB</p> |  <p>P0080S SENCHIP P0080S SENCHIP</p> |

Hot Parts

[More](#)

- | | | | | |
|-------------------|-----------------|------------------------|------------------------|----------------------|
| ⚙️ 06033C153KAT2A | ⚡ 1DI400HB-120 | ➡️ C0603C0G1E3R3B030BG | D CGA2B2NP01H391J050BA | ➡️ EM7324SU16SP-70LF |
| ⚡ FDD6N50TM_WS | ⚙️ LNJ312G8J0QP | D MAX664ESA | ➡️ N990CH12 | ➡️ NPR1TTER510F |
| ⚙️ P0060D-B | ⚡ P0080BES | ⚙️ P0080EAL | ⚡ P0080EBL | ➡️ P0080ECL |
| D P0080EDL | ⚙️ P0080SAL | ⚡ P0080SALRP | ⚙️ P0080SAMCL | ➡️ P0080SAMCLRP |
| ➡️ P0080SAMCLRP | ⚡ P0080SAMCRP | ⚙️ P0080SARP | ⚡ P0080SB-L | ➡️ P0080SBL |
| ⚡ P0080SBLRP | ➡️ P0080SBMCLRR | D P0080SBMCRP | ⚙️ P0080SBRP | ⚡ P0080SC-L |
| ⚙️ P0080SCL | D P0080SCLRP | ➡️ P0080SCMCL | ⚡ P0080SCMCLRP | ➡️ P0080SCMCRP |
| ⚡ P0080SCRIP | ⚙️ P0080SDL | ⚡ P0080T023G5RP | ➡️ P0080TAA | ➡️ P0084UARP |
| ⚙️ P213A0402 | ⚡ SIT8103AI | ⚙️ SKDI26/08 | D SKKT15/14E | ➡️ SKKT42B08E |
| ⚡ SN74HCT00PWR | ⚙️ SSM3K15AFS | ⚡ TS5A3159QDBVRQ1 | ⚙️ TTB6C95N12KOF | ➡️ UC3875DWPTRG4 |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.
Copyright © 2019 YIC International Co., Limited