

 <p>A Renesas Company</p>	<p>Manufacturer Part Number: CS82C59A-12Z96</p>
	<p>Manufacturer/Brand: Intersil</p>
	<p>Part of Description: IC CTRL INTERRUPT 12.5MHZ 28PLCC</p>
	<p>Datasheets:  CS82C59A-12Z96.pdf</p>
<p>RoHs Status:  Lead free / RoHS</p>	<p>Stock Condition: Compliant New original, Stock Available.</p>
<p>Ship From: Hong Kong</p>	<p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	

Specifications

Part Number	CS82C59A-12Z96
Manufacturer	Intersil
Description	IC CTRL INTERRUPT 12.5MHZ 28PLCC
Category	Integrated Circuits (ICs) > Interface - Specialized
Part Status	Require For Quote & Check Stock
Series	-
Mounting Type	Surface Mount
Interface	System Bus
Applications	-
Package / Case	28-LCC (J-Lead)
Supplier Device Package	28-PLCC (11.51x11.51)
Voltage - Supply	4.5 V ~ 5.5 V
Packaging	Tape & Reel (TR)

CS82C59A-12Z96 is New Original in Stock, Search CS82C59A-12Z96 Datasheets, PDF, Inventory at Y-IC.com Online, Order CS82C59A-12Z96 Intersil with warrantied and confidence. RFQ CS82C59A-12Z96 : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>CS82C84A Intersil IC CLOCK GEN 5V 25MHZ 20-PLCC</p>	 <p>CS82C59AZ96 Intersil IC INTERRUPT CTRLR 8MHZ 28PLCC</p>	 <p>CS82C59A Intersil IC INTERRUPTER CMOS 8MHZ 28-PLCC</p>	 <p>CS82C59A96 Intersil IC INTERRUPTER CMOS 8MHZ 28-PLCC</p>
 <p>CS82C59A-12Z Intersil IC CTRL INTERRUPT 12.5MHZ 28PLCC</p>	 <p>CS82C59A-10X4027 INTERSI INTERSI PLCC28</p>	 <p>CS82C59AZ Intersil IC INTERRUPT CONTROLLER 28-PLCC</p>	 <p>CS82C59A-1296 Intersil IC CTRL INTERRUPT 12.5MHZ 28PLCC</p>

Hot Parts

More

- | | | | | |
|----------------------|----------------------|------------------|-------------------|----------------------|
| ⊕ 08053C684K4Z2A | ↔ 2220AC104KAT9A | ⇒ 6RI30B-060 | D ALP031B-TLM | ↔ AOTF8N50L |
| ⊖ AOZ8808DI-03 | ⊕ APS8922AGN3B | D AU01-11E | ⇒ CA3306AE | ↔ CD143A-SR3.3 |
| ⊕ DTA115EEBTL | ⊖ DTC114WSATP | ⊕ EH100AP-9262 | ↔ FODM121R2 | ↔ GQM2195C2E150JB12D |
| D GRM0337U1H6R7CD01D | ⊕ GRM216R71H223KA01J | ⊖ GT20J341 | ⊕ IMP1832S | ↔ IRFB3307ZPBF |
| ⇒ K4S643233H-HN75 | ↔ K9F6408U0C-TIBO | ⊕ LQW18AN10NG00D | ⊖ LQW2BAS24NJ00L | ↔ MAZS360G0L |
| ↔ MMF2X100J120D | ⇒ MT47H128M8CF-25:H | D MT6515MA | ⊕ NJG1133MD7 | ⊖ PE-8272QNL |
| ⊕ PE4242-52 | D PLC-0735-100S | ⇒ PQ12DZ1M | ↔ RM250DZ-M | ↔ RYC8502L |
| ⊖ SA5775AD | ⊕ SC1202CST-3.3TR | ↔ SI9200EY-E3 | ⇒ SMV1142-011 | ↔ STK654-430 |
| ⊕ T0570VA25G | ⊖ T250N600EOF | ⊕ TDA6142-5X | D TMK316B7225KLHT | ↔ TT50F13KFL-A |
| ↔ UNV300/B | ⊕ V24A12H400B3 | ⊖ VI-2N2-MV | ⊕ XN04A8800L | ↔ ZXRE330AV-A |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited