

 <p>A Renesas Company</p>	<h2 style="color: red;">X40421V14I-C</h2>	
	<p>Manufacturer Part Number: X40421V14I-C</p> <hr/> <p>Manufacturer/Brand: Intersil</p> <hr/> <p>Part of Description: IC VOLT MON DUAL SUP/SW 14-TSSOP</p> <hr/> <p>Datasheets:  X40421V14I-C.pdf</p> <hr/> <p>RoHs Status: Contains lead / RoHS non-compliant</p> <hr/> <p>Stock Condition: New original, Stock Available.</p> <hr/> <p>Ship From: Hong Kong</p> <hr/> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>	
<p>Image may be representation. See specs for product details.</p>		









Specifications

Part Number	X40421V14I-C
Manufacturer	Intersil
Description	IC VOLT MON DUAL SUP/SW 14-TSSOP
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Multi-Voltage Supervisor
Package / Case	14-TSSOP (0.173", 4.40mm Width)
Supplier Device Package	14-TSSOP
Output	Open Drain or Open Collector
Reset	Active Low
Number of Voltages Monitored	2
Reset Timeout	Adjustable/Selectable
Voltage - Threshold	1.6V, 2.9V
Packaging	Tube

X40421V14I-C is New Original in Stock, Search X40421V14I-C Datasheets, PDF, Inventory at Y-IC.com Online, Order X40421V14I-C Intersil with warrantied and confidence. RFQ X40421V14I-C : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>X40421V14I-B Intersil IC VOLT MON DUAL SUP/SW 14-TSSOP</p>	 <p>X40421V14I-CT1 Intersil IC VOLT MON DUAL SUP/SW 14-TSSOP</p>	 <p>X40421V14I-AT1 Intersil IC VOLT MON DUAL SUP/SW 14-TSSOP</p>	 <p>X40421V14I-BT1 Intersil IC VOLT MON DUAL SUP/SW 14-TSSOP</p>
 <p>X40426V14I-2.7AT1 Intersil IC SUPERVISR CPU IIC LVS 14TSSOP</p>	 <p>X40421V14-CT1 Intersil IC VOLT MON DUAL SUP/SW 14-TSSOP</p>	 <p>X40426V14I Intersil IC SUPERVISR CPU IIC LVS 14TSSOP</p>	 <p>X40426V14I-2.7 Intersil IC SUPERVISR CPU IIC LVS 14TSSOP</p>

Hot Parts

[More](#)

- | | | | | |
|--|--|---|--|---|
|  2225CC184KAT3A\SB |  ACPM-2308-TR1 |  ADP1714AUJZ-1.2-R7 |  AK4628VQ |  AK55GB40 |
|  AP1084K50 |  BZD27C36P-GS08 |  C1005X7S2A682M050BB |  CDSOD323-T05 |  CDZGJT2RA5.6B |
|  CGJ3E3X7S2A683K080AA |  CL21B562KBANFNC |  CL31C470JBCNNNC |  CP2230QN28-A2 |  CY28331OXCT |
|  D EC49119CB6N-F |  GRM033R71H331KA12D |  H11AG1VM |  H11N1SR2M |  HMC787LC3BTR |
|  IRFL9110 |  IXFX98N50P3 |  LP38962EMPX-2.5 |  LTC1538IG-AUX |  M45PE40-VMW6 |
|  MAX5441AEUA+T |  MAX6314US26D4-T |  MC100LVEP16DT |  MCC162-16I08 |  MDD95A12N |
|  MM1251BFFE |  NJM2516VC3-TE1 |  PVZ3A223C01R00 |  RT9169-50CX. |  RUF015N02 |
|  S-24CL01AOI-J8T1GE |  SN75HVD10D |  SST12LP08-QX6E |  TC7S02FE3 |  TCFGB1A476K8R |
|  TMP68HC11E1T |  TPCA8088 |  TT251N1200KOF |  UCC29002DR |  UCC3895PW |
|  UPD70F3102AGJ-33-8EU-A |  V300A24C500BL |  XBS204S17R-G |  XR16L2750CM-F |  ZXRE1004FF |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited