

 <p>A Renesas Company</p>	<h2 style="color: #E67E22;">X5323V14-2.7</h2>
	<p>Manufacturer Part Number: X5323V14-2.7</p> <hr/> <p>Manufacturer/Brand: Intersil</p> <hr/> <p>Part of Description: IC SUPERVISOR CPU 32K EE 14TSSOP</p> <hr/> <p>Datasheets:  X5323V14-2.7.pdf</p> <hr/> <p>RoHs Status: Contains lead / RoHS non-compliant</p> <hr/> <p>Stock Condition: New original, Stock Available.</p> <hr/> <p>Ship From: Hong Kong</p> <hr/> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	





Specifications

Part Number	X5323V14-2.7
Manufacturer	Intersil
Description	IC SUPERVISOR CPU 32K EE 14TSSOP
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	0°C ~ 70°C (TA)
Mounting Type	Surface Mount
Type	Simple Reset/Power-On Reset
Package / Case	14-TSSOP (0.173", 4.40mm Width)
Supplier Device Package	14-TSSOP
Output	Open Drain or Open Collector
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	100 ms Minimum
Voltage - Threshold	2.63V
Packaging	Tube

X5323V14-2.7 is New Original in Stock, Search X5323V14-2.7 Datasheets, PDF, Inventory at Y-IC.com Online, Order X5323V14-2.7 Intersil with warrantied and confidence. RFQ X5323V14-2.7 : Info@Y-IC.com






































You May Be Also Be interested

In:

 <p>X5323V14 Intersil IC SUPERVISOR CPU 32K EE 14TSSOP</p>	 <p>X5323V14-4.5A Intersil IC SUPERVISOR CPU 32K EE 14TSSOP</p>	 <p>X5323V14-2.7T1 Intersil IC SUPERVISOR CPU 32K EE 14TSSOP</p>	 <p>X5323V14I Intersil IC SUPERVISOR CPU 32K EE 14TSSOP</p>
 <p>X5323V14-2.7A Intersil IC SUPERVISOR CPU 32K EE 14TSSOP</p>	 <p>X5323S8Z-4.5 XICOR X5323S8Z-4.5 XICOR</p>	 <p>X5323V14I-2.7 Intersil IC SUPERVISOR CPU 32K EE 14TSSOP</p>	 <p>X5323S8Z-2.7T1 Intersil IC CPU SUPERV 32K EE 8-SOIC</p>

Hot Parts

[More](#)

- | | | | | |
|--|--|---|---|--|
|  1808HA680KAT1A |  AAT5102IVN-T1 |  AD815ARBZ-24 |  AD8631ARTZ-RL7 |  ATMEGA165-16AI |
|  C0402JRNPO9BN390 |  CC0100JRNPO6BN120 |  CC0603JRX7R6BB224 |  CC0603KRX7R7BB471 |  CDCR83DBQR |
|  CGJ6M2X7R2A105K200AA |  CL03C5R1CA3GNNC |  CL10C5R6CB8NNNC |  EL9211IWZ-T7 |  GCM155R71H332KA37D |
|  GRM1535C1H180JDD5D |  GRM1555C1E100JA01D |  GRM1555C1E7R9DA01D |  GRM1555C1H3R4BZ01D |  GRM1555C2A7R1CA01J |
|  GRM2195C1H103JA01D |  HIN202EIBNZ |  KA3406-ADJ |  KSD240AC3 |  LD2985-3.3V |
|  LM2675LD-5.0 |  LM833MMX/NOPB |  LT1963AEQ-1.8#TRPBF |  MAX691EWE |  MDD26-02N1B |
|  NX3008NBKMB |  NX5032GA-19.66 |  PRW1726A |  REF3330AIDBZT |  RSF14N03 |
|  S29AL016D90BF1020 |  SC445TETRT |  SIHG16N50C-E3 |  SMAJ100A |  SN74CBTLV3125PWR |
|  SPI-42X39090 |  SS2PH9LHE3/85A |  ST380CH06C0 |  STM8AF6288TD |  STS9NH3LL |
|  TB2906HJ |  TC54VN2702EMB713 |  WG30060SN |  XC61CC5502MRN |  ZXMP10A18KTC |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited