	K4S561638H-UCBC	
	Manufacturer Part Number:	K4S561638H-UCBC
Manufacturer/Brand:	SAMSUNG	
Part of Description:	SAMSUNG TSOP66	
RoHs Status:		
Stock Condition:	New original, 800 pcs Stock Available.	
Ship From:	Hong Kong	
Shipment Way:	DHL/Fedex/TNT/UPS/EMS	
Image may be representation. See specs for product details.		









Specifications

Part Number	K4S561638H-UCBC
Manufacturer	SAMSUNG
Description	SAMSUNG TSOP66
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	800 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

K4S561638H-UCBC is New Original in Stock, Search K4S561638H-UCBC Datasheets, PDF, Inventory at Y-IC.com Online, Order K4S561638H-UCBC with warrantied and confidence. RFQ K4S561638H-UCBC : Info@Y-IC.com

You May Be Also Be interested

In:

 K4S561633F-ZN75 Samsung Semiconductor K4S561633F-ZN75 SAMSUNG	 K4S56163LF SAMSUNG K4S56163LF SAMSUNG	 K4S561633F-XN75 SAMSUNG K4S561633F-XN75 SAMSUNG	 K4S561633F SAMSUNG K4S561633F SAMSUNG
 K4S561633F-XL75 SAMSUNG K4S561633F-XL75 SAMSUNG	 K4S56163LF-ZG75 SAMSUNG K4S56163LF-ZG75 SAMSUNG	 K4S561633F-ZL75 SAMSUNG K4S561633F-ZL75 SAMSUNG	 K4S56163LF-XG75 SEC K4S56163LF-XG75 SEC

Hot Parts More

- | | | | | |
|--------------------|--------------------------|----------------------|----------------------|-------------------|
| ⚙️ 04025A1R3BAT2A | ➡️ 18122C563KAT2A | ➡️ 5STF07D1414 | D 6MBI300U4W-120 | ➡️ 6MBP30RA060-01 |
| ⚡ AP8855-18PL | ⚙️ AZ1085S-ADJ | D BD9885FV-E2 | ➡️ BL8566-MPR6 | ➡️ CDBM2200-HF |
| ⚙️ CM2838GPIM25 | ⚡ CR70U-040 | ⚙️ FAN1587AM33X | ➡️ FCA16N60_F109 | ➡️ FDS6986S |
| D G1205S-2W | ⚙️ G6CU-1114P-FD-US-3VDC | ⚡ GRM1885C2AR70CZ01D | ⚙️ H5N3011P | ➡️ ICE2AS01G |
| ➡️ IDT2308-1HDCG | ➡️ KA5M0380RTU | ⚙️ KIA78L06F-RTF | ⚡ M36DR432A10CZA6 | ➡️ M5M5278DVP-20L |
| ➡️ MCP809T-460I/TT | ➡️ MDD172-16 | D MEC1322-LZY | ⚙️ MIC49150-1.2YMM | ⚡ MM74HC32SJ |
| ⚙️ NDS8434A | D NE5556AM | ➡️ NJM2346M-TE2 | ➡️ NJM2505AF | ➡️ NX1117C33Z |
| ⚡ PE130F-40 | ⚙️ PHZ20-9.1 | ➡️ PS9213-V-A | ➡️ R5000610XXWA | ➡️ RFP70N06 |
| ⚙️ RT8015GSP | ⚡ RT9818C-29PU3 | ⚙️ RX075FD24M | D S-8241AACMC-GAC-T2 | ➡️ SKM100GAR122D |
| ➡️ TDA8006A17 | ⚙️ TLC7628CDW | ⚡ TMP93CS40DF-1B70 | ⚙️ VI-23Z-CW | ➡️ VI-8105319 |