









 <p>A Renesas Company</p>	<p>ICL3222CV</p>
	<p>Manufacturer Part Number: ICL3222CV</p> <hr/> <p>Manufacturer/Brand: Intersil</p> <hr/> <p>Part of Description: IC 2DRVR/2RCVR RS232 3V 20-TSSOP</p> <hr/> <p>Datasheets:  ICL3222CV.pdf</p> <hr/> <p>RoHs Status: Contains lead / RoHS non-compliant</p> <hr/> <p>Stock Condition: New original, 30240 pcs Stock Available.</p> <hr/> <p>Ship From: Hong Kong</p> <hr/> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	

Specifications

Part Number	ICL3222CV
Manufacturer	Intersil
Description	IC 2DRVR/2RCVR RS232 3V 20-TSSOP
Category	Integrated Circuits (ICs) > Interface - Drivers,
Part Status	30240 pcs Stock
Series	-
Operating Temperature	0°C ~ 70°C
Mounting Type	Surface Mount
Type	Transceiver
Package / Case	20-TSSOP (0.173", 4.40mm Width)
Supplier Device Package	20-TSSOP
Voltage - Supply	3 V ~ 5.5 V
Protocol	RS232
Number of Drivers/Receivers	2/2
Duplex	Full
Receiver Hysteresis	300mV
Data Rate	250kbps
Packaging	Tape & Reel (TR)

ICL3222CV is New Original in Stock, Search ICL3222CV Datasheets, PDF, Inventory at Y-IC.com Online, Order ICL3222CV Intersil with warrantied and confidence. RFQ ICL3222CV : Info@Y-IC.com

You May Be Also Be interested In:

 <p>ICL3222CP Intersil IC TXRX RS-232 3-5.5V 18DIP</p>	 <p>ICL3222CVZ Intersil IC TXRX DL RS232 3-5.5V 20TSSOP</p>	 <p>ICL3222ECA Intersil IC 2DRVR/2RCVR RS232 3V 20-SSOP</p>	 <p>ICL3222ECA-T Intersil IC 2DRVR/2RCVR RS232 3V 20-SSOP</p>
 <p>ICL3222CVZ-T Intersil IC 2DRVR/2RCVR RS232 3V 20-TSSOP</p>	 <p>ICL3222CBZ Intersil IC TXRX RS232 250KBPS 18SOIC W</p>	 <p>ICL3222CB-T Intersil IC 2DRVR/2RCVR RS232 3V 18-SOIC</p>	 <p>ICL3222CBZ-T Intersil IC 2DRVR/2RCVR RS232 3V 18-SOIC</p>

Hot Parts

More

- [ICL3217ECA-T](#)
- [ICL3221CAZ](#)
- [ICL3221ECAZ](#)
- [ICL3221EIVZ-T](#)
- [ICL3222CA](#)
- [ICL3222CV-T](#)
- [ICL3222EIAZ-T](#)
- [ICL3222IBZ](#)
- [ICL3223ECVZ](#)
- [ICL3223IA-TS2463](#)
- [ICL3217ECAZ-T](#)
- [ICL3221CVZ](#)
- [ICL3221ECAZ-T](#)
- [ICL3221IA](#)
- [ICL3222CAZ](#)
- [ICL3222CVZ](#)
- [ICL3222EIBZ](#)
- [ICL3223CAZ](#)
- [ICL3223ECVZ-T](#)
- [ICL3223IV](#)
- [ICL3217ECBZ](#)
- [ICL3221CVZ-T](#)
- [ICL3221ECVZ](#)
- [ICL3221IA-T](#)
- [ICL3222CB](#)
- [ICL3222ECAZ](#)
- [ICL3222EIV](#)
- [ICL3223CV](#)
- [ICL3223EIA](#)
- [ICL3224ECAZ](#)
- [ICL3217EIBZ](#)
- [ICL3221ECA](#)
- [ICL3221EIAZ](#)
- [ICL3221IAZ](#)
- [ICL3222CBZ](#)
- [ICL3222ECP](#)
- [ICL3222EIV-T](#)
- [ICL3223ECA-T](#)
- [ICL3223EIAZ-T](#)
- [ICL3225EIAZ](#)
- [ICL3221CA](#)
- [ICL3221ECA-T](#)
- [ICL3221EIAZ-T](#)
- [ICL3221IAZ-T](#)
- [ICL3222CPZ](#)
- [ICL3222ECVZ](#)
- [ICL3222EIVZ](#)
- [ICL3223ECV](#)
- [ICL3223EIVZ](#)
- [ICL3227ECAZA](#)

Contact us:Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited