

	<h2 style="color: #D9534F;">ADM6315-29D4ARTL7</h2>
	<p>Manufacturer Part Number: ADM6315-29D4ARTL7</p> <hr/> <p>Manufacturer/Brand: ADI (Analog Devices, Inc.)</p> <hr/> <p>Part of Description: IC SUPERVISOR OD 2.93V SOT143</p> <hr/> <p>Datasheets:  ADM6315-29D4ARTL7.pdf</p> <hr/> <p>RoHs Status: Contains lead / RoHS non-compliant</p> <hr/> <p>Stock Condition: New original, Stock Available.</p> <hr/> <p>Ship From: Hong Kong</p> <hr/> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	

Specifications

Part Number	ADM6315-29D4ARTL7
Manufacturer	ADI (Analog Devices, Inc.)
Description	IC SUPERVISOR OD 2.93V SOT143
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 125°C (TA)
Mounting Type	Surface Mount
Type	Simple Reset/Power-On Reset
Package / Case	TO-253-4, TO-253AA
Supplier Device Package	SOT-143-4
Output	Open Drain or Open Collector
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	1.12 s Minimum
Voltage - Threshold	2.93V
Packaging	Tape & Reel (TR)

ADM6315-29D4ARTL7 is New Original in Stock, Search ADM6315-29D4ARTL7 Datasheets, PDF, Inventory at Y-IC.com Online, Order ADM6315-29D4ARTL7 ADI (Analog Devices, Inc.) with warrantied and confidence. RFQ ADM6315-29D4ARTL7 : Info@Y-IC.com



















































You May Be Also Be interested

In:

 <p>ADM6315-29D4ART-RL7 AD ADM6315-29D4ART-RL7 AD</p>	 <p>ADM6315-29D4ARTZ-RL7 AD/AD ADM6315-29D4ARTZ-RL7 AD/AD</p>	 <p>ADM6315-29D3ARTZR7 ADI (Analog Devices, Inc.) IC SUPERVISOR OD 2.93V SOT143</p>	 <p>ADM6315-29D4ARTZ-R7 ADI ADM6315-29D4ARTZ-R7 ADI</p>
 <p>ADM6315-30D4ARTL7 ADI (Analog Devices, Inc.) IC SUPERVISOR OD 3.00V SOT143</p>	 <p>ADM6315-29D4ARTZR7 ADI ADM6315-29D4ARTZR7 ADI</p>	 <p>ADM6315-29D3ARTZ-RL7 AD ADM6315-29D3ARTZ-RL7 AD</p>	 <p>ADM6315-29D4ARTZ AD ADM6315-29D4ARTZ AD</p>

Hot Parts

[More](#)

- | | | | | |
|--|---|---|--|---|
|  0402YA2R4CAT2A |  0805ZC154KAT4A |  12101C123KAT2A |  436500215 |  AAT1112ITP-0.6-T1 |
|  AM26LS31DC |  AR1PJHM3/84A |  AT120CA-2.1KER |  AT24C04N-10SI-2.7 |  AT5210-2.5KM4R |
|  AUIRFR4620 |  B39881-B4146-U510 |  BC213159A14-EK-E4 |  BH1JLB1WHFV-TR |  C1210C105K5NACTU |
|  CDSOD323-T24C |  CM600DXL-12A |  EDJ1108BFBG-DJ-F |  FCX458TA |  FQPF2N80YDTU |
|  GDMBZ5238B |  HK10053N6S-T |  IRF3515LPBF |  IRF9630PBF |  IRFI720G |
|  LMV842QMAX |  LT1468CS8#TRPBF |  LT6221CS8#PBF |  LTC1386CS |  LX1686EIPW |
|  M24C04-RDW6TP |  MAX706CSA+TG068 |  MM74HC574SJ |  N086RH06 |  NB669GQ-Z |
|  P543D12902 |  PQ05DZ1U-P |  RP1205-18GBR.TR |  S71PL127JB0BFWQB |  SI-3050F |
|  SI4703-C19-GM |  SI9407DY-T1-E3 |  SKFT60/08DS |  SMF05T1G |  SSM3K7002BS |
|  ST330C18L0 |  TLV320AIC23BIRHDR |  TP0101F-T1-GE3 |  TP8472AP |  Z8F0830PH020SG |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited