	R5F1076CGSP#V0
	Manufacturer Part Number: R5F1076CGSP#V0
	Manufacturer/Brand: Renesas Electronics America
	Part of Description: IC MCU 16BIT 32KB FLASH 20LSSOP
	Datasheets:  R5F1076CGSP#V0.pdf
	RoHs Status:  Lead free / RoHS
	Stock Condition: Compliant New original, Stock Available.
	Ship From: Hong Kong
Image may be representation. See specs for product details.	Shipment Way: DHL/Fedex/TNT/UPS/EMS









Specifications

Part Number	R5F1076CGSP#V0
Manufacturer	Renesas Electronics America
Description	IC MCU 16BIT 32KB FLASH 20LSSOP
Category	Integrated Circuits (ICs) > Embedded - Microcontrollers
Part Status	Require For Quote & Check Stock
Series	RL78/I1A
Operating Temperature	-40°C ~ 105°C (TA)
Package / Case	20-LSSOP (0.173", 4.40mm Width)
Supplier Device Package	20-LSSOP
Peripherals	DMA, LVD, POR, PWM, WDT
Core Processor	RL78
Speed	32MHz
Number of I/O	13
EEPROM Size	-
RAM Size	2K x 8
Core Size	16-Bit
Connectivity	I ² C, LIN, UART/USART
Program Memory Size	32KB (32K x 8)
Program Memory Type	FLASH
Voltage - Supply (Vcc/Vdd)	2.7 V ~ 5.5 V
Data Converters	A/D 6x8/10b
Oscillator Type	Internal
Packaging	Tube

R5F1076CGSP#V0 is New Original in Stock, Search R5F1076CGSP#V0 Datasheets, PDF, Inventory at Y-IC.com Online, Order R5F1076CGSP#V0 Renesas Electronics America with warrantied and confidence. RFQ R5F1076CGSP#V0 : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>R5F107ACGSP#V0 Renesas Electronics America IC MCU 16BIT 32KB FLASH 30LSSOP</p>	 <p>R5F1076CGSP#X0 Renesas Electronics America IC MCU 16BIT 32KB FLASH 20LSSOP</p>	 <p>R5F1057AGNA#W0 Renesas Electronics America RL78/G11 16KB/1.5KB+2KB 24QFN -4</p>	 <p>R5F107ACMSP#V0 Renesas Electronics America IC MCU 16BIT 32KB FLASH 30LSSOP</p>
 <p>R5F1076CMSP#V0 Renesas Electronics America IC MCU 16BIT 32KB FLASH 20LSSOP</p>	 <p>R5F107ACGSP#X0 Renesas Electronics America IC MCU 16BIT 32KB FLASH 30LSSOP</p>	 <p>R5F1058AGLA#W0 Renesas Electronics America RL78/G11 16K/1.5K 25WFLGA - 40_+1</p>	 <p>R5F1058AALA#W0 Renesas Electronics America RL78/G11 16K/1.5K+2K 25WFLGA -40</p>

Hot Parts

More

- | | | | | |
|----------------------|----------------------|----------------------|--------------------|-----------------------|
| ⊛ 0603YC152JAT2A | ↔ 08053C333KAT2A | ⇒ 12065C202JAT2A | D 6MBP200RTM060-10 | ⇒ AD7664AST |
| ⊣ AOZ8212CI-05 | ⊛ AS4PD-M3/86A | D AT24C08A-10PI-2.7 | ⇒ BC857BLT1G | ⇒ C3216X7R2A224M115AA |
| ⊛ C4532CH2J153K250KA | ⊣ CC0201JRX7R9BB151 | ⊛ DDZ5V6BSF | ↔ DP50Y1200N111907 | ⇒ FDMC7692 |
| D GCM3195C1H392JA16D | ⊛ GRM1886T1H150JD01D | ⊣ GRM1887U2A8R9DZ01D | ⊛ INA106KP | ⇒ IRF3205ZPBF. |
| ⇒ IXTQ44P15T | ↔ KNA16050C90VA5TS | ⊛ LP3964ESX-3.3/NOPB | ⊣ LT1084CT-3.3 | ⇒ LTC4066EUF |
| ↔ M50100DD800 | ⇒ MC74VHC04DTR2 | D MF-R010-2 | ⊛ MIC812SUY | ⊣ MLG1005S10NJT000 |
| ⊛ MP6510DF-LF-Z | D MT6L73FS | ⇒ N750DH44 | ↔ PIC12C671-04/SM | ⇒ PK40F-80/60/40 |
| ⊣ RGF1G-E3/67A | ⊛ RH5VL20CA-T1 | ↔ SD7401SM | ⇒ SD820S_L2_00001 | ⇒ SMB10J40C |
| ⊛ SN75LVPE802RTJR | ⊣ SSM01N60SL | ⊛ TBU-CA050-050-WH | D TCA0J156M8R | ⇒ TPS3307-33DGNRG4 |
| ↔ TS3DV520RHURG4 | ⊛ UC3845BVD1G | ⊣ V3P6-M3/84A | ⊛ VO3062D-X017 | ⇒ Z53C8003VSC |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited