
 <p>A Renesas Company</p>	<p>X40421V14I-B</p>
	<p>Manufacturer Part Number: X40421V14I-B</p> <p>Manufacturer/Brand: Intersil</p> <p>Part of Description: IC VOLT MON DUAL SUP/SW 14-TSSOP</p> <p>Datasheets: X40421V14I-B.pdf</p> <p>RoHs Status: Contains lead / RoHS non-compliant</p> <p>Stock Condition: New original, Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	









Specifications

Part Number	X40421V14I-B
Manufacturer	Intersil
Description	IC VOLT MON DUAL SUP/SW 14-TSSOP
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Multi-Voltage Supervisor
Package / Case	14-TSSOP (0.173", 4.40mm Width)
Supplier Device Package	14-TSSOP
Output	Open Drain or Open Collector
Reset	Active Low
Number of Voltages Monitored	2
Reset Timeout	Adjustable/Selectable
Voltage - Threshold	2.6V, 4.6V
Packaging	Tube

X40421V14I-B is New Original in Stock, Search X40421V14I-B Datasheets, PDF, Inventory at Y-IC.com Online, Order X40421V14I-B Intersil with warrantied and confidence. RFQ X40421V14I-B : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>X40421V14-CT1 Intersil IC VOLT MON DUAL SUP/SW 14-TSSOP</p>	 <p>X40421V14-BT1 Intersil IC VOLT MON DUAL SUP/SW 14-TSSOP</p>	 <p>X40426V14I-2.7 Intersil IC SUPERVISR CPU IIC LVS 14TSSOP</p>	 <p>X40421V14I-BT1 Intersil IC VOLT MON DUAL SUP/SW 14-TSSOP</p>
 <p>X40421V14I-C Intersil IC VOLT MON DUAL SUP/SW 14-TSSOP</p>	 <p>X40421V14-C Intersil IC VOLT MON DUAL SUP/SW 14-TSSOP</p>	 <p>X40421V14I-A Intersil IC VOLT MON DUAL SUP/SW 14-TSSOP</p>	 <p>X40421V14I-AT1 Intersil IC VOLT MON DUAL SUP/SW 14-TSSOP</p>

Hot Parts

[More](#)

- | | | | | |
|-----------------------|-----------------------|-----------------------|-----------------------|-----------------------|
| ⚙️ 112RKI20 | ➡️ 1812HC681KAT1A\SB | ➡️ AM79C303AJC/T | D APL5308-30AC-TRL | ➡️ AUIRFC4568ED |
| ⊖ C3216X7T2V683M130AA | ⚙️ CD74HC366M96 | D CT300DJB060 | ➡️ DRA5114T0L | ➡️ FJX945YTF |
| ⚙️ FQP140N03 | ⊖ FZ400R12KS4 | ⚙️ GJM0335C1E4R8CB01D | ➡️ GJM1555C1H4R0BB01D | ➡️ GRM1555C1H9R0BA01D |
| D GRM32ER61E226KE15L | ⚙️ HD64336013A11FYV | ⊖ HMK107C7224KAHTE | ⚙️ ICS574MLFT | ➡️ IP-262-EU |
| ➡️ IRFH5207TRPBF. | ➡️ KSC5338DTU | ⚙️ LD06YC684KAB2A | ⊖ LM75CIM-3/NOPB | ➡️ LMB2010MX |
| ➡️ LMV612MAX | ➡️ LP2952IMX-3.3/NOPB | D LQW04AN12NH00D1X | ⚙️ LTC3722IGN-1#PBF | ⊖ MAX8561ETA+T |
| ⚙️ MC74AC175N | D MCC44-16 | ➡️ MTP10N15 | ➡️ P2600EARP | ➡️ PA1278NLT |
| ⊖ PIC16F677-I/ML | ⚙️ PM6C-2002F | ➡️ SBRA8160T3G | ➡️ SKKH91/16D25 | ➡️ SMDA12.TB |
| ⚙️ TD425N08KOF | ⊖ TLC2274IPWR | ⚙️ TPS3801J25DCKR | D TPS51275RUKT | ➡️ TS921IYDT |
| ➡️ TZMB20-GS18 | ⚙️ UPC277G2-E2 | ⊖ VI-22Z-CW | ⚙️ VI-811249 | ➡️ VO2630-X007T |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited