





| | | |
|---|---|--|
|  | <h2 style="color: #E67E22;">MAX6865UK20D2L+T</h2> | |
| | Manufacturer Part Number: | MAX6865UK20D2L+T |
|  | Manufacturer/Brand: | Maxim Integrated |
| | Part of Description: | IC MPU SUPERVISOR SOT23-5 |
|  | Datasheets: | 1.MAX6865UK20D2L+T.pdf 2.MAX6865UK20D2L+T.pdf |
| | RoHs Status: |  Lead free / RoHS |
| Stock Condition: | Compliant New original, Stock Available. | |
| Ship From: | Hong Kong | |
| Shipment Way: | DHL/Fedex/TNT/UPS/EMS | |
| Image may be representation. See specs for product details. | | |

Specifications

| | |
|------------------------------|--|
| Part Number | MAX6865UK20D2L+T |
| Manufacturer | Maxim Integrated |
| Description | IC MPU SUPERVISOR SOT23-5 |
| Category | Integrated Circuits (ICs) > PMIC - Supervisors |
| Part Status | Require For Quote & Check Stock |
| Series | - |
| Operating Temperature | -40°C ~ 85°C (TA) |
| Mounting Type | Surface Mount |
| Type | Simple Reset/Power-On Reset |
| Package / Case | SC-74A, SOT-753 |
| Supplier Device Package | SOT-23-5 |
| Output | Push-Pull, Totem Pole |
| Reset | Active High |
| Number of Voltages Monitored | 1 |
| Reset Timeout | 40 ms Minimum |
| Voltage - Threshold | 2V |
| Packaging | Tape & Reel (TR) |

MAX6865UK20D2L+T is New Original in Stock, Search MAX6865UK20D2L+T Datasheets, PDF, Inventory at Y-IC.com Online, Order MAX6865UK20D2L+T Maxim Integrated with warrantied and confidence. RFQ MAX6865UK20D2L+T : Info@Y-IC.com

You May Be Also Be interested

| | | | |
|---|---|--|---|
| In:  <p>MAX6865UK19D6S+T Maxim Integrated IC MPU SUPERVISOR SOT23-5</p> |  <p>MAX6865UK20D4L+T Maxim Integrated IC MPU SUPERVISOR SOT23-5</p> |  <p>MAX6865UK20D3S+T Maxim Integrated IC MPU SUPERVISOR SOT23-5</p> |  <p>MAX6865UK20D2S+T Maxim Integrated IC MPU SUPERVISOR SOT23-5</p> |
|  <p>MAX6865UK20D1S+T Maxim Integrated IC MPU SUPERVISOR SOT23-5</p> |  <p>MAX6865UK20D1L+T Maxim Integrated IC MPU SUPERVISOR SOT23-5</p> |  <p>MAX6865UK20D4S+T Maxim Integrated IC MPU SUPERVISOR SOT23-5</p> |  <p>MAX6865UK20D3L+T Maxim Integrated IC MPU SUPERVISOR SOT23-5</p> |

Hot Parts

More

| | | | | |
|---------------------|--------------------|-------------------|-------------------|------------------|
| 04023C222KAJ2A | 12065F333K4T2A | ACPL-244-500E | ADS7843E | ADUM3401ARWZ |
| ADUM5230ARWZ | AK93C65LV-L | AT42QT1110-MU | AT45DB011D-MH-T | BD7004NUX-E2 |
| C0603C0G1E820J030BA | CY25403SXC-008 | CY7C199-25VCT | EMA2004-50MA08GRR | FM16W08-SG |
| FT500GZ-24 | GRM43ER60J476KE01L | HM62V8128LFP-12SL | HMK212BJ104MG-T | HZD10-48S03Y |
| ICS9212EF-03T | IXDN409PI | KA278R33CTSTU | LB1638ML-YE-L | LDC211G8114B-027 |
| LM26CIM5X-VHA | LT1012DN8 | LT3580IMS8E#PBF | M30300SAGP#U5CG | M37516M6-A34HP |
| MAX7306ALB+T | MC74AC04MEL | MCC122-08io8 | MD1507A42PQL | MP6401DQT-LF-Z |
| NDS9952A-NL | P382P1100SARP | P4SMAJ12CA | PS8821-2-AX | PSB45030-T/V1.2 |
| R9G01222 | RC0402JR-0720ML | RJK0603DPN-E0#T2 | SKN4000/06 | SML4728AHE3/61 |
| SPD04N60C3 | SS2PH10HE3/84A | ST120C14K1 | SXN15-48D3V3-2V5 | TMCMA1D475MTRF |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited