









	<h2 style="color: red;">ISL88041IBZ-T</h2>	
	Manufacturer Part Number:	ISL88041IBZ-T
	Manufacturer/Brand:	Intersil
	Part of Description:	IC SUPERVISORY VOLT QUAD 8-SOIC
Datasheets:	 ISL88041IBZ-T.pdf	
RoHS Status:	 Lead free / RoHS	
Stock Condition:	Compliant New original, Stock Available.	
Ship From:	Hong Kong	
Shipment Way:	DHL/Fedex/TNT/UPS/EMS	
<p>Image may be representation. See specs for product details.</p>		

Specifications

Part Number	ISL88041IBZ-T
Manufacturer	Intersil
Description	IC SUPERVISORY VOLT QUAD 8-SOIC
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Multi-Voltage Supervisor
Package / Case	8-SOIC (0.154", 3.90mm Width)
Supplier Device Package	8-SOIC
Output	Open Drain or Open Collector
Reset	Active Low
Number of Voltages Monitored	4
Reset Timeout	-
Voltage - Threshold	Adjustable/Selectable
Packaging	Tape & Reel (TR)

ISL88041IBZ-T is New Original in Stock, Search ISL88041IBZ-T Datasheets, PDF, Inventory at Y-IC.com Online, Order ISL88041IBZ-T Intersil with warrantied and confidence. RFQ ISL88041IBZ-T : Info@Y-IC.com

You May Be Also Be interested

<p>In:</p>  <p>ISL88031IUHFZS2711 Intersil IC QUINTUPLE VOLT MONITOR</p>	 <p>ISL88031IUHFZTKS2711 Intersil IC VOLTAGE MONITOR QUINT 8-MSOP</p>	 <p>ISL88042IRTEEZ Intersi Intersi DFN</p>	 <p>ISL88042IRTEEZ-TK Intersil IC SUPERVISOR VMON QUAD 8-TDFN</p>
 <p>ISL88031IU8HFZ-TK Intersil IC VOLTAGE MONITOR QUINT 8-MSOP</p>	 <p>ISL88042IRTEEZS2378 INTERSI INTERSI QFN</p>	 <p>ISL88041IBZ Intersil IC SUPERVISORY VOLT QUAD 8-SOIC</p>	 <p>ISL88041EVAL1 Intersil EVAL BOARD 1 FOR ISL88041</p>

Hot Parts

[More](#)

- | | | | | |
|--------------------------|----------------------|-------------------|------------------------|---------------------|
| ⚙️ 1210YC105MAT2A | ➡️ 1812WC272ZAT1A | ➡️ 2MBI400U2B060 | D ADP3330ART-3.6 | ➡️ APT82N60JCS |
| ⊖ AS78L05MTR-G1 | ⚙️ AT25DF081MH-1.8 | D AZV331KSTR-E1 | ➡️ C2012X6S1A475K085AB | ➡️ CY7C65640A-LFCT |
| ⚙️ EZ1117ACM-2.5 | ⊖ GJM0335C1E8R4CB01D | ⚙️ GP103HAMTR-G1 | ➡️ HD3SS3220RNHR | ➡️ IDT5T929-30NLGI8 |
| D IDT71V416S12PHGI | ⚙️ KBPC3510 | ⊖ LE24C162M-TLM-E | ⚙️ LM2903DR | ➡️ LTC1143CS#TRPBF |
| ➡️ LTC3405AES6-1.8#TRPBF | ➡️ MAX1415EUE+ | ⚙️ MAX5053AEUA+T | ⊖ MAX5880PUXF+C737475 | ➡️ MDU1513URH |
| ➡️ MG25N1ZS1 | ➡️ MGA-43003-TR | D MIC5310-MMYML | ⚙️ MTT50A12N | ⊖ NDC7003P |
| ⚙️ NTLGD3502NT2G | D PCA9511DP | ➡️ PI3A3160ZEEX | ➡️ R6004ENX | ➡️ REG1117A-2.5 |
| ⊖ RP130Q401D-TR-F | ⚙️ SA52045723 | ➡️ SBR12U120P5-13 | ➡️ SIR168DP-T1-GE3 | ➡️ SPX2950ACN-5.0 |
| ⚙️ TA2147FG | ⊖ TB62777FG | ⚙️ TESD712G2B | D TMC57606TB10 | ➡️ TPS62560DRVR |
| ➡️ TPS65193RGER | ⚙️ TS5A22364YZPR | ⊖ UC3844BVD1R2G | ⚙️ VI-261-64 | ➡️ VI-J52-EZ |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited