







 Not Actual Photo YIC International Co., Limited.	BB1117-5.0/SOT-23-3
	Manufacturer Part Number: BB1117-5.0/SOT-23-3 Manufacturer/Brand: BB Part of Description: BB1117-5.0/SOT-23-3 BB RoHs Status: Stock Condition: New original, 30000 pcs Stock Available. Ship From: Hong Kong Shipment Way: DHL/Fedex/TNT/UPS/EMS
Image may be representation. See specs for product details.	

Specifications

Part Number	BB1117-5.0/SOT-23-3
Manufacturer	BB
Description	BB1117-5.0/SOT-23-3 BB
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	30000 pcs Stock
Package	SOT-223
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

BB1117-5.0/SOT-23-3 is New Original in Stock, Search BB1117-5.0/SOT-23-3 Datasheets, PDF, Inventory at Y-IC.com Online, Order BB1117-5.0/SOT-23-3 with warrantied and confidence. RFQ BB1117-5.0/SOT-23-3 : Info@Y-IC.com

You May Be Also Be interested In:

 Not Actual Photo YIC International Co., Limited.	 Not Actual Photo YIC International Co., Limited.	 Not Actual Photo YIC International Co., Limited.	 Not Actual Photo YIC International Co., Limited.
BB1117-2.85 BB BB1117-2.85 BB	BB1117-3.3 BB BB SOT223	BB1117-5.0 BB BB SOT223	BB11172 TI BB11172 TI
 Not Actual Photo YIC International Co., Limited.	 Not Actual Photo YIC International Co., Limited.	 Not Actual Photo YIC International Co., Limited.	 Not Actual Photo YIC International Co., Limited.
BB11172-2.85 Original BB11172-2.85 Original	BB11175 TI BB11175 TI	BB1117-1.2V TI BB1117-1.2V TI/	BB1117 BB BB1117 BB

Hot Parts

[More](#)

- | | | | | |
|---------------------------------|-----------------------------------|--------------------------------------|---------------------------------------|-------------------------------|
| 12063A103FAT2A | AP2204RA-5.0TRG1 | APT130SM70B | D AQY210HLA | BA08CC0WFP-E2 |
| BB1117-1.2V | BB1117-2.85 | D BB11172-2.85 | BB1117N-3.3 | BB131+115 |
| BB145B-01 | BB15AH-FA | BB178+115 | BB179+115 | BB179BTR |
| D BB179LX+315 | BB181LX+315 | BB182+115 | BB182LX+315 | BB187+115 |
| CL10B474KA8NNWC | CQ0201ARNPO8BN1R8 | DBFZ1200R12KL4C30 | FC-25532.7680K-A | FDP036N10A |
| FGB3040E1 | FJP13009H2TU | D GRM1556T1H5R7CD01D | GRM21BF11H224ZA01L | IRKT230-18 |
| IRKV26/16A | D IRL8114PBF | KA7912ETU | MB81V17805A-60LPFTN-E | MDC310-16IO8 |
| MDD-12N1 | MG100Q2YS42(EP) | MSM56V16160F-10TSKR1 | N350MH14HOO | PDTA114ET/FD |
| PI3EQX6701DZDEX | PP15-24-3.3 | RB068LAM150 | D SM2100MH | TACT235/12 |
| THS4140IDR | UQCL2A180JAT2A | VT2008ECH | WRE0505S-W5 | ZMM5237BST |

Contact us:Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited