









| | | |
|--|---|---------------------------------|
|  <p>A Renesas Company</p> | <h2 style="color: #E67E22;">X9421WV14IZT1</h2> | |
| | Manufacturer Part Number: | X9421WV14IZT1 |
|  | Manufacturer/Brand: | Intersil |
| | Part of Description: | IC XDCP SGL 64-TAP 10K 14-TSSOP |
| Datasheets: |  X9421WV14IZT1.pdf | |
| RoHS Status: |  Lead free / RoHS | |
| Stock Condition: | Compliant New original, Stock Available. | |
| Ship From: | Hong Kong | |
| Shipment Way: | DHL/Fedex/TNT/UPS/EMS | |
| <p>Image may be representation. See specs for product details.</p> | | |

Specifications

| | |
|---------------------------------|--|
| Part Number | X9421WV14IZT1 |
| Manufacturer | Intersil |
| Description | IC XDCP SGL 64-TAP 10K 14-TSSOP |
| Category | Integrated Circuits (ICs) > Data Acquisition - Digital |
| Part Status | Require For Quote & Check Stock |
| Series | XDCP™ |
| Operating Temperature | -40°C ~ 85°C |
| Features | Selectable Address |
| Interface | SPI |
| Configuration | Potentiometer |
| Tolerance | ±20% |
| Package / Case | 14-TSSOP (0.173", 4.40mm Width) |
| Supplier Device Package | 14-TSSOP |
| Number of Circuits | 1 |
| Voltage - Supply | 5V |
| Memory Type | Non-Volatile |
| Resistance (Ohms) | 10k |
| Taper | Linear |
| Number of Taps | 64 |
| Temperature Coefficient (Typ) | ±300 ppm/°C |
| Resistance - Wiper (Ohms) (Typ) | 40 |
| Packaging | Tape & Reel (TR) |

X9421WV14IZT1 is New Original in Stock, Search X9421WV14IZT1 Datasheets, PDF, Inventory at Y-IC.com Online, Order X9421WV14IZT1 Intersil with warrantied and confidence. RFQ X9421WV14IZT1 : Info@Y-IC.com

You May Be Also Be interested

| | | | |
|--|---|--|--|
| <p>In:</p>  <p>X9421WV14I-2.7T1 Intersil IC XDCP SGL 64-TAP 10K 14-TSSOP</p> |  <p>X9421WV14ZT1 Intersil IC XDCP SGL 64-TAP 10K 14-TSSOP</p> |  <p>X9421WV14Z-2.7T1 Intersil IC XDCP SGL 64-TAP 10K 14-TSSOP</p> |  <p>X9421WV14IZ Intersil IC XDCP SGL 64-TAP 10K 14-TSSOP</p> |
|  <p>X9421WV14IT1 Intersil IC XDCP SGL 64-TAP 10K 14-TSSOP</p> |  <p>X9421WV14Z Intersil IC XDCP SGL 64-TAP 10K 14-TSSOP</p> |  <p>X9421WV14T1 Intersil IC XDCP SGL 64-TAP 10K 14-TSSOP</p> |  <p>X9421WV14IZ-2.7 Intersil IC XDCP SGL 64-TAP 10K 14-TSSOP</p> |

Hot Parts

More

| | | | | |
|------------------------|------------------|-------------------------|-----------------------|---------------------------|
| ⚙️ 0805ZC333KAT2A | ↔️ 7MBR50U2A-060 | ⇒ A3955SLBT | D AD60F08KEC | ⇒ ADM6348-40ARTZ-R7 |
| ⊖ APX823-26W5G-7 | ⚙️ DCX53-16 | D DS90LV031BTMX/NOPB | ⇒ F921C225MAA | ⇒ FAN5007MX |
| ⚙️ FGA25S125P | ⊖ FGB20N60SFD | ⚙️ FZ1200R12KF1 | ↔️ GRM219C81C225KA12D | ⇒ GRM39X7R683K25D500/T115 |
| D HK06034N3S-T | ⚙️ HSR15S50SP | ⊖ INA216A4YFFRG4 | ⚙️ IRF6665TRPBF | ⇒ IRS2153D |
| ⇒ MP3394ES-LF-Z | ↔️ MRF2947AT2 | ⚙️ MSB2403MD-3W | ⊖ MT48LC16M4A2P-75:G | ⇒ PF100A360 |
| ↔️ PHP23NQ10LT | ⇒ PQ018EZ5MZPH | D QCA150AA60 | ⚙️ R325CH14 | ⊖ RT9618APS |
| ⚙️ S-875041BUP-ABCT2G | D S2S4B00F | ⇒ S32-LS16-972-DC-C5 | ↔️ SAFEA1G84FA0F00R15 | ⇒ SC29911VKR2 |
| ⊖ SI7860DP-TI-E3 | ⚙️ SiHB15N65E | ↔️ SLF10145T-681MR38-PF | ⇒ SM34CXC624 | ⇒ SP3083EEN-L/TR |
| ⚙️ STI5516BUC | ⊖ STL66N3LLH5 | ⚙️ TA2020-020 | D TC7W125FU | ⇒ TCET1106 |
| ↔️ TCM1005-900-2P-T002 | ⚙️ TT104N14KOF-K | ⊖ VE-2N0-MW | ⚙️ VI-261-CV | ⇒ VUO82-12N07 |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited