
 <p>A Renesas Company</p>	<p>ICL3241IB-T</p>
	<p>Manufacturer Part Number: ICL3241IB-T</p> <hr/> <p>Manufacturer/Brand: Intersil</p> <hr/> <p>Part of Description: IC 3DRVR/5RCVR RS232 3V 28-SOIC</p> <hr/> <p>Datasheets: PDF ICL3241IB-T.pdf</p> <hr/> <p>RoHs Status: Contains lead / RoHS non-compliant</p> <hr/> <p>Stock Condition: New original, Stock Available.</p> <hr/> <p>Ship From: Hong Kong</p> <hr/> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	









Specifications

Part Number	ICL3241IB-T
Manufacturer	Intersil
Description	IC 3DRVR/5RCVR RS232 3V 28-SOIC
Category	Integrated Circuits (ICs) > Interface - Drivers, Receivers,
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C
Mounting Type	Surface Mount
Type	Transceiver
Package / Case	28-SOIC (0.295", 7.50mm Width)
Supplier Device Package	28-SOIC
Voltage - Supply	3 V ~ 5.5 V
Protocol	RS232
Number of Drivers/Receivers	3/5
Duplex	Full
Receiver Hysteresis	300mV
Data Rate	250kbps
Packaging	Tape & Reel (TR)

ICL3241IB-T is New Original in Stock, Search ICL3241IB-T Datasheets, PDF, Inventory at Y-IC.com Online, Order ICL3241IB-T Intersil with warrantied and confidence. RFQ ICL3241IB-T : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>ICL3241IB Intersil IC 3DRVR/5RCVR RS232 3V 28-SOIC</p>	 <p>ICL3241IV Intersil IC 3DRVR/5RCVR RS232 3V 28-TSSOP</p>	 <p>ICL3241IAZ-T Intersil IC 3DRVR/5RCVR RS232 3V 28-SSOP</p>	 <p>ICL3242CB INTERSI ICL3242CB INTERSI</p>
 <p>ICL3241IA Intersil IC 3DRVR/5RCVR RS232 3V 28-SSOP</p>	 <p>ICL3241IBZ Intersil IC 3DRVR/5RCVR RS232 3V 28-SOIC</p>	 <p>ICL3241IV-T Intersil IC 3DRVR/5RCVR RS232 3V 28-TSSOP</p>	 <p>ICL3241IAZ Intersil IC 3DRVR/5RCVR RS232 3V 28-SSOP</p>

Hot Parts

[More](#)

- | | | | | |
|-----------------------|----------------------|--------------------|----------------------|-----------------------|
| ⊛ 06031C681MAT2A | ➔ 08055C473KAZ2A | ➔ 1808CC390KAT9A | D 1812AC471MAT3A\SB | ➔ 6R1MBI125LP-160-02 |
| ⊣ AAT3111IGU-3.6-T1 | ⊛ AD5640CRJ-1 | D AD7895BRZ-2 | ➔ APL5301-28BC-TR | ➔ AVE350B-48S28P-6 |
| ⊛ BAS40C-R1-00001 | ⊣ BD6980NUX-E2 | ⊛ BTB10-800CWRG | ➔ BTS442D2E3062A | ➔ C1005X6S1C334K050BC |
| D C2012X7R0J106M125AB | ⊛ C2225C225J5RAC7800 | ⊣ CK37236R | ⊛ CMR1-06M | ➔ D3501N42 |
| ➔ DTC144WKA | ➔ FDS4559_F085 | ⊛ FFPF30UP20DNTU | ⊣ GRM0335C1ER50BA01J | ➔ GRM1557U1HR50CZ01D |
| ➔ HAT2038RJ | ➔ IP4369CX4-H500 | D IRFK6H150 | ⊛ KP2000A1400V | ⊣ KR1006-12045 |
| ⊛ LE25FW106ALQ-TLM-E | D LM25088QMH-2 | ➔ LM5107MAX/NOPB | ➔ LMB1029T | ➔ LMC6064AIMX |
| ⊣ LT3684IDD | ⊛ LTC1046CS8 | ➔ LTC1779ES6#TRPBF | ➔ MA2SP060GL | ➔ MA4E1340E-1068T |
| ⊛ MAX3171CAI+T | ⊣ MAX393HAUA+T | ⊛ MIG30J804H | D MMF150S120B | ➔ NFE31PT221D1E9L |
| ➔ OB2539AP | ⊛ SST177-T1-GE3 | ⊣ TOP270EG | ⊛ VJ0603Y272KXAAT | ➔ ZW102412 |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited