

 <p>A Renesas Company</p>	<p>X5325P-4.5A</p>
	<p>Manufacturer Part Number: X5325P-4.5A</p> <hr/> <p>Manufacturer/Brand: Intersil</p> <hr/> <p>Part of Description: IC SUPERVISOR CPU 32K EE 8-DIP</p> <hr/> <p>Datasheets:  X5325P-4.5A.pdf</p> <hr/> <p>RoHs Status: Contains lead / RoHS non-compliant</p> <hr/> <p>Stock Condition: New original, Stock Available.</p> <hr/> <p>Ship From: Hong Kong</p> <hr/> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
 <p>Image may be representation. See specs for product details.</p>	









Specifications

Part Number	X5325P-4.5A
Manufacturer	Intersil
Description	IC SUPERVISOR CPU 32K EE 8-DIP
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	0°C ~ 70°C (TA)
Mounting Type	Through Hole
Type	Simple Reset/Power-On Reset
Package / Case	8-DIP (0.300", 7.62mm)
Supplier Device Package	8-PDIP
Output	Open Drain or Open Collector
Reset	Active High
Number of Voltages Monitored	1
Reset Timeout	100 ms Minimum
Voltage - Threshold	4.63V
Packaging	Tube

X5325P-4.5A is New Original in Stock, Search X5325P-4.5A Datasheets, PDF, Inventory at Y-IC.com Online, Order X5325P-4.5A Intersil with warrantied and confidence. RFQ X5325P-4.5A : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>X5325PI-2.7 Intersil IC SUPERVISOR CPU 32K EE 8-DIP</p>	 <p>X5325P Intersil IC CPU SUPRV 32K EE RST HI 8DIP</p>	 <p>X5325PI-2.7A Intersil IC SUPERVISOR CPU 32K EE 8-DIP</p>	 <p>X5325S8 Intersil IC CPU SUPRV 32K EE RST HI 8SOIC</p>
 <p>X5323ZI INTERASIL X5323ZI INTERASIL</p>	 <p>X5325P-2.7 Intersil IC SUPERVISOR CPU 32K EE 8-DIP</p>	 <p>X5325P-2.7A Intersil IC SUPERVISOR CPU 32K EE 8-DIP</p>	 <p>X5325 INTRESIL INTRESIL SOP8</p>

Hot Parts

More

- | | | | | |
|----------------------|----------------------|----------------------|---------------------|----------------------|
| ⊛ 06033A471GAT2A | ↔ 06035A121G4T2A | ⇒ A3958SLBTR-T | D AD5315ARMZ | ⇒ ADL5502ACBZ-P7 |
| ⊣ AK8772-L | ⊛ AP131-28WG-7 | D BC63B239A04-IKB-E4 | ⇒ BZX585-C4V3 | ⇒ DS1848B-010+ |
| ⊛ DSC557-0344SI1 | ⊣ DT1608C-223MLD | ⊛ ELM89333BC-S | ↔ FDS86267P | ⇒ GRM1885C1H470FA01J |
| D GRM1886P1H5R8DZ01D | ⊛ GRM2195C1H103GA01D | ⊣ H11AV1SM | ⊛ HX6096NL | ⇒ HZM6.2NB2TR-E |
| ⇒ IR21365PBF. | ↔ IRF3704S | ⊛ IS62LV256L-15J | ⊣ K4B2G1646C-HCKO | ⇒ KSH30CTF |
| ↔ LTC1841IS8 | ⇒ MAX8606ETD+T | D MBRM140ET3 | ⊛ MDS100A-1600V | ⊣ MI-RAM-I1 |
| ⊛ MMF200S170DA2B | D PQ05DZ5M | ⇒ PS21342-BN | ↔ RNC55H60R4FS | ⇒ RT9226BCS |
| ⊣ S-8211CDF-I6T1U | ⊛ S8035KTP | ↔ SDT90GK18 | ⇒ SI6880AEDQ-T1-GE3 | ⇒ SKDL150/16 |
| ⊛ SKIIP450TAT16DF | ⊣ SKM75GD123D | ⊛ SR24S15/200 | D TA6F9.1AHM3_A/H | ⇒ TK15A20D |
| ↔ TR/0603FA2.5A | ⊛ UP01213G0LBF | ⊣ UP04213008S0 | ⊛ XC6215B182GR | ⇒ ZP2500A2600V |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited